

MIDLAND DIVISION,THE DEXTER CORPORATION -- LAMINAR X-500 HRDNER(50-C-3)(2ND REFORMLTN) -- 8030-00-908-0362

=====
===== Product Identification =====

Product ID:LAMINAR X-500 HRDNER(50-C-3)(2ND REFORMLTN)

MSDS Date:01/01/1987

FSC:8030

NIIN:00-908-0362

Kit Part:Y

MSDS Number: BFVYY

=== Responsible Party ===

Company Name:MIDLAND DIVISION,THE DEXTER CORPORATION

Address:31500 HAYMAN ST

City:HAYWARD

State:CA

ZIP:94544-7120

Country:US

CAGE:98795

=== Contractor Identification ===

Company Name:DEXTER CORP THE DEXTER CROWN METRO AEROSPACE DIV

Address:31500 HAYMAN ST

Box:City:HAYWARD

State:CA

ZIP:94544-7120

Country:US

Phone:510-471-7171

CAGE:98795

=====
===== Composition/Information on Ingredients =====

Ingred Name:TOLUENE-2,4-DIISOCYANATE (TDI) (SARA III)

CAS:584-84-9

RTECS #:CZ6300000

Fraction by Wt: 0.6%

OSHA PEL:C,0.02 PPM/0.02 STEL

ACGIH TLV:0.005PPM/0.02STEL;93

EPA Rpt Qty:100 LBS

DO

T Rpt Qty:100 LBS

Ingred Name:1 METHOXY 2 PROPANOL ACETATE (CAS # 108-65-6)

Fraction by Wt: 25%

Ingred Name:XYLENES (O-,M-,P- ISOMERS) (SARA III)

CAS:1330-20-7

RTECS #:ZE2100000

Fraction by Wt: 15%

OSHA PEL:100 PPM/150 STEL

ACGIH TLV:100 PPM/150STEL;9192

EPA Rpt Qty:1000 LBS

DOT Rpt Qty:1000 LBS

=====
===== Hazards Identification =====

Effects of Overexposure:INH:ANESTH;IRRIT RESP TRACT,ACUTE CNS DEPRESS
W/HDCH,DIZ,STAG GAIT,CONFUS,UCON,COMA. SKIN/EYE:IRRIT

=

=====
===== First Aid Measures =====

First Aid:FUMES: REMOVE FROM EXPOS. RESTORE BREATHING. KEEP WARM &
QUIET. NOTIFY MD. EYES:FLUSH IMMED W/COPIOUS QTY OF RUNNING WATER
AT LEAST 15 MIN. SEE MD FOR DEFINITIVE TREATMENT. SKIN:REMOVE
W/SOAP & WATER. REMOVE CONTAMINATED CLOTHING.

=====
===== Fire Fighting Measures =====

Flash Point:92F SCC

Lower Limits:0.9

Extinguishing Media:CO*2,DRY CHEMICAL,FOAM FOR CLASS IB FLAM LIQ

Fire

Fighting Procedures:USE WATER FOG TO COOL CLSD CONTAINERS EXPOS TO
FIRE.

Unusual Fire/Explosion Hazard:KEEP CANS TIGHTLY CLSD. KEEP FROM IGNIT
SOURCES. CLSD CANS MAY EXPLO FROM HEAT EXPOS. SEE OTHER PREC

=====
===== Accidental Release Measures =====

Spill Release Procedures:REMOVE ALL SOURCES OF IGNITION(FLAMES,HOT
SURFACES, & ELECTRICAL,STATIC OR FRICTIONAL SPARKS). AVOID
BREATHING VAPORS. VENTILATE AREA. REMOVE W/INERT ABSORBENT &
NON-SPARKING TOOLS

