View NSN Online: https://aerobasegroup.com/nsn/3439-00-027-0954

## EUTECTIC CORPORATION -- XUPER 146 SFC -- 3439-00-027-0954

============= Product Identification ==============

Product ID:XUPER 146 SFC MSDS Date:01/01/1987

FSC:3439

NIIN:00-027-0954

MSDS Number: BCVQJ === Responsible Party ===

Company Name: EUTECTIC CORPORATION

Emergency Phone Num: (718)358-4000

CAGE:EO060

=== Contractor Identification ===
Company Name:EUTECTIC CORP

Address:9625-J SOUTHERN PINE BLVD

Box:City:CHARLO

TTE

State:NC ZIP:28273 Country:US

Phone:704-527-9800/800-221-1433

CAGE:72271

Company Name: EUTECTIC CORPORATION

CAGE:EO060

======= Composition/Information on Ingredients ========

Ingred Name: COPPER (SARA III)

CAS:7440-50-8

RTECS #:GL5325000

OSHA PEL:0.1MG/M3 FUME/1 DUST ACGIH TLV:0.2MG/M3 FUME; 9192

EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:ZINC (SARA III)

CAS:7440-66-6

RTECS #:ZG8600000

OSHA PEL:10 MG ZNO/M3

ACGIH TLV:10 MG ZNO/M3; 9192

EPA Rpt Qty:1000 LBS

**DOT Rpt** 

Qty:1000 LBS Ingred Name:BORIC ACID, CAS#10043-35-3 CAS:10043-35-3 RTECS #:ED4550000 ACGIH TLV:10MG/CUM(MFR) Ingred Name:POTASSIUM BORATE,CAS#1332-77-0 Ingred Name: PHENOLIC RESIN Effects of Overexposure: METALLIC TASTE, NAUSEA, TIGHTNESS OF CHEST, FEVER, DIZZINESS, EYE, NOSE, THROAT DRYNESS AND IRRITATION. First Aid:REMOVE FROM EXPOSURE AND OBTAIN PROMPT ME DICAL ATTENTION.IF UNCONSCIOUS, GIVE OXYGEN. IF NOT BREATHING GIVE CPR. EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY AMERICAN RED CROSS. Extinguishing Media: EXTINGUISH WITH AGENT SUITABLE FOR SURROUNDING FIRE Unusual Fire/Explosion Hazard: WELDING ARC AND SPARKS CAN IGNITE COMBUSTIBLE PRODUCTS. ========= Accidental Release Measures ============== Spill Release Procedures: CLEAN UP ANY GRINDING DUST OR WA STE RESIDUE AND PLACE IN SUITABLE DOT APPROVED DISPOSAL CONTAINER ============ Handling and Storage =========================== Other Precautions: TRAIN WELDER TO KEEP HIS HEAD OUT OF THE FUMES.MONITOR AIR TO ENSURE ACCEPTABLE EXPOSURES.AVOID ELECTRICAL SHOCK BY MAINTAINING DRY WORK AREA. ===== Exposure Controls/Personal Protection ========

Respiratory Protection: FUME RESP.OR AIR SUPPLIED RESP.IN CONFINED

Ventilation:LOCAL EXHAUST TO MAINTN BELOW T

SPACES.

| Eye Protection:FACE SHLD W/FILTER LENS. Other Protective Equipment:SUBST.DK.CLOTH,ARM PROTECTOR,APRON,HAT,SHOULDR.PROTECTION. Supplemental Safety and Health MSDS DATED 09-18-86/ |
|---|
| ========= Physical/Chemical Properties ==========   |
| HCC:N1 Appearance and Odor:WELDING ROD 1/8"DIAX18"LONG.   |
| ======== Stability and Reactivity Data =========  |
| Stability Indicator/Materials to Avoid:YES Hazardous Decomposition Products:FUMES O F METALS AND METAL OXIDES,CO,NO*2,O*3.  |
| ====== Disposal Considerations ==========   |

LV.

Protective Gloves: WELDER'S GLOVES

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.