View NSN Online: https://aerobasegroup.com/nsn/3439-00-141-8707

J.W.HARRIS -- STA-SILV 15 -- 3439-00-141-8707

Product ID:STA-SILV 15 MSDS Date:09/01/1992

FSC:3439

NIIN:00-141-8707

MSDS Number: BDBQR
=== Responsible Party ===
Company Name: J.W.HARRIS
Address: 10930 DEERFIELD RD.

City:CINCINNATI

State:OH ZIP:45242 Country:US

Info Phone Num:513-891-2000

Emergency Phone Num:513-891-2000

CAGE:27911

=== Contractor Identification ===

Company Name: J. W. HARRIS CO., INC.

Address:10930 DEERFIELD ROAD

Box:City:CINCINNATI

State:OH

ZIP:45242-4110

Country:US

Phone:513-891-2000

CAGE:27911

====== Composition/Information on Ingredients ========

Ingred Name: SILVER (SARA III)

CAS:7440-22-4

RTECS #:VW3500000 Fraction by Wt: 15%

Other REC Limits: ACGIH 0.01 MG SOL.AG

OSHA PEL:0.01 MG/M3 ACGIH TLV:0.1 MG/M3; 9293

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name: COPPER (SARA III)

CAS:7440-50-8

RTECS #:GL5325000

Fraction by W

t: 80% Other REC Limits: NONE SPECIFIED OSHA PEL:0.1MG/M3 FUME/1 DUST ACGIH TLV:0.2MG/M3 FUME; 9293 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS Ingred Name:PHOSPHOROUS (YELLOW) (SARA III) CAS:7723-14-0 RTECS #:TH3500000 Fraction by Wt: 5.0% Other REC Limits: NONE SPECIFIED OSHA PEL:0.1 MG/M3 ACGIH TLV:0.1 MG/M3; 9293 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

=========== Hazards Identification ==========================

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO

Reports of Carcinogenic

ity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic: ACUTE HAZARD IS METAL FUME FEVER, CAUSED BY BREATHING COPPER OR ZINC FUME. CHRONIC EFFECTS MAY BE CAUSED BY FLUORIDES FROM THE FLUX OR POSSIBLE PULMONARY DISEASE, SUCH AS PNEUMOCONIOSIS.

Explanation of Carcinogenicity: NO INGREDIENT OF A CONCENTRATION OF 0.1% OR GREATER IS LISTED AS A CARCINOGEN OR SUSPECTED CARCINOGEN BY IARC, NTP, OSHA

Effects of Overexposure: METAL FUME INHALATION: METALLIC TASTE, THROAT

TATION, COUGHING, SHORTNESS OF BREATH, NAUSEA, FEVER, BODY ACHE, CHILLS.

Medical Cond Aggravated by Exposure: PULMONARY DISEASES


First Aid:REMOVE FROM EXPOSURE. GIVE OXYGEN OR ARTIFICIAL RESPIRATION IF NEEDED, GET MEDICAL ATTENTION.

============ Fire Fighting Measures =========================

Flash Point: NON-FLAMMABLE

Extinguishing Media: EXTINGUISH WITH MEDIA APPROPRIATE FOR SURROUNDING FIRE.

Fire Fightin



s:FUMES AND/OR GASES PRODUCED DURING
WELDING OR BRAZING OPERATIONS. THEY WILL VARY IN COMPOSITION

======= Disposal Considerations ===========

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied

, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.