View NSN Online: https://aerobasegroup.com/nsn/3439-01-047-4141

Product ID:MARCOLOY 1900 FLUX (SILVER BRAZING) MSDS Date:01/01/1987 FSC:3439 NIIN:01-047-4141 Kit Part:Y MSDS Number: BGHQN === Responsible Party === Company Name:MARCO COMPANY Emergency Phone Num: (213)723-0711 CAGE:HO294 === Contractor Identification === Company Name:MARCO CO Address:5722 UNION PACIFIC AVENUE Box:City:LOS ANGELES State:CA ZIP:90022-5135 Country:US Phone:213-723-0711 CAGE:55278 Company Name:MARCO COMPANY CAGE:HO294

Ingred Name:BORIC ACID,CAS#10043-35-3 CAS:10043-35-3 RTECS #:ED4550000 ACGIH TLV:15PPM(MFR)

Ingred Name:POTASSIUM TETRABORATE,CAS#12228-88-5 ACGIH TLV:1PPM(MFR)

Ingred Name:POTASSIUM BIFLUORIDE (POTASSIUM HYDROGEN FLUORIDE) CAS:7789-29-9 RTECS #:TS6650000 OSHA PEL:2.5 MG/M3 (F) ACG IH TLV:2.5 MG/M3 (F); 8990

Ingred Name:POTASSIUM PENTABORATE,CAS#1229-13-9 ACGIH TLV:1PPM(MFR)

Ingred Name:DEIONIZED WATER,CAS#7732-18-5 CAS:7732-18-5 RTECS #:ZC0110000

Effects of Overexposure: IRR.TO EYES & NOSE.

First Aid:REMOVE TO FRESH AIR. GIVE CPR/OXYGEN IF NEED. SKIN:WASH WITH SOAP & WATER. EYES:FLUSH WITH WATER 15 MIN. KEEP WARM AND QUIET.

ING:SEE DOCTOR IMMEDIATELY.

Extinguishing Media:WATER Fire Fighting Procedures:NONE. WILL NOT BURN Unusual Fire/Explosion Hazard:NONE

Spill Release Procedures: SWEEP UP AND PLACE IN SUITABLE DISPOSAL CONTAINER. FLUSH RESIDUE WITH LARGE AMOUNTS OF WATER.

Other Precautions:TRAIN WELDER T O KEEP HIS HEAD OUT OF THE FUMES.MONITOR AIR TO ENSURE ACCEPTABLE EXPOSURES.AVOID ELECTRICAL SHOCK BY MAINTAINING DRY WORK AREA.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection:FUME RESP.OR AIR SUPPLIED RESP.IN CONFINED SPACES. Ventilation:PROVIDE MECHAN(GEN/LOCAL EXHAUST)VENT TO MAINTN