View NSN Online: https://aerobasegroup.com/nsn/8010-00-068-8778

Product ID:LACQUER, ACRYLIC, WHITE 37875 ID 794720

MSDS Date:08/16/1990

FSC:8010

NIIN:00-068-8778

MSDS Number: BJPWW === Responsible Party ===

Company Name: PRATT & LAMBERT INC

Box:2153 City:WICHITA State:KS ZIP:67201

Country:US

Info Phone Num:316-733-1361 Emergency Phone Num:316-7

33-1361

Preparer's Name: W.A. ELLISON

CAGE:PRATT

=== Contractor Identification ===
Company Name:PRATT & LAMBERT

Address:250 PETTIT AVE

Box:2153

City:BELLMORE

State:NY ZIP:11710 Country:US

Phone:800-647-2253

CAGE:PRATT

Company Name: PRATT AND LAMBERT INC

Address:Box:6027 City:CLEVELAND

State:OH

ZIP:44101-1027 Country:US

Phone:216-566-2902

CAGE:61196

====== Composition/Information on Ingredients ========

Ingred Name: CYCLOHEXANONE (SARA III)

CAS:108-94-1

RTECS #:GW1050000

Fraction by

Wt: 20%

Other REC Limits:LFL 1.1 OSHA PEL:S, 50 PPM

ACGIH TLV:S, 25 PPM; 9293

EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name: TOLUENE (SARA III)

CAS:108-88-3

RTECS #:XS5250000 Fraction by Wt: 10%

Other REC Limits:LFL 1.7/UFL 7.1 OSHA PEL:200 PPM/150 STEL ACGIH TLV:50 PPM; 9293 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:TITANIUM DIOXIDE

CAS:13463-67-7 RTECS #:XR2275000 Fraction by Wt: 15%

Other REC Limits: NONE SPECIFIED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Name: TALC (CONTAINING NO ASBESTOS)

CAS:14807-96-6 RTECS #:WW2710000 Fraction by Wt: 10%

Other REC Limits: NONE SPECIFIED

OSHA PEL:2 MG/M3 RDUST

ACGIH TLV:2 MG/M3 RDUST; 9192

Ingred Name: SILICA, CRYSTALLINE - QUARTZ

CAS:14808-60-7 RTECS #:VV7330000 Fraction by Wt: THAN AIR

Spec Gravity:1.1

Evaporation Rate & Evaporation R

Percent Volatiles by Volume:67%

======== Stability and Reactivity Data =========

Stability Indicator/Materials to Avoid:YES

STRON

G ACIDS OR ALKALINE MATERIALS.

Stability Condition to Avoid:AVOID EXCESSIVE HEAT AND SOURCES OF IGNITION.

Hazardous Decomposition Products:BURNING, INCLUDING WHEN HEATED BY WELDING OR CUTTING, WILL PRODUCE SMOKE, CARBON MONOXIDE AND CARBON DIOXIDE

Conditions to Avoid Polymerization: KEEP AWAY FROM HEAT SPARKS AND FLAME.

======== Disposal Considerations =============

Waste Disposal Methods:DISPOSE OF I/A/W FEDERAL, STATE AND LOCAL LAWS. INCINERATE ONLY I

N EPA PERMITTED FACILITY. DO NOT INCINERATE CLOSED CONTAINERS. OBSERVE PRECAUTIONS FOR DISPOSAL OF FLAMMABLE MATERIALS. CONTAMINATED AB SORBANT MAY BE DISPOSED IN A HAZ WASTE LANDFILL.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability

for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.