View NSN Online: https://aerobasegroup.com/nsn/3439-00-004-4547

HI-TECH ALLOYS CORP -- HI-TECH -- 3439-00-004-4547

Product ID:HI-TECH MSDS Date:01/01/1987

FSC:3439

NIIN:00-004-4547

MSDS Number: BKBJD === Responsible Party ===

Company Name: HI-TECH ALLOYS CORP

Address:25 WEST ST. City:STAFFORD SPRINGS

State:CT ZIP:06076 Country:US

Info Phone Num:203-684-6326

Emergency Phone Num:203-684-6326

CAGE:64576

=== Contractor Identifica

tion ===

Company Name: HI-TECH ALLOYS CORP

Address:47 CAPITAL DR Box:City:WALLINGFORD

State:CT

ZIP:06492-2318 Country:US CAGE:64576

======= Composition/Information on Ingredients ========

Ingred Name:IRON CAS:7439-89-6 PTECS #:NO456550

RTECS #:NO4565500

Other REC Limits:10 MG/M3 FOR FE2O3

Ingred Name: CHROMIUM (SARA III)

CAS:7440-47-3

RTECS #:GB4200000

Other REC Limits: 0.05 MG/M3 CR(VI)

OSHA PEL:1 MG/M3

ACGIH TLV:0.5 MG/M3; 9192

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name: NICKEL (SARA III)

CAS

:7440-02-0

RTECS #:QR5950000

Other REC Limits: NONE SPECIFIED

OSHA PEL:1 MG/M3

ACGIH TLV:1 MG/M3; 9192

Ingred Name: MANGANESE (SARA III)

CAS:7439-96-5

RTECS #:OO9275000

Other REC Limits:1 MG/M3 OSHA PEL:(C) 5 MG/M3 DUST

ACGIH TLV:5 MG/M3 DUST 9293

Ingred Name:SILICON

CAS:7440-21-3

RTECS #:VW0400000

Other REC Limits: 3 MG/M3 AS SIO2

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Name: MOLYBDENUM

CAS:7439-98-7

RTECS #:QA4680000

Other REC Limits: NONE SPECIFIED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3; 9293

Ingred Name:NIOBIUM

CAS:7440-03-1

Other REC Limits: 5 MG/M3

Ingred Name:TITANIUM DIOXIDE

CAS:13463-67-7

RTECS #:XR2275000

Other REC Limits: NONE SPECIFIED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Name: POTASSIUM TITANATE

CAS:12030-97-6

Other REC Limits: NONE SPECIFIED

Ingred Name: CALCIUM CARBONATE (MARBLE) (LIMESTONE)

CAS:1317-65-3

RTECS #:EV9580000

Other REC Limits:5 MG/M3 AS CAO

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9192

Ingred Name:F

LUORSPAR CAS:14542-23-5

Other REC Limits: 2.5 MG/M3 AS F

Ingred Name: SODIUM FLUOALUMINATE (CRYOLITE)

CAS:15096-52-3 RTECS #:WA9625000

Other REC Limits: 2.5 MG/M3 AS F

Ingred Name:POTASSIUM ALUMINUM SILICATE (FELDSPAR)

CAS:68476-25-5

Other REC Limits: 2 MG/M3

Ingred Name: POTASSIUM SILICATE

CAS:1312-76-1

Other REC Limits: 5 MG/M3

Ingred Name: SODIUM SILICATE

CAS:1344-09-8

Other REC Limits:5 MG/M3

Ingred Name: POTASSIUM HYDROXIDE (SARA III)

CAS:1310-58-3

RTECS #:TT2100000

Other REC Limits: NONE SPEC

**IFIED** 

OSHA PEL:C, 2 MG/M3

ACGIH TLV:C 2 MG/M3; 9192

EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

========== Hazards Identification ================

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:SHORT TERM EXPOSURE TO WELDING FUMES, GASES OR DUST MAY RESULT IN DISCOMFORT SUCH AS DIZZINESS, NAUSEA, FEVER, DRYNESS AND/OR IRRITATION OF NOSE, THROAT AND EYES. SKIN SENSITIVITY M

AY ALSO BE NOTED. L ONG TERM EXPOSURE TO

FUMES/GASES/DUST MAY CAUSE PULMONARY IRRITATION OR PNEUMOCONIOSIS; & SIDEROSIS FROM IRON FUMES.

Explanation of Carcinogenicity:NICKEL AND CHROMIUM ARE CONSIDERED POSSIBLE CARCINOGENS UNDER OSHA. RESPIRATORY CANCER FROM WELDING IS UNCONFIRMED.

Effects of Overexposure:EXPOSURE TO WELDING FUMES MAY RESULT IN DISCOMFORT SUCH AS DIZZINESS, NAUSEA, FEVER, DRYNESS AND/OR IRRITATION OF NOSE, THROAT AND EYES. SKIN SENSITIVITY MAY ALSO BE

NOTED. WATERY EYES, HEADACHE, BREA THING DIFFICULTY, FREQUENT COUGHING AND/OR CHEST PAINS MAY OCCUR FROM ACUTE EXPOSURE. TOXIC GASES CAN BE FATAL. Medical Cond Aggravated by Exposure: INDIVIDUALS WITH IMPAIRED PULMONARY FUNCTION OR ILLNESS MAY HAVE SYMPTOMS EXACERBATED BY IRRITANTS CONTAINED IN WELDING FUMES. ============== First Aid Measures =========================== First Aid:IN CASE OF ELECTRICAL SHOCK, TURN OFF POWER PRIOR TO REMOVAL FROM EXPOSURE AREA AND ADM INISTRATION OF FIRST AID. REMOVE FROM EXPOSURE AREA AND CALL FOR MEDICAL AID. ADMINISTER OXYGEN IF BREATHING IS D IFFICULT. IF NOT BREATHING, BEGIN ARTIFICIAL RESPIRATION. IF NO DETECTABLE PULSE, BEGIN EXTERNAL HEART MASSAGE. EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY THE AMERICAN RED CROSS. =========== Fire Fighting Measures ========================== Extinguishing Media: NON-COMBUSTIBLE. FOR SURROUNDING FIRE USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY CHEMICAL. Fire Fighting Procedures: WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL FACED SELF CONTAINED BREATHING APPARATUS. COOL FIRE EXPOSED CONTAINERS WITH WATER SPRAY. CONTAIN RUNOFF. Unusual Fire/Explosion Hazard: NONE. WELDING PROCEDURES MAY PRODUCE HAZARDOUS DECOMPOSITION PRODUCTS AND FUMES. ========= Accidental Release Measures ============ AND PLACE IN SUITABLE DOT APPROVED CONTAINERS AND DISPOS

Spill Release Procedures: CLEAN UP ANY GRINDING DUST OR WASTE RESIDUES E OF IN

FULL COMPLIANCE WITH FEDERAL, STATE AND LOCAL REGULATIONS. AVOID INHALATION AND SKIN EXPOSU RE.

============ Handling and Storage ===========================

Handling and Storage Precautions: WEAR GLOVES AND FLAME RETARDANT CLOTHING WHEN CUTTING, GRINDING OR WELDING. DO NOT EXPOSE SKIN TO RADIATION WHEN HOT CUTTING OR WELDING.

Other Precautions: PROVIDE PROTECTIVE SCREENS TO SHIELD OTHERS. WHEN ELECTRODES AND FLUXES ARE CONSUMED, THE FUME AND GAS DECOMPOSITION PRODUCTS GENERATED ARE DIFFERENT IN FORM FROM THE INGREDIENTS LISTED. NEW COMPOUNDS NOT IN THE ELECTRODES MAY FORM.

====== Exposure Controls/Personal Protection ========

Respiratory Protection: USE WELD FUME RESPIRATOR OR AIR SUPPLIED RESPIRATOR WHEN CUTTING, GRINDING OR WELDING IN A CONFINED SPACE OR WHERE LOCAL EXHAUST OR GENERAL VENTILATION DOES NOT KEEP EXPOSURE BELOW RECOMMENDED LIMITS. USE ONLY NIOSH APPROVED RESPIRATORS.

Ventilation: USE ENOUGH VENTILATI

ON WHEN CUTTING, GRINDING OR WELDING TO

KEEP THE DUST, FUMES & GASES FROM THE WORKERS BREATHING ZONE

Protective Gloves:FLAMEPROOF GAUNTLER GLOVES

Eye Protection: OSHA APPROVED GOGGLES/FACE SHIELD W/LENS

Other Protective Equipment:FLAME RETARDANT CLOTHING WHEN CUTTING, GRINDING OR WELDING. DO NOT EXPOSE SKIN TO RADIATION WHEN HOT CUTTING OR WELDING.

Work Hygienic Practices:WASH THOROUGHLY BEFORE EATING OR SMOKING. LAUNDER CONTAMINATIED CLOTHING BEFORE REUSE.

Supplemental Safety and

Health

WELDING AND HOT CUTTING FUMES & GASES CANNOT BE CLASSIFIED SIMPLY.
THEIR COMPOSITION AND QUANTITY ARE DEPENDENT ON THE METAL BEING
WELDED, THE PROCEDURES, PROCESSES AND THE TYPE OF WIRE OR
ELECTRODES USED. OTHER INFLUENCING FACTORS ARE THEPRESENCE OF
CONTAMINANTS. CHLORINATED SOLVENTS MAY DECOMPOSE TO TOXIC GASES.

==============	Physical/Chemical Properties	===========

HCC:N1

Melt/Freeze Pt:M.P/F.P Text:2600F,1427C

Vapor Pres:NIL Vapor Density:NIL

vapor Density:N

Spec Grav

ity:8

Solubility in Water: INSOLUBLE

Appearance and Odor: SOLID ODORLES METAL

======== Stability and Reactivity Data =========

Stability Indicator/Materials to Avoid:YES

STRONG ACIDS & ALKALIES.

Stability Condition to Avoid:NONE

Hazardous Decomposition Products:WELDING/CUTTING OPERATIONS MAY INCLUDE ELEMENTAL METALS, OXIDES OF THE METALS, FUMES/GASES & ELECTROMAGNETIC RADIATION.

====== Disposal Considerations ==========

Waste Disposal Method

## s:DISPOSE I/A/W FEDERAL, STATE & LOCAL REGULATIONS

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitabil ity of this information to their particular situation.