FSC:8040 NIIN:00-262-9028 MSDS Number: BKHKV === Responsible Party ===

Company Name: CLIFTON ADHESIVE, INC

Address:BURGESS PLACE

City:WAYNE State:NJ

ZIP:07474-0832

Info Phone Num:(201) 694-0845

Emergency Phone Num:(201) 694-0845

CAGE:79833

=== Contractor Identification ===

Company Name: CLIFTON ADHESIVE INC

Address:BURGESS PL

Box:City:WAYNE

State:NJ ZIP:07470 Country:US

Phone:201-694-0845; 973-694-0845

CAGE:79833

======= Composition/Information on Ingredients ========

Ingred Name: HEXANE (N-HEXANE)

CAS:110-54-3

RTECS #:MN9275000 Fraction by Wt: 60% Other REC Limits:50 PPM OSHA PEL:500 PPM ACGIH TLV:50 PPM; 9293

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Rou

tes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: INHALATION: NAUSEA, NARCOSIS, CENTRAL NERVOUS SYSTEM DAMAGE, IRRITATION TO MUCOUS MEMBRANES. EYES: IRRITTION. SKIN: DRYNESS. INGESTION: VOMITING, NUMBNESS, TINGLING & WEAKNESS OF ARMS/LEGS. **Explanation of Carcinogenicity:NONE** Effects of Overexposure: INHALATION: NAUSEA, NARCOSIS, CENTRAL NERVOUS SYSTEM DAMAGE, IRRITATION TO MUCOUS MEMBRANES. S KIN: DRYNESS. INGESTION: VOMITING, NUMBNESS, TINGLING & WEAKNESS OF ARMS/LEGS. EYES: IRRITATION. Medical Cond Aggravated by Exposure: RESPIRATORY AILMENTS First Aid:SKIN: WASH W/SOAP & WATER. EYES: FLUSH W/CLEAN WATER. INGESTION: DON'T INDUCE VOMITING. INHALATION: REMOVE TO FRESH AIR OR GIVE OXYGEN. USE CPR IF PATIENT ISN'T BREATHING. OBTAIN MEDICAL ATTENTION IN ALL CASES. ====== Fire Figh ting Measures ========= Flash Point Method:TCC Flash Point:-25F Autoignition Temp: Autoignition Temp Text: 510 F Lower Limits:1% Upper Limits:7.5% Extinguishing Media:CO2, FOAM, DRY CHEMICAL Fire Fighting Procedures: NIOSH/MSHA APPROVED SCBA SHOULD BE WORN. USE WATER SPRAY TO COOL FIRE EXPOSED STRUCTURES/DISPERSE VAPOR CLOUD IF FIRE ISN'T PRESENT. Unusual Fire/Explosion Hazard: VAPOR IS > AIR & MAY TRAVEL CONSIDERABLE DISTANCE TO SOURCES OF IGNITION/FLASHBACK. AUTOIGNTION TE MP: 510F. ========= Accidental Release Measures ============= Spill Release Procedures: ABSORB SPILL IN SAND, EARTH, VERMICULITES, OIL-DRI, OR SOL-SPEED-DRI. SHOVE ABSORBED MATERIAL INTO STEEL CONTAINER/COVER. ============ Handling and Storage ===========================

Handling and Storage Precautions:STORE IN APPROVED SOLVENT STORAGE AREA. KEEP TIGHTLY CLOSED. KEEP AWAY FROM HEAT, OPEN FLAMES, SPARKS, HOT SURFACES/OXIDIZING AGENTS.

Other Precautions:KE

EP AREA CLEAN. CLEAN UP SPILLS IMMEDIATELY.

====== Exposure Controls/Personal Protection ========

Respiratory Protection:USE NIOSH-APPROVED ATMOSPHERE SUPPLYING OR AIR PURIFYING RESPIRATOR FOR ORGANIC VAPORS AS REQUIRED TO KEEP