View NSN Online: https://aerobasegroup.com/nsn/3439-00-347-5226

AMERICAN SOLDER & FLUX CO INC FORCE INDUSTRIES DIV -- AIRCO 162 MARVEL 3439-00-347-5226

Product ID:AIRCO 162 MARVEL MSDS Date:01/03/1994 FSC:3439 NIIN:00-347-5226 MSDS Number: BWKVY === Responsible Party === Company Name: AMERICAN SOLDER & FLUX CO INC FORCE INDUSTRIES DIV Address:28 INDUSTRIAL BLVD City:PAOLI State:PA ZIP:19301-5000 Country:US Info Phone Num:2 15-647-3575 Emergency Phone Num:215-647-3575 CAGE:70540 === Contractor Identification === Company Name: AMERICAN SOLDER AND FLUX CO INC FORCE CHEMICAL DIV Address:28 INDUSTRIAL BLVD Box:City:PAOLI State:PA ZIP:19301 Country:US Phone:800-424-9300 CAGE:70540 

Ingred Name:BORIC ACID, ORTHOBORIC ACID CAS:10043-35-3 RTECS #:ED4550000 OSHA PEL:10 MG/CUM

Ingred Name:SODIUM TETRABORATE DECAHYDRATE, SODIUM BORATE, BORAX, ANHYDROUS

BORAX CAS:1303-96-4 RTECS #:VZ2275000 OSHA PEL:1 MG/CUM ACGIH TLV:5 MG/CUM

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: INHALATION: RESPIRATORY TRACT IRRITATION, SKIN: MILD DERMATITIS/IRRITATION, EYES: MILD IRRITATION. CHRONIC EXPOSURE MAY CAUSE CNS EFFECTS. Explanation of Carcinogenicity:NONE Effects of Overexposure:IRRITA TION, COUGHING, ERYTHEMA, NAUSEA, VOMITING, DIARRHEA, SNEEZING. Medical Cond Aggravated by Exposure: EXISTING LUNG, SKIN, EYE DISORDERS. First Aid:SKIN: WASH W/SOAP & WATER TO REMOVE ALL RESIDUE. INHALATION: REMOVE TO FRESH AIR. EYES: FLUSH W/WATER FOR 15 MINS TO REMOVE ALL RESIDUE. OBTAIN MEDICAL ATTENTION IN ALL CASES. Extinguishing Media:NONE -PRODUCT IS AN INHERENT RETARDANT. Fire Fighting Procedures: WEAR SELF CONTAINED BREATHING APPARATUS. **Unusual Fire/Explosion Hazard:NONE** 

Spill Release Procedures: CONTAIN, ABSORB/SWEEP UP. REMOVE TO CHEMICAL SEWER. FLUSH AREA TO CHEMICAL SEWER.

Handling and Storage Precautions:STORE MATERIAL UNDER AMBIENT CONDITIONS. Other Precautions:DON'T WEAR CONTAC T LENSES.

Respiratory Protection: WEAR NIOSH APPROVED MASK IF WORK STATION ISN'T PROPERLY VENTILATED TO EXHAUST ALL FUMES/VAPORS/DUSTS. Ventilation: MAINTAIN AIR FLOW AWAY FROM USER TO REMOVE ALL FUMES/VAPORS/DUSTS SO THE PEL IS NEVER EXCEEDED. Protective Gloves: CHEMICAL & OIL IMPERVIOUS Eye Protection: CHEMICAL TIGHT SAFETY GOGGLES Other Protective Equipment: FULL PROTECTIVE EQUIPMENT NORMALLY USED IN **BRAZE/WELDING OP ERATION** Work Hygienic Practices: REMOVE & PROFESSIONALLY WASH CONTAMINATED CLOTHING BEFORE REUSE. Supplemental Safety and Health Spec Gravity:1.72 Solubility in Water:MODERATE Appearance and Odor:WHITE, GRANULAR POWDER W/NO CHARACTERISTIC ODOR. Stability Indicator/Materials to Avoid:YES ACETIC ANHYDRIDE, ELEMENTAL POTASSIUM. Stability Condition to Avoid: NONE Hazardous Decomposition Products: BORON OXIDE FUMES. Waste Disposal Methods: DISPOSE OF IAW/FEDERAL, STATE & LOCAL **REGULATIONS.** 

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all I iability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.