

View Online at <https://aerobasegroup.com/nsn/1560-01-426-8035>

**Aircraft Location:**

1058 frame

**Aircraft Mission Design Series:**

C-141

**Special Features:**

Requested name angle, repair splice; accomodate frame repair 94-ljle-008; p/n 7131249-21 is the opposite configuration

**Material:**

Steel comp 4130

**Material Specification:**

Qq-s-624 federal specification single material response

**Surface Treatment Specification:**

Qq-p-416, type ii, class 2 federal specification single treatment response

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

Yes - demil/mli

**Fiig:**

A11800