

View Online at <https://aerobasegroup.com/nsn/1560-01-426-8036>

Aircraft Location:

1058 frame

Aircraft Mission Design Series:

C-141

Special Features:

Requested name angle, repair splice; accomodate frame repair 94-ljle-008; p/n 7131249-22 is the opposite configuration

Material:

Steel comp 4130

Material Specification:

Qq-s-624 federal specification single material response

Surface Treatment Specification:

Qq-p-416, type ii, class 2 federal specification single treatment response

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

Yes - demil/mli

Fig:

A11800