

View Online at <https://aerobasegroup.com/nsn/6105-01-508-3113>

End Application:

Aircraftembraer

Special Features:

Wpart number contains anti buckling ring; part number 23075489 replaced part number 23070291, nsn 6105-01-446-6968; reason for replacement magnet alternator stator failures showed the possibility of buckling of the lamination stack

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fig:

T321-b