

View Online at <https://aerobasegroup.com/nsn/6105-01-508-3113>

**End Application:**

Aircraftembraer

**Special Features:**

Wpart number contains anti buckling ring; part number 23075489 replaced part number 23070291, nsn 6105-01-446-6968; reason for replacement magnet alternator stator failures showed the possibility of buckling of the lamination stack

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No

**Fig:**

T321-b