PLASTICS/ADDITIVES DIV, CIBA-GEIGY CORP -- RP 1700 RESIN -- 8040-01-046-5056
==================== Product Identification =====================

Product ID:RP 1700 RESIN
MSDS Date:11/08/1985
FSC:8040
NIIN:01-046-5056
MSDS Number: BGHPR
=== Responsible Party ===
Company Name:PLASTICS/ADDITIVES DIV, CIBA-GEIGY CORP
Address:3 SKYLINE DRIVE
City:HAWTHORNE
State:NY
ZIP:10532
Info Phone Num:(914) 347-4700
Emergency Phone Num:(914) 347
-4700
Preparer's Name:ALAN TAYLOR
CAGE:MO729
=== Contractor Identification ===
Company Name:CIBA SPECIALTY CHEMICALS CORPORATION
Address:4917 DAWN AVE
Box:City:EAST LANSING
State:MI
ZIP:48823-5691
Country:US
Phone:517-351-5900
CAGE:02684
Company Name:PLASTICS/ADDITIVES DIV, CIBA-GEIGY CORP
Address:3 SKYLINE DRIVE
City:HAWTHORNE
State:NY
ZIP:10532
Phone:(914) 347-4700
CAGE:MO729

============= Composition/Information on Ingredients =============

Ingred Name:BISPHENOL A DIGLYCIDYL ETHER RESIN
C

AS:25068-38-6
RTECS #:KC2100000

Ingred Name:DIBUTYL PHTHALATE (SARA III)
CAS:84-74-2
RTECS #:TI0875000
OSHA PEL:5 MG/M3
ACGIH TLV:5 MG/M3; 9192
EPA Rpt Qty:10 LBS
DOT Rpt Qty:10 LBS

==================== Hazards Identification ====================

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES
Reports of Carcinogenicity:NTP:NO   IARC:NO OSHA:NO
Health Hazards Acute and Chronic:SKIN & EYES: IRRITATION. INHALATION:
   HEATED PRODUCT MAY PRODUCE INHALABLE VAPORS. SENSITIZATION:

   POSSIBLE IN SUSCEPTIBLE INDIVIDUALS.
Explanation of Carcinogenicity:NONE
Effects of Overexposure:SKIN & EYE IRRITATION AND ALLERGIC SKIN
   REACTIONS.

====================== First Aid Measures ======================

First Aid:SKIN: WASH WITH SOAP & WATER. REMOVE CONTAMINATED CLOTHING &
   LAUNDER BEFORE RE-USE. INGESTION: IF CONSCIOUS, GIVE PLENTY OF
   WATER. INDUCE VOMITING BY TOUCHING BACK OF THROAT WITH FINGER. CALL
   PHYSICIA N. INHALATION: REMOVE TO FRESH AIR. GIVE OXYGEN AND
/OR
   ARTIFICIAL RESPIRATION, IF NEEDED. CALL PHYSICIAN.

==================== Fire Fighting Measures ====================

Flash Point Method:PMCC
Flash Point:400F
Extinguishing Media:CO2, DRY CHEMICAL, FOAM
Fire Fighting Procedures:USE SELF-CONTAINED BREATHING APPARATUS.
Unusual Fire/Explosion Hazard:DECOMPOSITION AND COMBUSTION PRODUCTS MAY
   BE TOXIC.

================== Accidental Release Measures ==================

Spill Release Procedures:REMOVE SPILLAGE BY ABSORBING IN ABSORBE

NT
  MATERIAL.

==================== Handling and Storage ======================

Handling and Storage Precautions:WARNING: CAUSE SKIN & EYE IRRITATION.
  MAY CAUSE ALLERGIC SKIN REACTION. AVOID CONTACT W/EYES, SKIN, &
  CLOTHING.
Other Precautions:PROLONGED OR REPEATED CONTACT W/SKIN. WASH THOROUGHLY
  AFTER HANDLING. NUISANCE DUST MAY BE GENERATED WHEN SANDING OR
  SAWING CURED MATERIAL.

============= Exposure Controls/Personal Protection =============

Respiratory Protection:U
SE NIOSH APPROVED ORGANIC VAPOR CARTRIDGE
  RESPIRATOR WHEN VAPOR/MIST EXPOSURE IS LIKELY
Ventilation:GENERAL MECHANICAL & LOCAL EXHAUST
Protective Gloves:IMPERMEABLE
Eye Protection:WEAR SPLASH-PROOF CHEMICAL GOGGLES
Supplemental Safety and Health

================== Physical/Chemical Properties ==================

HCC:N1
Vapor Pres:.016
Spec Gravity:1.12-1.15
Solubility in Water:INSOLUBLE
Appearance and Odor:CLEAR COLORLESS TO LIGHT STRAW COLORED LOW VISOSITY
  LIQUID.
Percent Volatiles b
y Volume: