## NSN 6080-01-377-5858

Fiber Optic System Repair Kit - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/6080-01-377-5858

| Component Quantity:     |  |
|-------------------------|--|
| 53                      |  |
| Component Documer       | nt Origin:   |
| Government              |  |
| Document Source:        |  |
| 80063                   |  |
| Document Type:          |  |
| Military drawing        |  |
| Component Documer       | nt Page Number:  |
| 1                       |  |
| Supply Items And Qu     | antities:  |
| Label 7; bottle 7; tray | 1; sleeve 2; retainer assembly 1; screw 4; bushing 5; washer 5; bend limiter subassembly 1; cap-plug, protective |
| dust and moisture sea   | 1; lanyard assembly 1; wedge 1; adapter bushing 1; nut 2; shell assembly, fiber optic connector 1; connctor body |
| assembly, fiber optic-p | olug and receptacle 1; plate 1; sleeve 2; spring 2; retaining ring 4; contact, fiber optic-biconic               |
| Document Identificati   | on:  |
| A3102645                |  |
| Shelf Life:             |  |
| N/a                     |  |
| Unit Of Measure:        |  |
|                         |  |
| Demilitarization:       |  |
| Yes - demil/mli         |  |
| Fiig:                   |  |
| A23800                  |  |