

ALLEN L B CO INC -- FLUX, SOLDERING, LIQUID, ROSIN BASE SC100 -- 3439-00-009-8808

=====  
Product Identification  
=====

Product ID:FLUX, SOLDERING, LIQUID, ROSIN BASE SC100

MSDS Date:12/01/1994

FSC:3439

NIIN:00-009-8808

MSDS Number: BCVGN

=== Responsible Party ===

Company Name:ALLEN L B CO INC

Address:725 N CENTRAL

City:WOOD DALE

State:IL

ZIP:60191-1240

Country:US

Info Phone Num:708-595-2600

Emergen

cy Phone Num:708-595-2600

CAGE:70279

=== Contractor Identification ===

Company Name:L.B. ALLEN CO INC

Address:725 N CENTRAL

Box:City:WOODALE

State:IL

ZIP:60191-1240

Country:US

Phone:708-595-2600

CAGE:70279

=====  
Composition/Information on Ingredients  
=====

Ingred Name:ROSIN ACID

CAS:8050-09-7

Other REC Limits:NONE RECOMMENDED

Ingred Name:ISOPROPYL ALCOHOL (SARA III)

CAS:67-63-0

RTECS #:NT8050000

Fraction by Wt: 400%PPM

Other REC Limits:NONE RECOMMENDED

OSHA PEL:400 PPM

ACGI

=====  
===== Hazards Identification =====  
=====

LD50 LC50 Mixture:TLV=400PPM.

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:GIDDINESS, DIZZINESS, SLURRED SPEECH,  
DISORIENTATION, POSSIBLE UNCONSCIOUSNESS.

Explanation of Carcinogenicity:NONE SPECIFIED BY MANUFACTURER.

Effects of Overexposure:GIDDINESS, DIZZINESS, SLURRED SPEECH,  
DISORIENTATION, PO

SSIBLE UNCONSCIOUSNESS.

Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.

=====  
===== First Aid Measures =====  
=====

First Aid:REMOVE TO FRESH AIR IF INHALED. IN CASE OF EYE OR SKIN  
CONTACT FLUSH WITH PLENTY OF WATER. IF SWALLOWED DO NOT INDUCE  
VOMITING. DRINK LUKEWARM WATER. GET IMMED MED ATTN.

=====  
===== Fire Fighting Measures =====  
=====

Flash Point Method:COC

Flash Point:69.8F,21.0C

Extinguishing Media:WATER, FOAM  
OR DRY CHEMICAL.

Fire Fighting Procedures:DIVERT WATER TO BASE OF FLAME.

Unusual Fire/Explosion Hazard:OVERHEATING OF PRODUCT IN CLOSED  
CONTAINERS CAN CAUSE EXPLOSION HAZARD.

=====  
===== Accidental Release Measures =====  
=====

Spill Release Procedures:USING AN OXYGEN MASK OR GOOD VENTILATION OR  
FAN, SCOOP UP MAJORITY OF SPILL. WIPE UP BLANCE WITH RAGS FOR  
DISPOSAL.

=====  
===== Handling and Storage =====  
=====

Handling and Storage Precaution

s:KEEP IN AREA WHERE PRODUCT WILL NOT  
OVERHEAT.

Other Precautions:KEEP AWAY FROM OPEN FLAMES.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE ORGANIC MASK OR OXYGEN (IF NO HOOD OR  
BLOWER).

Ventilation:VENTILATION:GOOD CROSS VENTILATION. LOCAL EXHAUST:EXHAUST  
FAN.

Protective Gloves:RUBBER GLOVES

Eye Protection:GOGGLES

Other Protective Equipment:RUBBER APRON TO PREVENT SPILL ON CLOTHING.

Work Hygienic Practices:WASH HANDS AFTER HANDLING.

Supplemental Safety and Health

MSDS UNDATED

===== Physical/Chemical Properties =====

HCC:F2

Boiling Pt:B.P. Text: