

CORNELL-DUBILIER ELECTRONIC DIV OF FED PAC ELEC -- DYRT6150 -- 5910-00-128-6275
===== Product Identification =====

Product ID: DYRT6150
MSDS Date: 01/01/1985
FSC: 5910
NIIN: 00-128-6275
MSDS Number: BCZYB
=== Responsible Party ===
Company Name: CORNELL-DUBILIER ELECTRONIC DIV OF FED PAC ELEC
Address: ONE INTERCHANGE PLZ
City: WAYNE
State: NJ
ZIP: 07470
Country: US
Emergency Phone Num: 508-996-8561
CAGE: 1465
5

=== Contractor Identification ===
Company Name: CORNELL-DUBILIER ELECTRONICS
Address: ONE INTERCHANGE PLZ
Box: City: WAYNE
State: NJ
ZIP: 07470
Country: US
Phone: 201-694-8600
CAGE: 14655

===== Composition/Information on Ingredients =====

Ingred Name: POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)
CAS: 1336-36-3
RTECS #: TQ1350000
EPA Rpt Qty: 1 LB
DOT Rpt Qty: 1 LB

===== Hazards Identification =====

Effects of Overexposure: ABSORBED THRU SKIN, LUNGS, INTES

TINE.CAUSES

CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)

=====
First Aid Measures
=====

First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR.AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UNC ONSCIOUS PERSON VOMIT.

=====
Accidental Release Measures
=====

Spill Release Procedures:USE ABSORBENT & DIKES TO PREVENT RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.

=====
Handling and Storage
=====

Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD
Ventilation:LOCAL EXHAUST
Protective Gloves:RUBBER-IMPERV
Eye Protection:GOGGLES,FACE SHIELD
Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT
Supplemental Safety and Health
OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.

=====
Physical/Chemical Properties
=====

HCC:Z3
Appearance and Odor:LIGHT STRAW-COLORED LIQUID,AROMATIC ODOR

=====
Stability and Reactivity Data
=====

STRONG OXIDIZERS

=====
Disposal Considerations
=====

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPER

ATURE INCINERATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.