

PORTER PAINT -- 351B,ZINC-LOCK INORGANIC ZINC,ZINC POWDER -- 8010-00-145-0190

=====
Product Identification
=====

Product ID:351B,ZINC-LOCK INORGANIC ZINC,ZINC POWDER

MSDS Date:01/01/1987

FSC:8010

NIIN:00-145-0190

Kit Part:Y

MSDS Number: BDCDW

=== Responsible Party ===

Company Name:PORTER PAINT

Emergency Phone Num:502-588-9200

CAGE:KO267

=== Contractor Identification ===

Company Name:COURTAULDS CO

ATINGS INC

Address:400 S 13TH STREET

Box:City:LOUISVILLE

State:KY

ZIP:40203-1714

Country:US

Phone:502-588-9651

CAGE:50411

Company Name:PORTER PAINT

CAGE:KO267

=====
Composition/Information on Ingredients
=====

Ingred Name:ZINC OXIDE

CAS:1314-13-2

RTECS #:ZH4810000

Fraction by Wt: 3%

OSHA PEL:15MG/M3 TDUST/5 FUME

ACGIH TLV:10MG/M3 TDUST; 9293

Ingred Name:ZINC (SARA III)

CAS:7440-66-6

RTECS #:ZG8600000

Fraction by Wt: 97%

OSHA PEL:10 MG ZNO/M3

ACGIH TLV:10 MG ZNO/M3; 9192

EPA

Rpt Qty:1000 LBS
DOT Rpt Qty:1000 LBS

Ingred Name:LEAD (SARA III)
CAS:7439-92-1
RTECS #:OF7525000
Fraction by Wt: 0.07%
OSHA PEL:0.05 MG/M3;1910.1025
ACGIH TLV:0.15 MG/M3;DUST 9192
EPA Rpt Qty:1 LB
DOT Rpt Qty:1 LB

=====
Hazards Identification
=====

Effects of Overexposure:INHAL:IRRIT RESP TRACT OR ACUTE NERVOUS SYSTEM
CAUSING HDCH,DIZZ OR NAUS.EYE,SKIN:PRIMARY IRRITATION

=====
First Aid Measures
=====

First Aid:
NHAL:REMOVE FROM EXPOS.KEEP WARM AND QUIET.CALL
MD.EYES:FLUSH IMMEDIATELY WITH LARGE AMOUNTS OF WATER FOR AT LEAST
15 MINUTES.TAKE TO PHYSICIAN FOR MEDICAL TREATMENT.SKIN:WASH
AFFECTED AREAS WITH LAR GE AMOUNTS OF WATER.REMOVE CONTAM CLOTHING.

=====
Fire Fighting Measures
=====

Flash Point:N/R(PER MFR)
Extinguishing Media:FOAM,DRY CHEMICAL,CO*2
Fire Fighting Procedures:KEEP CONTNR TIGHT CLOSED.ISOL FROM IGNIT
SOURCE.WEAR SCBA.
Unusual Fire/Expl
losion Hazard:CLOSED CONTNR MAY EXPLO.AVOID EXPOS TO
DECOMP.IF NO ELECTRICITY,WATER SPRAY W/ FOG NOZ USED TO COOL.

=====
Accidental Release Measures
=====

Spill Release Procedures:REMOVE ALL SOURCES OF IGNITION(FLAMES,HOT
SURFACES & ELECTRICAL,STATIC OR FRICTION SPARKS).AVOID BREATHING
VAPORS,WEAR APPROVED(NIOSH OR MSHA) RESPIRATOR AND VENTILATE
AREA.REMOVE WITH INERT ABSORBENT SUCH AS SAND,KITTY LITER,ETC &
USE NON-SPARK TOOL

=====

==== Handling and Storage =====

Handling and Storage Precautions: SECURE CLOSURES & KEEP CONTAINERS UPRIGHT TO PREVENT LEAKAGE. DO NOT STORE ABOVE 120F. DO NOT TAKE INTERNALLY. WASH HANDS BEFORE EATING OR SMOKING.

Other Precautions: DO NOT GET IN EYES, SKIN. AVOID BREATH VAP OR SPRAY MIST. KEEP AWAY FROM IGNIT SOURCE. GROUND CONTNR WHEN POURING. AVOID FREE FALL OF LIQ ABOVE FEW INCH. USE ONLY NON-FERROUS TOOLS, NON-SPARKING SHOE

==== Exposure Controls/Personal Protection =====

Respiratory Protection: NIOSH/MSHA APPRVD EQUIP, ONLY. IN CONFINED AREA, AIR-LINE RESP, HOOD-SUP

Ventilation: GEN DILUT OR LOCAL EXHST TO KEEP