View NSN Online: https://aerobasegroup.com/nsn/8010-00-221-2809 PRATT AND LAMBERT INC -- 703-100 -- 8010-00-221-2809 ============ Product Identification ========================= Product ID:703-100 MSDS Date:01/01/1985 FSC:8010 NIIN:00-221-2809 MSDS Number: BDJWD === Responsible Party === Company Name: PRATT AND LAMBERT INC Address:945 BURLINGTON Box:206 City: KANSAS CITY State:MO ZIP:64141 Country:US CAGE:92216 === Contractor Identification === Company Name: PRATT AND LAMBERT INC Address :945 BURLINGTON Box:206 City: KANSAS CITY State:MO ZIP:64141 Country:US CAGE:92216 ======= Composition/Information on Ingredients ======== Ingred Name: CELLOSOLVE SOLVENT 10-20% RTECS #:KK8550000 **ACGIH TLV:100 PPM** Ingred Name: NAPHTHA (PETROLEUM SPIRITS OR BENZIN) CAS:8030-30-6 RTECS #:SE7555000 OSHA PEL:100 PPM =========== Hazards Identification ==========================

Effects of Overexposure:ANESTHETIC,IRRITATION OF RESP TRACT,CNS DEPRESSION.PRIMARY IRRITATION OF S

KIN AND EYES.
======================================
First Aid:SKIN/EYES:FLUSH WITH PLENTY OF WATER.REMOVE CONTAMINATED CLOTHES. INHAL:MOVE TO FRESH AIR. CALL DR.IF NEEDED.
======================================
Flash Point:40 C/104 F TCC Lower Limits:1.10
Extinguishing Media:NFPA CLASS B EXTINGUISHER.POLYMER FOAM FOR LARGE FIRES
Fire Fighting Procedures:SELF-CONTAINED BREATHING APPARATUS.WATER WITH FOG NOZZLE. Unusual F
ire/Explosion Hazard:KEEP CONTAINERS TIGHTLY CLOSED.ISOLATE FROM HEAT,SPARKS,FLAME.DO NOT APPLY TO VERY HOT SURFACES.
========= Accidental Release Measures ==========
Spill Release Procedures:REMOVE ALL SOUCES OF IGNITION.AVOID BREATHING VAPORS.VENTILATE AREA.REMOVE WITH INERT ABSORBENT AND NON-SPARKING TOOLS.
=========== Handling and Storage =============
Handling and Storage Precautions:DO NOT STORE ABOVE 120 F. STORE LARGE AMTS.IN OS HA APPROVED BUILDING.
Other Precautions:GROUND CONTAINER WHEN POURING.AVOID FREE FALL OF LIQUID IN EXCESS OF FEW INCHES.DO NOT TAKE INTERNALLY.ADD LABLE WARNING.DO NOT FLAME CUT,BRAZE OR WELD WITH OUT RESPIRATOR OR VENT.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:BUREAU OF MINES APPROVED FILTER, RESPIRATOR OR HOOD AS REQUIRED.
Ventilation:GENERAL DILUTION TO KEEP LEL & TLV BELOW LIMITS Protective Gloves:YES
Eye Protection: AGAINST SPLAS

Stability Condition to Avoid:FIRE,HEAT,HOT SURFACES

======= Disposal Considerations ==========

Waste Disposal Methods: ACCORDING TO REGULATIONS. DO NOT INCINERATE CLOSED CONTAINERS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclai

ms all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.