

CHEM SOURCES INC.(MICHEL & PELTON CO.) -- TROLUOIL -- 6810-00-238-8119

=====  
Product Identification  
=====

Product ID:TROLUOIL

MSDS Date:01/01/1985

FSC:6810

NIIN:00-238-8119

MSDS Number: BDMCK

=== Responsible Party ===

Company Name:CHEM SOURCES INC.(MICHEL & PELTON CO.)

Emergency Phone Num:415-652-1610

CAGE:0BP09

=== Contractor Identification ===

Company Name:CHEM SOURCES INC.(MICHEL & PELTON CO.)

CAGE:0BP09

=====  
Composition/Information on Ingredients  
=====

Ingred Name:LIGHT ALIPHATIC SOLVENT NAPHTHA(CAS NO. 64742-89-8)

Fraction by Wt: 99.0%

ACGIH TLV:300 PPM

=====  
Hazards Identification  
=====

Effects of Overexposure:INHALING:ANESTHETIC IRRITATES RESPIRATORY  
TRACT.SKIN & EYES IRRITATION,SERIOUS NERVOUS SYST.DEPRESS.

=====  
First Aid Measures  
=====

First Aid:SKIN:FLUSH WITH PLENTY OF WATER.

EYES:FLUSH W/PLENTY OF WATER

FOR 15 MINS & GET MEDICAL ATTENTION.AFTER HIGH VAPOR

EXPOSURE,REMOVE TO FRESH AIR,RESTORE BREATHING IF NEEDED.IF

SWALLOWED,CALL A DOCTOR IM MEDIATELY.DO NOT INDUCE VOMITING.

=====  
Fire Fighting Measures  
=====

Flash Point:18F,-8C,TCC

Lower Limits:1.2

Extinguishing Media:CO\*2 OR FOAM,DRY CHEMICAL

Fire Fighting Procedures:USE AIR-SUPPLIED BREATHING MASKS,H\*2O TO COOL  
CONTS.

Unusual Fire/Explosion Hazard:CLOSED CONTS.MA

Y EXPLODE IF EXPOSED TO  
EXTREME HEAT.ISOLATE FR OXIDIZERS,HEAT,SPARKS,ELECT.EQUIP.

===== Accidental Release Measures =====

Spill Release Procedures:MFR.SPECIFIES ISOLATE FROM  
OXIDIZERS,HEAT,SPARKS,ELEC.EQUIP & OPEN FLAME.EVACUATE UNPROTECTED  
PERSONS.ELIM.IGNITION SOURCES.STOP LEAK.USE H\*2O TO REDUCE  
VAPORS.SM.SPILL:TAKE UP W/ABSORBENT,SHOVEL INTO DISPOSAL CONTS.LG  
SPILL:DIKE W/COMML.ABSORB.

===== Handling and Storage =====

=====

Handling and Storage Precautions:PROTECT CONTS FROM PHYSICAL  
DAMAGE.ELIMINATE ALL IGNITION SOURCES.DO NOT STORE ABOVE  
49C/120F.STORE LARGE AMTS IN STRUCTURES MADE FOR OSHA CL 1B LIQS.

Other Precautions:AVOID FREE FALL OF LIQUID.GROUND CONTAINERS WHEN  
POURING.DO NOT FLAME CUT,SAW,BRAZE OR WELD.EMPTY CONTAINER  
HAZARDOUS.STORE IN COOL,DRY WELL VENTILATED,LOW FIRE RISK  
AREA.AVOID PHYS.CONTACT

===== Exposure Controls/Personal Protection =====

Res  
piratory Protection:IF TLV ISEXCEEDED,USE SELF-CONTAINED AIR PACK.  
Ventilation:LOCAL EXHAUST IS PREFERRED;MECH IS  
ACCEPTABLE.MAINT.