View NSN Online: https://aerobasegroup.com/nsn/3439-00-267-4787

## TELEDYNE-MCKAY -- 6013 WELDING ROD -- 3439-00-267-4787

============= Product Identification ==============

Product ID:6013 WELDING ROD

MSDS Date:11/01/1986

FSC:3439

NIIN:00-267-4787

MSDS Number: BDRJJ === Responsible Party ===

Company Name: TELEDYNE-MCKAY

Address:850 GRANTLEY RD.

Box:1509 City:YORK State:PA

ZIP:17405-1509

Country:US

Info Phone Num:717-845-7581

Emergency Phone Num:717-845-7581

CAGE:KO940 === Contra

ctor Identification ===

Company Name: HOBART BROS CO MCKAY WELDING PRODUCTS DIV

Address:400 TRADE SQ E

Box:City:TROY

State:OH

ZIP:45373-2900

Country:US

Phone:513-332-5706

CAGE:76254

Company Name: SHAMROCK SUPPLY CO

Address:301 E. ALTON AVE

Box:City:SANTA ANA

State:CA ZIP:92707 Country:US

Phone:714-556-4422

CAGE:48111

Company Name: TELEDYNE-MCKAY

Address:850 GRANTLEY RD.

Box:1509 City:YORK State:PA

ZIP:17405-1509 Country:US

Phone:717-845-7581

CAGE:KO940

====== Composition/Information on In

gredients ========
Ingred Name:IRON CAS:7439-89-6 RTECS #:NO4565500 Fraction by Wt: >99% OSHA PEL:10 MG/CUM ACGIH TLV:5 MG/CUM
Ingred Name:MANGANESE (SARA III) CAS:7439-96-5 RTECS #:OO9275000 Fraction by Wt: 0.25% OSHA PEL:(C) 5 MG/M3 DUST ACGIH TLV:5 MG/M3 DUST 9293
Ingred Name:SILICON CAS:7440-21-3 RTECS #:VW4000000 Fraction by Wt: 0.25% OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/M3 TDUST; 9293
Ingred Name:CARBON CAS:7440-44-0 RTECS #:FF2501000 Fraction by Wt: 0.09% OSHA PEL:15 MG/M3 T DUST ACGIH TLV:2 MG/M3 TDUST; 9293
========== Hazards Identification ============
Effects of Overexposure:METALLIC TASTE,NAUSEA,TIGHTNESS OF CHEST,FEVER,DIZZINESS.EYE,NOSE,THROAT DRYNESS AND IRRITATION.

TECHNIQUES RECOMMENDED BY AMERICAN RED CROSS.

=====

First Aid:REMOVE FROM EXPOSURE AND OBTAIN PROMPT MEDICAL ATTENTION.IF UNCONSCIOUS, GIVE OXYGEN.IF NOT BREATHING GIVE CPR.EMPLOY FIRST AID

======== Fire Fighting Measures =============
Extinguishing Media:EXTINGUISH WITH AGENT SUITABLE FOR SURROUNDING FIRE Unusual Fire/Explosion Hazard:WELDING ARC AND SPARKS CAN IGNITE COMBUSTIBLE PRODUCTS.
======================================
Spill Release Procedures:CLEAN UP ANY GRINDING DUST OR WASTE RESIDUE AND PLACE IN SUITABLE DOT APPROVED DISPOSAL CONTAINER.
======================================
Other Precautions:TRAIN WELDER TO KEEP HIS HEAD OUT OF THE FUMES,MONITOR AIR TO ENSURE ACCEPTABLE EXPOSURES.AVOID ELECTRICAL SHOCK BY MAINTAINING DRY WORK AREA.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:FUME RESP OR AIR SUPPLIED RESP IN CONFINED SPACES.  Ventilation:LOCAL EXHAUST TO MAINTN BELOW TLV.  Protective Gloves:WELDER'S GLOVES  Eye Protection:FACE SHLD W/FILTER LENS.  Other Protective Equipment:SUBST.DK.CLOTH,ARM PROTECTOR,APRON,HA  T,SHOULDR.PROTECTION.  Supplemental Safety and Health  MSDS DATED NOV. 86/OTHER INGRED:OXIDES OF ALUMINUM,CALCIUM,MAGNESIUM,POTASSIUM,SODIUM,TITANIUM/  ===================================
HCC:N1 Appearance and Odor:WELDING ROD 3132 INCH DIA X 12 INCH LONG ====================================
Stability Indicator/Materials to Avoid:YES Hazardous Decomposition Products:FUMES OF METALS AND METAL OXIDES,CO,NO*2,O*3.
========

====== Disposal Considerations ===========

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this

ument should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.