

KINNEY VACUUM CO. -- SUPER X MECHANICAL VACUUM PUMP OIL, D250-76 -- 9150-00-273-8663

=====
Product Identification
=====

Product ID: SUPER X MECHANICAL VACUUM PUMP OIL, D250-76

MSDS Date: 06/25/1987

FSC: 9150

NIIN: 00-273-8663

MSDS Number: BDSBK

=== Responsible Party ===

Company Name: KINNEY VACUUM CO.

Address: 495 TURNPIKE STREET

City: CANTON

State: MA

ZIP: 02021

Country: US

Info Phone Num: 617-828-9500

Eme

Agency Phone Num: 617-828-9500

Preparer's Name: A. H. BORNEMANN

CAGE: 33781

=== Contractor Identification ===

Company Name: KINNEY VACUUM CO A UNIT OF GENERAL SIGNAL CORP

Address: 495 TURNPIKE ST

Box: City: CANTON

State: MA

ZIP: 02021-2702

Country: US

Phone: 617-828-9500

CAGE: 33781

=====
Composition/Information on Ingredients
=====

Ingred Name: MINERAL OIL, PETROLEUM DISTILLATES, SOLVENT-REFINED

(SEVERE) HEAVY PARAFFINIC; (SOLVENT REFINED PARAFFINIC DISTILLATE)

CAS: 64741-88-4

RTECS #

: PY8040501

Fraction by Wt: 100%

Other REC Limits: 5MG/M3 OIL MIST(MFR)

=====
Hazards Identification
=====

LD50 LC50 Mixture: NONE SPECIFIED BY MANUFACTURER.

Routes of Entry: Inhalation: YES Skin: NO Ingestion: NO

Reports of Carcinogenicity: NTP: NO IARC: NO OSHA: NO

Health Hazards Acute and Chronic: HEADACHE, NAUSEA DUE TO INHALATION OF
OIL MIST. OIL IS NOT TOXIC BY INGESTION OR SKIN ABSORPTION.

Explanation of Carcinogenicity: NOT RELEVANT.

Effects of Overexposu

re:SEE HEALTH HAZARDS.

Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.

=====
First Aid Measures
=====

First Aid:INHAL:REMOVE TO FRESH AIR. SKIN:WASH W/SOAP & WATER.
EYES:FLUSH W/WATER FOR AT LEAST 15 MINS. INGEST:DO NOT INDUCE
VOMITING.

=====
Fire Fighting Measures
=====

Flash Point Method:COC

Flash Point:450F,232C

Lower Limits:1%

Upper Limits:6%

Extinguishing Media:CHEMICAL FOAM, DRY CHEMICAL
POWDER & WATER FOG.

Fire Fighting Procedures:WEAR NIOSH/MSHA APPROVED SCBA & FULL
PROTECTIVE EQUIPMENT .

Unusual Fire/Explosion Hazard:NONE

=====
Accidental Release Measures
=====

Spill Release Procedures:MECHANICAL CLEAN UP. USE OIL ABSORBENT (SPEEDI
DRI).

Neutralizing Agent:NONE SPECIFIED BY MANUFACTURER.

=====
Handling and Storage
=====

Handling and Storage Precautions:STORE