Product ID:INNERBOND 2010 FLUID,200 CST MSDS Date:01/20/1986 FSC:9150 NIIN:00-584-3134 MSDS Number: BFGLZ === Responsible Party === Company Name:INLAND PACKAGING Box:644 City:ELIZABETHTOWN State:KY ZIP:42701-9804 Country:US Info Phone Num:502-737-6757 Emergency Phone Num:502-737-6757 CAGE:66172

=== Contractor Identification === Company Name:INLAND PACKAGING INC Address:209 PETERSON DR Box:644 City:ELIZABETHTOWN State:KY ZIP:42701-9804 Country:US Phone:502-737-6757 CAGE:66172

Ingred Name:POLYDIMETHYLSILOXANE CAS:9016-00-6 RTECS #:TQ2690000 Fraction by Wt: 100.0%

Routes of Entry: Inhalation:UNKNOWN Skin:YES Ingestion:YES Reports of Carcinogenici

GET MEDICAL ATTENTION. EYES: IMMEDIATELY FLUSH WITH PLENTY OF WATER FOR 15 MINUTES HOLDING EYELIDS OPEN. GET MEDICAL ATTENTION. SKIN:REMOVE CONTAMINATED CLOTHING. WASH WITH SOAP AND WATER. IF IRRITATION PERSISTS, GET MEDICAL ADVICE. INGESTION:DO NOT INDUCE VOMITING. GIVE NOTHING BY MOUTH IF UNCONSCIOUS. GET IMMEDIA TE

MEDICAL ATTENTION.

Flash Point Method:OC

Flash Point:600F,316C

Extinguishing Media:USE CARBON DIOXIDE, FOAM, DRY CHEMICAL, OR WATER FOG.

Fire Fighting Procedures:FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE. Unusual Fire/Explosion Hazard:NONE KNOWN TO MFR

======= Accidental Release

Measures ===============

Spill Release Procedures:REMOVE IGNITION SOURCES,VENTILATE AREA WELL.ABSORB WITH VERMICULITE OR OTHER MATERIALS, SUCH AS SAWDUST,RAGS,PAPER & PLACE IN CLOSED CONTAINER. USE NON SPARKING TOOLS. WEAR PROPER PROTECTIVE EQUIPMENT DURING CLEAN UP. Neutralizing Agent:NOT APPLICABLE.

Handling and Storage Precautions:STORE IN COOL,DRY WELL VENTED LOW FIRE RISK AREA. PROTECT FROM HEAT,SHO

CK,FRICTION. KEEP CONTAINERS CLOSED.

Other Precautions: AVOID DIRECT OR PROLONGED CONTACT WITH SKIN& EYES-WASH HANDS THOROUGHLY AFTER HANDLING-DO NOT DRINK, EAT, SMOKE IN WORK ROOM-AVOID BREATHING ANY VAPORS.

Respiratory Protection:NONE REQUIRED IF USED WITH GOOD VENTILATION.
Ventilation:LOCAL/GENERAL TO MAINTAIN PEL/TLV.
Protective Gloves:NEOPRENE, NITRILE, OR NATURAL RUBBER
Eye Protection:SAFETY GOGGLES WITH OPTIONAL
FACE SHIELD
Other Protective Equipment:EYE WASH STATION AND SAFETY SHOWER,WORK
CLOTHING AND APRON AS REQUIRED.
Work Hygienic Practices:OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND
RECOMMENDED PROCEDURES. DO NOT WEAR CONTAMINATED CLOTHING OR
FOOTWEAR.
Supplemental Safety and Health
AVOID PROLONGED OR REPEATED EXPOSURE. DO NOT GET ON SKIN OR IN EYES. DO
NOT BREATHE VAPORS OR MISTS.

HCC:V6 Boiling Pt:B.P. Text:>3 00F,>149C Vapor Pres: