View NSN Online: https://aerobasegroup.com/nsn/8010-00-584-3148

## ILLINOIS BRONZE POWDER AND PAINT COMPANY -- IB NO 2658 -- 8010-00-584-3148

Product ID:IB NO 2658 MSDS Date:01/01/1985

FSC:8010

NIIN:00-584-3148

MSDS Number: BFGMZ === Responsible Party ===

Company Name: ILLINOIS BRONZE POWDER AND PAINT COMPANY

Address:300 EAST MAIN STREET

City:LAKE ZURICH

State:IL

ZIP:60047-2580 Country:US

Info Phone Num:312-488-8001

**Emergency Ph** 

one Num:800-228-5635

CAGE:91794

=== Contractor Identification ===

Company Name: ILLINOIS BRONZE PAINT COMPANY

Address:300 EAST MAIN STREET

City:LAKE ZURICH

State:IL

ZIP:60047-2580

Country:US

Phone:800-228-5635

CAGE:91794

====== Composition/Information on Ingredients ========

Ingred Name: TOLUENE (SARA III)

CAS:108-88-3

RTECS #:XS5250000 Fraction by Wt: 25.3%

OSHA PEL:200 PPM/150 STEL ACGIH TLV:50 PPM; 9293 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name: METHYLENE CHLORIDE (

Fraction by Wt: 26.7% OSHA PEL:500 PPM/C,1000; Z2 ACGIH TLV:50 PPM, A2; 9192 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS =========== Hazards Identification ========================== Effects of Overexposure: INHALATION-ANESTHETIC; IRRITATION OF RESPIRATORY TRACT: DIZZINESS. SKIN OR EYE-PRIMARY IRRITATION First Aid:FUMES-REMOVE FROM EXPOSURE.MOVE TO FRESH AIR.EYES-FLUSH WITH ARGE AMOUNTS OF WATER FOR AT LEAST 15 MIN. CALL PHYSICIAN.SKIN-WIPE OFF WITH TOWEL.REMOVE REMAINDER WITH MINERAL SPIRITS OR LACQUER REMOVE R.WASH WITH SOAP & WATER Flash Point:-40F,-40C Lower Limits: 1.3% Extinguishing Media:NFPA CLASS B EXTINGUISHERS Fire Fighting Procedures: WATER TO COOL CONTAINERS WEAR GOGGLES & **BREATHING APPARATUS** Unusual Fire/Explosion Hazard: CANS WILL RUPTURE AT 190F AND DISCHARGE **FLAMMAB** LE CONTENTS ======== Accidental Release Measures ============= Spill Release Procedures: REMOVE ALL SOURCES OF IGNITION. AVOID BREATHING VAPORS. VENTILATE AREA. REMOVE WITH INERT ABSORBENT =========== Handling and Storage ============================ Handling and Storage Precautions: DO NOT STORE ABOVE 120F. STORE LARGE QUANTITIES IN BUILDINGS DESIGNED AND PROTECTED FOR STORAGE OF NFPA CLASS 1A FLAMMABLE LIQUIDS Other Precautions: DO NOT SPRAY IN EYES. DO NOT PUNCT

SARA III) CAS:75-09-2

RTECS #:PA8050000

URE OR INCINERATE
CANS.DO NOT FLAME CUT,BRAZE OR WELD WITHOUT BUR. OF MINES APPROVED
RESPIRATOR OR APPROPRIATE VENTILATION

====== Exposure Controls/Personal Protection ========

Respiratory Protection: NONE FOR CASUAL USE

Ventilation: DILUTION OR EXHAUST TO KEEP BELOW TLV

Protective Gloves:NONE

Eye Protection: NO SPECIAL REQUIRED

Supplemental Safety and Health

**B.P.RANGE 6-199C** 

======== Physical/Chemical Properties ===========

HCC:V3

Boiling Pt:B.P. Text:4

2-391F

Percent Volatiles by Volume:89

======== Stability and Reactivity Data ==========

Stability Indicator/Materials to Avoid:YES

Hazardous Decomposition Products: HCL, CO, PHOSGENE

======= Disposal Considerations ===========

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.INCINERATE IN APPROVED FACILITY.DO NOT INCINERATE CLOSED CONTAINERS

Disclaimer (provided with this information by the compiling age ncies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.