View NSN Online: https://aerobasegroup.com/nsn/8010-00-728-3091 AMERON INDUSTRIAL COATINGS DIVISION -- 745-644 -- 8010-00-728-3091 Product ID:745-644 MSDS Date:01/01/1985 FSC:8010 NIIN:00-728-3091 MSDS Number: BFMQX === Responsible Party === Company Name: AMERON INDUSTRIAL COATINGS DIVISION Emergency Phone Num:316-733-1361 CAGE:09869 === Contractor Identification === Company Name: AMERON INDUSTRIAL COATINGS DIVISION Address:20 1 N BERRY ST Box:City:BREA State:CA ZIP:92621-3904 Country:US Phone:714-529-4597 CAGE:09869 ======= Composition/Information on Ingredients ======== Ingred Name: NAPHTHA (PETROLEUM SPIRITS OR BENZIN) CAS:8030-30-6 RTECS #:SE7555000 Fraction by Wt: 35.0% OSHA PEL:100 PPM

Ingred Name:LEAD CHROMATE

Fraction by Wt: 0.25%

========= Hazards Identification ==============

Effects of Overexposure:INHALE:ANESTHETIC,IRRITATION TO AIRWAY, & IF SKIN/EYE CONTACT, HEADA

CHE, DIZZINESS, COMA
======================================
First Aid:INCASE OF CONTACT, FLUSH SKIN AND EYES WITH PLENTY OF WATER WHILE REMOVING CONTAMINATED CLOTHING. IF INHALED, REMOVE TO FRESH AIR. CALL A PHYSICIAN IF SYMPTONS PERSIST.
======================================
Flash Point:85F, 29C TCC Lower Limits:1.1 Extinguishing Media:CARBON DIOXIDE/DRY CHEMICA-SMALL; POLYMER FOAM-LARGE FIRE Fire Fighting Procedures:S ELF-CONTAINED BREATHING APPARATUS AVAILABLE FOR FIREMEN Unusual Fire/Explosion Hazard:CLOSED CONTAINERS EXPOSED TO HEAT MAY EXPLODE DUE TO PRESSURE BUILD-UP
======== Accidental Release Measures ==========
Spill Release Procedures:REMOVE ALL SOURCES OF IGNITION (FLAMES, HOT SURFACES, & ELECTRICAL, STATIC, OR FRICTIONAL SPARKS). AVOID BREATHING VAPORS. VENTILATE AREA. REMOVE WITH INERT ABSORBENT AND NON-SPARKING TOOLS.
============= Handling and Storage ====================================
Handling and Storage Precautions:DO NOT STORE ABOVE 120F. STORE LARGE QUANTITIES IN BUILDINGS DESIGNED AND PROTECTED FOR STORAGE OF NFPA CLASSONE FLAMMABLE (OR COMBUSTIBLE) LIQUID. Other Precautions:DO NOT TAKE INTERNALLY,CONTAINERS SHOULD BE GROUNDED WHEN POURING,AVOID FREE FALL IN EXCESS OF A FEW INCHES,DO NOT FLAME CUT,BRAZE, OR WELD COATED MATERIAL WITHOUT VENTILATION.
====== Exposure Controls/Personal Protection ========
Respi

Waste Disposal Methods:DISPOSE IN ACCORDANCE WITH LOCAL, STATE, AND FEDERAL REGULATIONS. INCINERATE IN APPROVED FACILITY. DO NOT INCINERATE CLOSED CONTAINERS.

Disclaimer (provided with this information by the compiling agen cies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.