View NSN Online: https://aerobasegroup.com/nsn/8040-00-738-1780

GRACE W R AND CO. -- ECCOBOND SOLDER 57C PART A -- 8040-00-738-1780

Product ID: ECCOBOND SOLDER 57C PART A MSDS Date:01/01/1987 FSC:8040 NIIN:00-738-1780 Kit Part:Y MSDS Number: BFMVD === Responsible Party === Company Name: GRACE W R AND CO. Emergency Phone Num:617-828-3300 CAGE:0NAV2 === Contractor Identification === Company Name: GRACE W R & CO EMERSON & CUMING D **EWEY & ALMY CHEM** Address:869 WASHINGTON ST City:CANTON State:MA ZIP:02021-2513 Country:US Phone:617-935-4850 CAGE:04552 Company Name: GRACE W R AND CO Address:919 18TH ST NW **City:WASHINGTON** State:DC ZIP:20006 Country:US Phone:410-659-9000 CAGE:0NAV2

Ingred Name:NO INGREDIENT FOR THIS FORMULATION_INGREDIENT

Effects of Overexposure: IRRIT TO SKIN & EYE UPON DI

RECT CONTACT. HARMFUL IF SWALLOWED.

| ====================================== |
|---|
| First Aid:IMMED FLUSH EYES W/WATER FOR 15 MINUTES. GET MEDICAL ATTN. RMV CONTAMINATED CLOTHING. WASH AFFECTED AREA OF CONTACT W/SOAP & WATER. INGEST:DILUTE W/LG QTY OF WATER. INDUCE VOMITING ONLY IF VICTIM IS C ONSCIOUS. GET IMMED MED HELP. |
| ====================================== |
| Flash Point:>400F,204C Extinguishing Media:CARBON DIOXIDE, DRY CH EMICAL, FOAM, WATER FOG. Fire Fighting Procedures:WEAR SCBA Unusual Fire/Explosion Hazard:TOXIC FUMES MAY BE EVOLVED UPON EXPOSURE TO HEAT OR OPEN FLAME. |
| ====================================== |
| Spill Release Procedures:WIPE UP OR ABSORB W/VERMICULITE OR OTHER ABSORBENT MATERIAL. WIPE UP RESIDUE W/SOLVENT. COLLECT IN SEALED CONTAINERS. |
| ====================================== |
| Handling and Storage Precautions:AVOID SKIN & EYE C ONTACT. AVOID BREATHING VAPORS. USE ONLY WITH ADEQUATE VENTILATION. STORE IN COOL, DRY PLACE. KEEP AWAY FM HEAT OR OPEN FLAME. Other Precautions:NONE |
| ====================================== |
| Respiratory Protection:NONE Ventilation:MECHANICAL (GEN) RECOMMENDED. LOCAL FOR ELEVATED TEMPERATURE Protective Gloves:RUBBER Eye Protection:SAFETY GLASSES Other Protective Equipment:WORK CLOTHING Supplemental Safety and Health PART OF A 2 PART KIT. SEE P/N IND B, THI |

| S NSN FOR ADDITIONAL INFORMATION. MSDS DATED 5-28-85. |
|--|
| ====================================== |
| HCC:N1 Vapor Pres:1 Spec Gravity:3.65 Solubility in Water:NEGLIGIBLE Appearance and Odor:SILVER COLORED PASTE. Percent Volatiles by Volume:NIL |
| ====================================== |
| Stability Indicator/Materials to Avoid:YES STRONG OXIDIZERS,AMINES,AMIDES,MINERAL ACIDS,THIOSULFATE Stability Condition to Avoid:STORAGE IN OPEN CONTAINER,EXP TO HEAT/OPEN FLAME. |
| Hazardous Decomposition Products:CARBON MONOXIDE, CARBON DIOXIDE. |
| ====================================== |
| Waste Disposal Methods:LANDFILL I/A/W ALL LOCAL, STATE & FEDERAL REGULATIONS. |
| Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department |

of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this informati

on to be accurate and

disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.