

AMERON INC -- AMERCOAT,78 CURE -- 8010-00-997-2610

=====
Product Identification
=====

Product ID:AMERCOAT,78 CURE

MSDS Date:01/01/1987

FSC:8010

NIIN:00-997-2610

Kit Part:Y

MSDS Number: BGCKP

=== Responsible Party ===

Company Name:AMERON INC

Address:201 N BERRY ST

City:BREA

State:CA

ZIP:92621-3904

Country:US

CAGE:JO830

=== Contractor Identification ===

Company Name:AMERON INC

CAGE:JO830

Company Na

me:AMERON INTERNATIONAL PROTECTIVE COATINGS GROUP

Address:201 NORTH BERRY ST.

Box:City:BREA

State:CA

ZIP:92821

Country:US

Phone:714-529-1951

CAGE:55849

=====
Composition/Information on Ingredients
=====

Ingred Name:DIETHYLENE TRIAMINE

CAS:111-40-0

RTECS #:IE1225000

Fraction by Wt: 49%

OSHA PEL:1 PPM

ACGIH TLV:S, 1 PPM; 9192

Ingred Name:PROPYLENE GLYCOL MONOMETHYL ETHER

CAS:107-98-2

RTECS #:UB7700000

Fraction by Wt: 25%

OSHA PEL:100 PPM/150 STEL

ACGIH TLV:100 PPM/150STEL;9192

Ingred Name:NAPHTHALENE (SARA III)
CAS:91-20-3
RTECS #:QJ0525000
Fraction by Wt: 16%
OSHA PEL:10 PPM/15 STEL
ACGIH TLV:10 PPM/15 STEL; 9192
EPA Rpt Qty:100 LBS
DOT Rpt Qty:100 LBS

Ingred Name:TRIS 2,4,6-(DIMETHYLAMINOMETHYL) PHENOL, CAS# 90-72-2
CAS:90-72-2
RTECS #:SN3500000
Fraction by Wt: 8%

=====
Hazards Identification
=====

Effects of Overexposure:IRRIT:SKIN,MUC MEMB,EYE,RESP
SYS.INHAL:HDCH,NAUS,DIZ,ASPHYXIA,RESP
SENSIT,ASTHMA.SKIN:SENSIT.SUPP

=====
First Aid Measures
=====

First Aid:INHAL:FRESH AIR.GIVE O*2,CPR.SKIN:WASH THOROUGHLY WITH SOAP
AND WATER.EYE:FLUSH IMMEDIATELY WITH PLENTY OF WATER FOR 15 MINS
AND GET MEDICAL ATTENTION.LAUNDER CONTAMINATED CLOTHING BEFORE
REUSE.INGEST :DO NOT INDUCE VOMITING;CALL PHYSICIAN IMMEDIATELY

=====
Fire Fighting Measures
=====

Flash Point:115F,46C PMCC
Lower Limits:1.7
Extinguishing Media:FOAM,CO*2,DRY CHEMICA
L
Unusual Fire/Explosion Hazard:ISOLATE FROM HEAT,ELECTRICAL
EQUIPMENT,SPARKS AND OPEN FLAME.WEAR SELF-CONTAINED BREATHING
APPARATUS

=====
Accidental Release Measures
=====

Spill Release Procedures:ELIMINATE ALL SOURCES OF IGNITION.USE
ABSORBENT CLEANUP MATERIALS.

=====
Handling and Storage
=====

Handling and Storage Precautions:KEEP CONTAINER CLOSED WHEN NOT IN
USE.STORE IN COOL,DRY,WELL VENTILATED AREA.
Other Pr

Precautions: AVOID PROLONGED BREATHING OF VAPORS OR SPRAY MIST OR CONTACT WITH SKIN AND EYES. WEAR PROTECTIVE BARRIER CREAM ON EXPOSED SKIN. CALLED MFR FOR SOL, APPEARANCE, IDENTITY OF PARTS OF KIT.

===== Exposure Controls/Personal Protection =====

Ventilation: SUFFICIENT VENTILATION TO KEEP AIR CONTAMINANT CONC 1

Spec Gravity: 0.94

Evaporation Rate & Reference: SLOWER THAN ETHER

Solubility in Water: NEGLIGIBLE

Appearance and Odor: LIQUID, SOLVENT ODOR

Percent Volatiles by Volume: 45

ume: 45

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid: YES

STRONG OXIDIZERS

Stability Condition to Avoid: HEAT, OPEN FLAME, ARC OR

SPARKS. LIGHT: PHOTOCHEMICALLY REACTIVE

Hazardous Decomposition Products: CO, CO*2 AND NO*X

===== Disposal Considerations =====

Waste Disposal Methods: IN SEPARATE CLOSED METAL CONTAINER IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.