

J.W.HARRIS CO -- ALLOY 620 WELDING WIRE -- 3439-01-007-8134

=====  
Product Identification  
=====

Product ID:ALLOY 620 WELDING WIRE

MSDS Date:01/01/1987

FSC:3439

NIIN:01-007-8134

MSDS Number: BGCWY

=== Responsible Party ===

Company Name:J.W.HARRIS CO

Emergency Phone Num:513-891-2000

CAGE:27911

=== Contractor Identification ===

Company Name:J. W. HARRIS CO., INC.

Address:10930 DEERFIELD ROAD

Box:City

:CINCINNATI

State:OH

ZIP:45242-4110

Country:US

Phone:513-891-2000

CAGE:27911

=====  
Composition/Information on Ingredients  
=====

Ingred Name:NICKEL (SARA III)

CAS:7440-02-0

RTECS #:QR5950000

Fraction by Wt: 74.0%

OSHA PEL:1 MG/M3

ACGIH TLV:1 MG/M3; 9192

Ingred Name:MOLYBDENUM

CAS:7439-98-7

RTECS #:QA4680000

Fraction by Wt: 16.0%

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3; 9293

=====  
Hazards Identification  
=====

Effects of Overexposure:INHL

:DIZZ,NAUS,URI IRRT,WELD FUME FEVER-  
BODY:ACHE,CHILLS,FEVER.WELDING ARC:POSS EYE & SKN BURNS.

=====  
First Aid Measures  
=====

First Aid:REMOVE TO FRESH AIR, GIVE ART RESP OR OXYGEN AS REQD. CALL  
PHYSICIAN IMMED.

=====  
Fire Fighting Measures  
=====

Flash Point:NONE  
Extinguishing Media:AS REQD FOR NEARBY FIRE.  
Fire Fighting Procedures:AS REQD FOR NEARBY FIRE  
Unusual Fire/Explosion Hazard:WELDING ARC CAN IGNITE COMBUS  
TIBLES.

=====  
Handling and Storage  
=====

Handling and Storage Precautions:DO NOT TOUCH LIVE ELECTRICAL PARTS OF  
WELDING GEAR,INSULATE BODY FROM WORK & GROUND.  
Other Precautions:PROVIDE PROTECTIVE SCREENS, FLASH GOGGLES TO NEARBY  
WORKERS AS REQD. AVOID DIRECT EYE, SKIN EXPOSURE TO WELD ARC.

=====  
Exposure Controls/Personal Protection  
=====

Respiratory Protection:USE DUST,FUME RESPIRATOR AS REQD  
Ventilation:LOCAL EXHAUST, WELDING BOO  
TH  
Protective Gloves:WELDERS GLOVES  
Eye Protection:WELD MASK W/FILTER LENS  
Other Protective Equipment:USE HEAD,BODY PROTECTION AS  
REQD,APRON,HAT,SHOULDER PROTECT  
Supplemental Safety and Health  
MSDS #21780 NON-STD DATED NOV 85.

=====  
Physical/Chemical Properties  
=====

HCC:N1  
Appearance and Odor:SOLID WIRE

=====  
Stability and Reactivity Data  
=====

Stability Indicator/Materials to Avoid:YES  
NONE  
Stability Condition to Avoid:NONE  
Hazardou

s Decomposition Products:WELD FUMES; CARBON, NITROGEN OXIDES,  
OZONE

Disclaimer (provided with this information by the compiling agencies):  
This information is formulated for use by elements of the Department  
of Defense. The United States of America in no manner whatsoever,  
expressly or implied, warrants this information to be accurate and  
disclaims all liability for its use. Any person utilizing this  
document should seek competent professional advice to verify and  
assume responsibility for the suitability of this information to their  
particular situation.