

XEROX CORPORATION -- 6R204, TONER (DRY IMAGER) -- 6850-01-052-0892

=====
Product Identification
=====

Product ID:6R204, TONER (DRY IMAGER)

MSDS Date:01/01/1987

FSC:6850

NIIN:01-052-0892

MSDS Number: BGJCZ

=== Responsible Party ===

Company Name:XEROX CORPORATION

Emergency Phone Num:716-422-2177

CAGE:9K207

=== Contractor Identification ===

Company Name:XEROX CORPORATION

Address:100 CLINTON AVE S

Bo

x:City:ROCHESTER

State:NY

ZIP:14644-1877

Country:US

CAGE:9K207

=====
Composition/Information on Ingredients
=====

Ingred Name:STYRENE AND N-BUTYLMETHACRYLATE COPOLYMER

Fraction by Wt: UNK

Ingred Name:CARBON BLACK

CAS:1333-86-4

RTECS #:FF5800000

Fraction by Wt: UNK

OSHA PEL:3.5 MG/M3

ACGIH TLV:3.5 MG/M3; 9192

=====
Hazards Identification
=====

Effects of Overexposure:PER MFR MSDS,PRODUCT IS NON-TOXIC,MINIMUMJ
IRRITATING TO EYES/NON-IRRI

TATING TO SKIN.

=====
===== First Aid Measures =====

First Aid:EYES:FLUSH W/WATER FOR 5 MINUTES;SKIN:NORMAL WASHING W/SOAP & WATER;INGESTION:RINSE MOUTH W/WATER.

=====
===== Fire Fighting Measures =====

Flash Point:NONE
Extinguishing Media:CO*2, FOAM, DRY CHEM. WATER
Fire Fighting Procedures:NONE
Unusual Fire/Explosion Hazard:TONER IS COMBUSTIBLE.EXPLOSIVE LIMITS OF TONER PARTICLES SUSPENDED IN AIR APPROX EQUAL TO COAL.

=====
===== Accidental Release Measures =====

Spill Release Procedures:LOOSE TONER CAN BE REMOVED USING A VACUUM CLEANER.RESIDUE CAN BE REMOVED W/SOAP & COLD WATER.AFTER REMOVAL OF LOOSE TONER,GARMENTS MAY BE WASHED OR DRY CLEANED.

=====
===== Handling and Storage =====

Handling and Storage Precautions:NONE
Other Precautions:NONE.

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NONE SHOULD BE NEEDED
Ventilation:NONE
Protective Gloves:NONE
Eye Protection:NONE
Other Protective Equipment:NONE
Supplemental Safety and Health
MSDS FROM XEROX CORP DATED:3/27/84

=====
===== Physical/Chemical Properties =====

HCC:N1
Spec Gravity:1.1
Solubility in Water:NEGLIGIBLE
Appearance and Odor:BLACK POWDER,FAINT ODOR

=====
===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES
NONE
Stability Condition to Avoid:NONE

=====

===== Disposal Considerations =====

Waste Disposal Methods:KEEP IN COVERED DRUMS,PENDING DISPOSAL. HANDLE & DISPOSE IN FULL COMPLIANCE WITH ALL APPLICABLE INTERNATIONAL,FEDERAL,STATE, & LOCAL REGULATIONS. PER MFR:DO NOT INCINERATE. NO SPECIAL TECHNIQUES BEYON D NORMAL PRACTICE.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.