View NSN Online: https://aerobasegroup.com/nsn/3460-01-135-2685

Product ID:S-744 (TRUING SLEEVE)

MSDS Date:08/15/1987

FSC:3460

NIIN:01-135-2685

MSDS Number: BGNKB === Responsible Party ===

Company Name: SUNNEN PRODUCTS CO.

Address:7910 MANCHESTER AVE

City:ST LOUIS

State:MO

ZIP:63143-2712 Country:US

Emergency Phone Num:(314)781-2105

Preparer's Name: TERRY MEILER

С

AGE:58436

=== Contractor Identification ===

Company Name: SUNNEN PRODUCTS CO

Address:7910 MANCHESTER AVE

Box: City: SAINT LOUIS

State:MO

ZIP:63143-2712 Country:US

Phone:314-781-2100

CAGE:58436

====== Composition/Information on Ingredients ========

Ingred Name:IRON CAS:7439-89-6 RTECS #:NO4565500

OSHA PEL:10MG/CUM(OXIDE FUME)

ACGIH TLV:5 MG/CUM(OXIDE FUME)

Ingred Name: COPPER (SARA III)

CAS:7440-50-8

RTECS #:GL5325000

OSHA PEL:0.1MG/M3 FUME/1 DUST ACGIH TLV:0.2MG/M3 FUME; 9192

EPA R

pt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name: COBALT (SARA III)

CAS:7440-48-4

RTECS #:GF8750000

OSHA PEL:0.1 MG/M3;AS CO

ACGIH TLV:0.05 MG/M3;DUST 9293

Ingred Name:TIN CAS:7440-31-5 RTECS #:XP7320000 OSHA PEL:2 MG/M3 ACGIH TLV:2 MG/M3; 9192

Ingred Name: GRAPHITE, SYNTHETIC

CAS:7440-44-0

RTECS #:FF5250100

OSHA PEL:15 MG/M3 TDUST ACGIH TLV:2 MG/M3 TDUST; 9293

Ingred Name: MANGANESE (SARA III)

CAS:7439-96-5

RTECS #:OO9275000

OSHA PEL:(C) 5 MG/M3 DUST ACGIH TLV:5 MG/M3 DUST 9293

Ingred Name:

ALUMINUM (SARA III)

CAS:7429-90-5

RTECS #:BD0330000

OSHA PEL:15MG/M3 DUST/5 FUME ACGIH TLV:10MG/M3 DUST; 9192

Ingred Name: CHROMIUM (SARA III)

CAS:7440-47-3

RTECS #:GB4200000 OSHA PEL:1 MG/M3

ACGIH TLV:0.5 MG/M3; 9192

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name: MOLYBDENUM

CAS:7439-98-7

RTECS #:QA4680000

OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/M3; 9293

Ingred Name: NICKEL (SARA III)

CAS:7440-02-0

RTECS #:QR5950000 OSHA PEL:1 MG/M3

ACGIH TLV:1 MG/M3; 9192

Ingred Name: SILICON

CAS:7440-21-3

R

TECS #:VW0400000

Other REC Limits:5MG/CUM(RESP.DUST)

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Name:LEAD (SARA III)

CAS:7439-92-1

RTECS #:OF7525000

OSHA PEL:0.05 MG/M3;1910.1025 ACGIH TLV:0.15 MG/M3;DUST 9192

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:ZINC (SARA III)

CAS:7440-66-6

RTECS #:ZG8600000

OSHA PEL:10 MG ZNO/M3

ACGIH TLV:10 MG ZNO/M3; 9192

EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

=========== Hazards Identification ==========================

Routes of

Entry: Inhalation:YES Skin:YES Ingestion:YES

Reports of Carcinogenicity:NTP:YES | IARC:YES | OSHA:YES

Health Hazards Acute and Chronic: OPERATIONS SUCH AS

ABRADING, MELTING, WELDING, CUTTING OR PROCESSING IN ANY OTHER FASHION MAY PRODUCE POTENTIALLY HAZARDOUS DUST OR FUMES WHICH CAN BE INHALED, SWALLOWED OR COME IN CONTACT WITH THE SKIN OR EYES. DUST OR FUME MAY CAUSE IRRITATION TO THE EYES, NOSE OR THROAT; -CONTINUES IN SUPPLEMENTAL SAFETY & HEALTH DATA-

Explanation of Carcin

ogenicity:NICKEL IS A CARCINOGEN AND CERTAIN

COMPOUNDS OF CHROMIUM AND COBALT HAVE BEEN IDENTIFIED AS SUSPECT HUMAN CARCINOGENS.

Effects of Overexposure: SEE HEALTH HAZARDS AND MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE.

Medical Cond Aggravated by Exposure:OVEREXPOSURE SYMPTOMS MAY BE AGGRAVATED FOR SENSITIVE INDIVIDUALS WITH RESP.CONDITION (SUCH AS EMPHYSEMA). PERSON WITH LT SKIN,SENSITIVE SKIN OR LG AMTS OF BODY HAIR MAY EXPERIENCE SKIN DISORDERS.

First Aid Measures ========== First Aid:EYES:FLUSH WITH WATER.SEEK MEDICAL ATTENTION;SKIN:WASH WITH SOAP & WATER; INHALATION: REMOVE TO FRESH AIR. IF NOT BREATHING GIVE CPR.SEEK MEDICAL ATTENTION; INGESTION: SEEK MEDICAL ATTENTION. Extinguishing Media: USE EXTINGUISHING MEDIA APPROPRIATE FOR SURROUNDING FIRE. Unusual Fire/Explosion Hazard: DUST HAZARDS EXIST UNDER FAVORING CONDITIONS OF SMALL PARTICL E SIZE. DISPERSION IN AIR AND STRONG IGNITION SOURCE MAY RESULT IN AN EXPLOSION. ======== Accidental Release Measures ============ Spill Release Procedures: PICK UP AND PLACE IN APPROPRIATE DISPOSAL CONTAINER. ============ Handling and Storage =========================== Handling and Storage Precautions: NO SPECIAL PROCEDURE REQUIRED. Other Precautions: REMOVE TRACES OF MATERIAL DUST IF SOLDERING, WELDING, BRAZING, CUTTING OR OTHER PROCESS INVOLVING **IGNITION** SOURCES TO PREVENT A FIRE HAZARD. ===== Exposure Controls/Personal Protection ======== Respiratory Protection: IN CASE OF DUST CONDITIONS, USE NIOSH APPROVED RESPIRATOR FOR METAL DUST. Ventilation:LOCAL EXHAUST

Ventilation:LOCAL EXHAUST
Protective Gloves:AS REQUIRED
Eye Protection:SAFETY GLASSES

Work Hygienic Practices: STANDARD PRACTICE

Supplemental Safety and Health

HEALTH HAZARDS,CONT'D:LEAVES A METALLIC TASTE IN THE MOUTH;RESULTS IN METAL FUME FEVER (FLU-LIKE SYMPTOMS).

======= Phy

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.