View NSN Online: https://aerobasegroup.com/nsn/6850-01-263-9774

MAGNAFLUX CORPORATION -- ZL-55 ZYGLO WATER WASHABLE PENETRNT -- 6850-01-263-9774

Product ID:ZL-55 ZYGLO WATER WASHABLE PENETRNT

MSDS Date:11/13/1985

FSC:6850

NIIN:01-263-9774

MSDS Number: BGRSK === Responsible Party ===

Company Name: MAGNAFLUX CORPORATION

Address:7300 W. LAWRENCE AVENUE

City:CHICAGO

State:IL

ZIP:60656-3504 Country:US

Info Phone Num:708-867-8000

F

mergency Phone Num:708-867-8000

Preparer's Name:BRUCE C. GRAHAM, CH. CHEM

CAGE:37676

=== Contractor Identification ===

Company Name: ILLINOIS TOOL WORKS INC MAGNAFLUX DIV

Address:3624 WEST LAKE AVENUE

Box:City:GLENVIEW

State:IL ZIP:60025 Country:US

Phone:847-657-5300/

CAGE:37676

======= Composition/Information on Ingredients ========

Ingred Name: SECONDARY ETHOXYLATED FATTY ALCOHOLS

CAS:68131-40-8

RTECS #:WZ5200000 Fraction by Wt: 50.0%

Ingred Name: UNIDENTIFIED COMPONENTS

Fraction

by Wt: 50.0%
========== Hazards Identification ===========
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:IRRITATES EYES ON LIQUID/VAPOR CONTACT.
Effects of Overexposure:INHALATION:CAUSES DIZZINESS,DROWSINESS,NAUSEA; SKIN:LIQUID IRRITATES BY DISSOLVING SKIN OIL; EYES:VAPOR/LIQUID CAUSES IRRITATION; INGESTION:MANUFACTURER DIDN'T LIST. Medical Cond Aggravated by Exposure:NOT KNOWN.
======================================
res ====================================
First Aid:INHALATION:REMOVE TO FRESH AIR.IF BREATHING IS DIFFICULT,GIVE OXYGEN; SKIN:REMOVE CONTAMINATED CLOTHES.WASH OFF WITH FLOWING WATER.USE SOOTHING LOTION.IF IRRITATION PERSISTS,GET MEDICAL ATTN; EYES:IMM EDIATELY RINSE/FLUSH WITH COPIOUS AMOUNT OF RUNNING WATER,AND GET MEDICAL ATTENTION.
======================================
Flash Point Method:PMCC Flash Point:>250F/121C Extinguishing Media:CARBON DIOXIDE,FOAM.
Fire Fighting Procedures:KEEP CONTAINERS COOL WITH WATER SPRAY.DO NOT SPRAY WATER ON BURNING ZL-55. Unusual Fire/Explosion Hazard:WHEN INVOLVE IN COMBUSTION,MAY EMIT TOXIC GASES AT OR ABOVE DECOMPOSITION TEMPERATURE.
======== Accidental Release Measures ==========
Spill Release Procedures:REMOVE IGNITION SOURCES.SM QTY:WIPE UP OR MOP UP BUT DO NOT BREATHE VAPORS.PLACE RAGS IN CLOSED DRUMS; LG QTY:WEAR PERSONAL SAFETY EQUIPMENTS.DIKE AREA FAR AHEAD.ABSORB
LIQUID WITH COMMERCIAL ABSORBEN T.TRANSFER WASTE MATL IN SALVAGE TANKS.
Neutralizing Agent:NOT KNOWN.
============ Handling and Storage ==============
Handling and Storage Precautions:STORE AWAY FROM HEAT SOURCES IN WELL VENTILATED AREA.AVOID AGAINST PHYSICAL DAMAGE TO CONTAINERS.KEEP CONTAINERS TIGHTLY CLOSED.
Other Precautions:DO NOT BREATHE VAPORS.DO NOT SMOKE WHILE USING.DO NOT HEAT ABOVE 130F(54C).AVOID FREQUENT OR PROLONGED SKIN CONTACT.

= Exposure Controls/Personal Protection ========== Respiratory Protection: USE NIOSH APPROVED RESPIRATOR FOR CONFINED AREAS. Ventilation: GENERAL ROOM VENTILATION TO KEEP BELOW TLV LIMITS. Protective Gloves: USE NITRILE RUBBER GLOVES IF NEEDED. Eye Protection: FULL GOGGLES/SAFETY GLASSES W/SIDESHIELD Other Protective Equipment: NOT KNOWN. Work Hygienic Practices: WASH OFF PROMPTLY WITH WATER. AVOID SKIN CONTACT. Supplemental Safety and Health NSN OF MIL-I-25135D, TYPE I, METHOD C, LEVEL 3; PE R QPL-25135,MAGNAFLUX CORP MAY SUPPLY ONE OF THE FOLLOWING PENETRANTS FOR TYPE I, METHOD C, LEVEL 3 NSN: ZL-22D, ZL-27A, ZL-37, ZL-54A, ZL-55 OR ZL-66A; THIS ENTR Y DESCRIBES ZL-55; PRODUCT NOT AVAILABLEIN AEROSOL CANS; SEE OTHER P/N IND OF THIS NSN FOR OTHER QUALIFIED ITEMS. ======== Physical/Chemical Properties =========== HCC:N1 Boiling Pt:B.P. Text:400F/204C Vapor Pres:1.0 Spec Gravity:1.01 Evaporation Rate & Dr. Reference: NOT KNOWN Solubility in Water: NEGLIGIBLE (E MULSIFY) Appearance and Odor: GREEN OILY LIQUID. Percent Volatiles by Volume:5.0% ======== Stability and Reactivity Data =========== Stability Indicator/Materials to Avoid:YES NOT KNOWN TO MFR. Stability Condition to Avoid: HEAT, HIGH TEMPERATURES. Hazardous Decomposition Products: EMITS OXIDES OF CARBON AND NITROGEN ON COMBUSTION. ======= Disposal Considerations =========== Waste Disposal Methods: INCINERATE OR DISPOSE OF AS EPA HAZARDOUS WASTE D0

01 (IGNITABLE WASTE),IN ACCORDANCE WITH ALL APPLICABLE FEDERAL,STATE,LOCAL REGULATIONS;IF LOCAL AUTHORITIES DO NOT ALLOW DUMPING RINSINGS DOWN THE SEW ER,PURIFY RINSINGS WITH MAGNFLUX TREATMENT SYSTM

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaim

s all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.