View NSN Online: https://aerobasegroup.com/nsn/6830-00-290-4291 NATIONAL WELDERS SUPPLY CO INC -- ARGON -- 6830-00-290-4291 Product ID:ARGON MSDS Date:11/20/1988 FSC:6830 NIIN:00-290-4291 MSDS Number: BHDJC === Responsible Party === Company Name: NATIONAL WELDERS SUPPLY CO INC Address:810 GESCO Box:31007 City:CHARLOTTE State:NC ZIP:28231 Country:US Info Phone Num:704-333-5475(X308)/FAX 344-1711 Emergency Phone Num:800-866-442 2/800-424-9300(CHEMTREC) CAGE:18264 === Contractor Identification === Company Name: NATIONAL WELDERS SUPPLY CO INC Address:810 GESCO ST Box:31007 City:CHARLOTTE State:NC ZIP:28231 Country:US Phone:704-333-5475 CAGE:18264 ======= Composition/Information on Ingredients ========

Ingred Name:ARGON CAS:7440-37-1

========= Hazards Identification ===========

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:N

Health Hazards Acute and Chronic:ARGON IS NONTOXIC BUT THE LIBERATION OF A LARGE AMOUNT IN A CONFINED AREA COULD DISPLACE THE AMOUNT OF OXYGEN IN AIR NECESSARY TO SUPPORT LIFE. IT SHOULD ALSO BE RECOGNIZED THAT IT IS POSSIBLE THAT N ONE OF THE SYMPTOMS MAY OCCUR IN ARGONASPHYXIA SO THAT THERE ARE NO DEFINITE WARNING SYMPTOMS.

Effects of Overexposure:ANY, ALL, OR NONE OF THE ABOVE COULD OCCUR RESULTING FROM ARGON DISPLACED OXYGENSYMPTOMS: DIZZINESS; FOREHEAD TIGHTNESS:

TINGLING OF TONGUE, FINGERTIPS, & TOES;WEAKENED
SPEECH;RAPID REDUCTION IN ABILI TY TO PERFORM MOVEMENTS;REDUCED
CONSCIOUNESS OF THE SURROUNDINGS; LOSS OF TACTILE SENSATIONS;
HEIGHTENED MENTAL ACTIVITY

First Aid:PROMPT MEDICAL ATTENTION IS MANDATORY IN ALL CASES OF OVEREXPOSURE TO ARGON. RESCUERS SHOULD BE EQUIPPED WITH SELF-CONTAINED BREATHING APPARATUS. CONSCIOUS PERSONS SHOULD BE ASSISTED TO AN U

NCONTA MINATED AREA & INHALE FRESH AIR.


QUICKREMOVAL FROM THE CONTAMINATED AREA IS MOST IMPORTANT.

UNCONSCIOUS PERSONS SHOULDBE MOVED TO AN UNCONTAMINATED AREA, GIVEN CPR, AND SUPPLEMENTAL OXYGEN.

======================================
Extinguishing Media:NONFLAMMABBLE, INERT GAS
======== Accidental Release Measures =========
Spill Release Procedures:EVACUATE ALL PERSONNEL FROM AFFECTED AREA. USE APPROPRIATE PROTECTIVE EQU IPMENT. IF LEAK IS IN CONTAINER OR CONTAINER VALVE, CONTACT CLOSEST SUNOX LOCATION.
======================================

Handling and Storage Precautions:USE/STORE IN COOL,DRY,WELL-VENTILATED AREA.PROTECTCYLINDERS FROM PHYS. DAMAGE. CYL. SHOULD BE STOREDSECURELY & UPRIGHT.SEGREGATE FULL/EMPTY CYLINDERS.

Other Precautions:KEEP CYLINDERS AWAY FROM ALL SOURCES OF HEAT.ARGON IS HEAVIER THAN AIR & LEAKINGGAS COULD ACCUMULATE IN LOW AREAS AND CAU



TEMP OF -188F/-122C

======== Disposal Considerations =============

Waste Disposal Methods:DO NOT ATTEMPT TO DISPOSE OF RESIDUAL OR UNUSED QUANTITIES. RTN IN THE SHIPPING CONTAINER PROPERLYLABELED, WITH ANY VALVE OUTLET PLUGS OR CAPS SECUREAND VALVE PROTECTION CAP IN PLACE, TO SUNOX

FOR PROPER DISPOSAL.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.