View NSN Online: https://aerobasegroup.com/nsn/8010-00-664-9077

NELSON TECHNICAL COATINGS INC -- PAINT READY MIXED -- 8010-00-664-9077

Product ID: PAINT READY MIXED MSDS Date:01/01/1987 FSC:8010 NIIN:00-664-9077 MSDS Number: BHDSV === Responsible Party === Company Name: NELSON TECHNICAL COATINGS INC Address:2147 N TYLER AVE City:SOUTH EL MONTE State:CA ZIP:91733-2754 Country:US Info Phone Num:213-575-3333 **Emergency Phone Num:2** 13-575-3333 CAGE:60800 === Contractor Identification === Company Name: NELSON TECHNICAL COATINGS INC Address:2147 N TYLER AVE Box:City:SOUTH EL MONTE State:CA ZIP:91733-2754 Country:US CAGE:60800

Ingred Name:TOLUENE (SARA III) CAS:108-88-3 RTECS #:XS5250000 Fraction by Wt: 14% OSHA PEL:200 PPM/150 STEL ACGIH TLV:50 PPM; 9293 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:NAPHTHA (PETROLEUM SPIRITS OR BENZIN) CAS:8030-

30-6 RTECS #:SE7555000 Fraction by Wt: 49% OSHA PEL:100 PPM

Ingred Name:XYLENES (O-,M-,P- ISOMERS) (SARA III) CAS:1330-20-7 RTECS #:ZE2100000 Fraction by Wt: 5% OSHA PEL:100 PPM/150 STEL ACGIH TLV:100 PPM/150STEL;9192 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

======

First Aid:FUMES: REMOVE TO FRESH AIR. RESTORE BREATHING KEEP WARM & QUIET. CALL PHYSICIAN.SPLASH EYE: FLUSH WITH LARGE QUANTITIES OF RUNNING WATER FOR 15 MIN. SEEK MEDICAL HELP. SKIN: WASH WELL WITH RUNNING WAT ER. REMOVE CONTAMINATED CLOTHING. CONSULT A PHYSICIAN.

Flash Point Method:SCC Flash Point:86F/30.00C Lower Limits:1.2 Upper Limits:1.0 Extinguishing Media:NFP CLASS B, EXTINGUISHERS,CO21, DRY CHEMI CAL, OR FOAM DESIGNED TO EXTINGUISH NFPA CL I LIQUID FIRES Fire Fighting Procedures:WTR SPRAY MAY BE INEFFECT, WTR MAY BE USED TO COOL CONTAINER TO PREVENT PRESSUREBUILD UP & POSSIBLE EXPLOSION WHEN EXPOSED TO EXTREME HEAT. USE FOG NOZZLES Unusual Fire/Explosion Hazard:PRESSURE MAY BUILD UP WHEN CLOSED CONTAINER IS EXPOSED TO HEAT. DO NOT APPLY TO HOT SURFACE. PAINT VAPORS MAY CAUSE VIOLENT EXPLOSION. USE EXPLOSION PROOF EQUIP

========= Accidental Release Meas

Spill Release Procedures:REMOVE SOURCES OF IGNITION (FLAMES, HOT SURFACES, ELECTRICAL OR STATIC, OR FRICTIONAL SPARKS). AVOIDBREATHING VAPORS. VENTILATE AREA. REMOVE WITH INERT ABSORBENT AND NON-SPARKING TOOLS

Handling and Storage Precautions:DO NOT STORE OVER 120 F. STORE LARGE QUANITITES INBLDS DESIGNED & PROTECTED FOR STORAGE OF NFPA CLASS I FLAMMABLE LIQUIDS Other Precautions:D O NOT TAKE INTERNALLY

======= Exposure Controls/Personal Protection ==========

Respiratory Protection:BUREAU OF MINES APPROVED CHEMICAL-MECHANICAL FILTERS TO REMOVE PARTICALS, GAS, AND VAPOR Ventilation:LOCAL-TO KEEP TLV/LEL OF MOST HAZARDOUS INGREDIENTS BELOW ACCEPTABLE LIMIT Protective Gloves:REQUIRED FOR PROLONGED/REPEATED CONTACT Eye Protection:GOGGLES OR FACE SHIELDS Other Protective Equipment:IN CONFINED AREAS USE BUREAU OF MINES APPROVED AIRLINE TYPE RESPIRATORS O R HOODS Supplemental Safety and Health NK

HCC:N1 Boiling Pt:B.P. Text:232-308 F Vapor Density:> AIR Spec Gravity:1.128 Evaporation Rate & amp; Reference:SLOWER THAN ETHER Percent Volatiles by Volume:70

Stability Indicator/Materials to Avoid:YES WATER Stability Condition to Avoid:FLAME AND HIGH HEAT Hazardous Decomposition Products:NORMALLY CARBON COMBUSTION

PRODUCTS

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE, & FED-ERAL REG. INCINERATE IN APPROVED FACILITY. DO NOT INCINERATE CLOSED CONTAINERS

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information t o be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and

assume responsibility for the suitability of this information to their particular situation.