View NSN Online: https://aerobasegroup.com/nsn/8030-00-251-3980

JET-LUBE INC. -- KOPR-KOTE (R) LEAD FREE -- 8030-00-251-3980

Product ID:KOPR-KOTE (R) LEAD FREE

MSDS Date:07/10/1991

FSC:8030

NIIN:00-251-3980

MSDS Number: BHQHV
=== Responsible Party ===
Company Name:JET-LUBE INC.
Address:4849 HOMESTEAD ROAD

Box:21258 City:HOUSTON

State:TX ZIP:77226 Country:US

Info Phone Num:713-674-7617

Emergency Phone Num:713-674-7617

Prepare

r's Name: DONALD A. OLDIGES

CAGE:JO923

=== Contractor Identification === Company Name:JET-LUBE INC Address:4849 HOMESTEAD RD

Box:21258 City:HOUSTON

State:TX ZIP:77026 Country:US

Phone:713-674-7617

CAGE:07431

Company Name: JET-LUBE INC. Address: 4849 HOMESTEAD ROAD

Box:21258 City:HOUSTON

State:TX ZIP:77226 Country:US

Phone:713-674-7617

CAGE:JO923

======= Composition/Information on Ingredients ========

Ingred Name:PETROLEUM OIL

CAS:64741-96-4

Fraction by Wt: 70% MAX Other REC Limits:NO

Ingred Name: COPPER POWDER CAS:7440-50-8 Fraction by Wt: 12% MAX Other REC Limits: NONE SPECIFIED ACGIH TLV:1 MG/M3 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS Routes of Entry: Inhalation:NO Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Effects of Overexposure: REDNESS AND IRRITATION OF SKIN. REPEATED SKIN CONTACT FOR PERSONS HYPERSENSITIVE TO PETROLEUM PRODUCTS CAN CAUSE REDNESS AND IRRITATION OF SKIN. First Aid:INHALATION- CLEAR AIR PASSAGE, CALL PHYSICIAN. INGESTION- IF INGESTED, CALL PHYSICIAN. EYES- WASH WITH COPIOUS QUANTITIES OF WATER. SKIN- REMOVE BY WIPING, OR WATERLESS HAND CLEANER, FOLLOWED BY WASHING. ============ Fire Fighting Measures ========================= Flash Point Method:COC Flash Point:465F,241C Autoignition Temp:Autoignition Temp Text:500F Extinguishing Media: USE FOAM, DRY CHEMICAL, WATER SPRAY (FOG), CARBON DIOXIDE OR VAPORIZING LIQUID TYPE EXTINGUISHING AGENTS. Fire Fighting Procedures: USE SUPPLIED-AIR BREATHING EQUIPMENT FOR ENCLOSED OR CONFINED SPACES. ======== Accidental Release Measures ============ Spill Release Procedures: SCOOP UP EXCESS, WIPE UP WITH RAGS, PICK-UP RESIDUE WITH DIATOMACEOUS EARTH TO AVOID WALKING HAZARD. ======== Handling and Storage =======

NE SPECIFIED

OSHA PEL:OIL MIST TWA-5 MG/M3

HCC:T6
Boiling Pt:B.P. Text:624F,329C
Vapor Pres:5
Spec Gravity:1.14
Evaporation Rate & Description Reference: