View NSN Online: https://aerobasegroup.com/nsn/3439-01-094-3337

## MARCO CO -- MARCOLOY 1408 BRAZING ALLOY -- 3439-01-094-3337

=========== Product Identification =============

Product ID:MARCOLOY 1408 BRAZING ALLOY

MSDS Date:06/01/1990

FSC:3439

NIIN:01-094-3337

MSDS Number: BHXZP === Responsible Party === Company Name: MARCO CO

Address:5722 UNION PACIFIC AVENUE

City:LOS ANGELES

State:CA

ZIP:90022-5135 Country:US

Info Phone Num:213-723-0711

Emergency Phone Num:213-723-0711

Pren

arer's Name:PAT HOUDESHELL

CAGE:55278

=== Contractor Identification === Company Name:MARCO CO

Address:5722 UNION PACIFIC AVENUE

Box:City:LOS ANGELES

State:CA

ZIP:90022-5135 Country:US

Phone:213-723-0711

CAGE:55278

======= Composition/Information on Ingredients ========

Ingred Name: COPPER (SARA III)

CAS:7440-50-8

RTECS #:GL5325000

Other REC Limits:NONE SPECIFIED OSHA PEL:0.1MG/M3 FUME/1 DUST ACGIH TLV:0.2MG/M3 FUME; 9192

EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:SILVE

R (SARA III) CAS:7440-22-4 RTECS #:VW3500000 Other REC Limits:NONE SPECIFIED OSHA PEL:0.01 MG/M3

ACGIH TLV:0.1 MG/M3; 9192

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:PHOSPHOROUS (YELLOW) (SARA III)

CAS:7723-14-0

RTECS #:TH3500000

Other REC Limits: NONE SPECIFIED

OSHA PEL:0.1 MG/M3

ACGIH TLV:0.1 MG/M3; 9192

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

========== Hazards Identification ===============

LD50 LC50 Mixture: NOT SPECIFIED BY MANUFACTURER.

Routes of Entry: Inhalation:YES

Skin:YES Ingestion:NO

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:SHORT TERM EXPOSURE TO WELDING FUMES, GASES OR DUST MAY RESULT IN DISCOMFORT SUCH AS DIZZINESS, NAUSEA, FEVER, DRYNESS AND/OR IRRITATION OF NOSE, THROAT, AND EYES, TIGHTNESS IN CHEST, ALLERGIC REACTIO NS. LONG-TERM OVEREXPOSURE TO WELDING FUMES MAY LEAD TO SIDEROSIS (IRON DEPOSIT IN LUNGS).

Explanation of Carcinogenicity:PRODUCT CONTAINS NO INGREDIENTS CURRENTLY CLASSI

FIED AS CARCINOGENIC BY NTP, IARC OR OSHA.

Effects of Overexposure:DIZZINESS, NAUSEA, FEVER, DRYNESS AND/OR IRRITATION OF NOSE, THROAT OR EYES, TIGHTNESS IN CHEST, FEVER, ALLERGIC REACTIONS, IRON DEPOSITS IN LUNGS, PULMONARY DISFUNCTION. Medical Cond Aggravated by Exposure:SOME WORKERS MAY BE AFFECTED BY A PRE-EXISTING CONDITIONAL OR OTHER OCCUPATIONAL ILLNESS BECAUSE OF THE WIDE VARIATION IN INDIVIDUAL SUSCEPTIBILITIES.

========= First Aid Measures ==========

	_				

First Aid:IN CASEE OF ELECTRICAL SHOCK, TURN OFF POWER PRIOR TO REMOVAL FROM EXPOSURE AREA AND ADMINISTER FIRST AID. REMOVE FROM EXPOSED AREA AND CALL FOR MEDICAL AID. ADMINISTER OXYGEN IF BREATHING IS DIFFICUL T. IF NOT BREATHING, BEGIN ARTIFICIAL RESPIRATION. IF NO DETECTABLE PULSE, BEGIN EXTERNAL HEART MASSAGE. EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY THE AMERICAN RED CROSS.

=========== Fire Fighting Measures ==========================

Flash Point:NO NFLAMMABLE

Autoignition Temp: Autoignition Temp Text: NONE

Lower Limits: NOT GIVEN Upper Limits: NOT GIVEN

Extinguishing Media: NONFLAMMABLE. USE MEDIA SUITABLE FOR SURROUNDING FIRE.

Fire Fighting Procedures: NONFLAMMBLE. USE PROCEDURES SUITABLE FOR SURROUNDING PROCEDURES.

Unusual Fire/Explosion Hazard:WELDING ARC AND SPARKS CAN IGNITE COMBUSTIBLES AND FLAMMABLES. REFER TO AMERICAN NATIONAL STANDARD Z49.1 FOR FIRE PREVENTION DURING WELDING PROCEDURES.

=======================================	== Accidental Re
lease Measures ====	

Spill Release Procedures:CLEAN UP ANY GRINDING DUST OR WASTE RESIDUES AND PLACE IN SUITABLE DOT CONTAINER AND DISPOSE OF IN FULL COMPLIANCE WITH FEDERAL, STATE AND LOCAL REGULATIONS. AVOID INHALATION AND SKIN EXPOSURE.

Neutralizing Agent: NONE SPECIFIED BY MANUFACTURER.

============= Handling and Storage ==========================

Handling and Storage Precautions:WEAR GLOVES AND FLAME RETARDANT CLOTHING WHEN CUTTING, GRINDING OR WELDING.

DO NOT EXPOSE SKIN TO

RADIATION WHEN HOT CUTTING OR WELDING.

Other Precautions:PROVIDE PROTECTIVE SCREENS TO SHIELD OTHERS. WHEN ELECTRODES AND FLUXES ARE CONSUMED, THE FUME AND GAS DECOMPOSITION PRODUCTS GENERATED ARE DIFFERENT IN FORM FROM THE INGREDIENTS LISTED. NEW COMPOUNDS NOT IN THE ELECTRODE MAY FORM.

====== Exposure Controls/Personal Protection ========

Respiratory Protection: USE WELD FUME RESPIRATOR OR AIR SUPPLIED RESPIRATOR WHEN CUTTING, GRINDING

OR WELDING IN A CONFINED SPACE OR

WHERE LOCAL EXHAUST OR GENERAL VENTILATION DOES NOT KEEP EXPOSURE BELOW RECOMMENDED LIMITS. USE ONLY NIOSH APPROVED RESPIRATORS.

Ventilation: USE ENOUGH VENTILATION WHEN CUTTING, GRINDING OR WELDING TO KEEP DUST, FUMES & GASES FROM THE WORKERS BREATHING ZONE.

Protective Gloves: WELDERS LEATHER GLOVES

Eye Protection: OSHA APPROVED GOGGLES/FACE SHIELD W/LENS

Other Protective Equipment: FLAME RETARDANT CLOTHING WHEN CUTTING,

GRINDING OR WELDING. DO NO

T EXPOSE SKIN TO RADIATION WHEN HOT

CUTTING OR WELDING.

Work Hygienic Practices:WASH WITH SOAP AND WATER AFTER HANDLING PRODUCT AND BEFORE EATING DRINKING OR SMOKING.

Supplemental Safety and Health

PRODUCT IS NONHAZARDOUS AS STORED AND SHIPPED. HAZARD OCCURS WHEN ROD IS USED IN WELDING AND HOT CUTTING OPERATIONS. THESE FUMES AND GASES CANNOT BE CLASSIFIED SIMPLY. THEIR COMPOSITION AND QUANTITY A RE DEPENDENT ON THE METAL BEING WELDED.

=======================================	Physical/Chemical Pr
operties =======	=====
1100 114	
HCC:N1	
Boiling Pt:B.P. Text:NOT	GIVEN
Melt/Freeze Pt:M.P/F.P	Γext:NOT GIVEN

Vapor Pres:0 Vapor Density:NOT GIVEN

Spec Gravity:NOT GIVEN

Evaporation Rate & Dry Reference: NIL

Solubility in Water: NEGLIGIBLE

Appearance and Odor:18 INCH LONG COPPER BRAZING ROD

Percent Volatiles by Volume:0

	Stability and Reactivity Data	=======================================
--	-------------------------------	---

Stability Indicator/Materials to Avoid:YES
NONE SPECIFIED BY MANUFACTURER.
Stability Condition to Avoid:AVOID OVER
HEATING TO AVOID GENERATION OF
HAZARDOUS DECOMPOSTION PRODUCTS.

Hazardous Decomposition Products:PHOSPHOROUS OXIDE VAPORS WHILE BRAZING, CARBON MONOXIDE, CARBON DIOXIDE, OZONE, NITROGEN OXIDES.

====== Disposal	Considerations	
-----------------	----------------	--

Waste Disposal Methods:PREVENT WASTE FROM CONTAMINATING SURROUNDING ENVIRONMENT. DISCARD ANY PRODUCT, RESIDUE, DISPOSAL CONTAINER OR LINER IN ACCORDANCE WITH ALL FEDERAL, STATE AND LOCAL REGULATIONS.

Disclaimer (provid

ed with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.