Address:100 MORSE STREET

City:NORWOOD

State:MA ZIP:02062

Info Phone Num:(617) 762-5300

Emergency Phone Nu m:(617) 762-5300 CAGE:88932

=== Contractor Identification ===

Company Name: ELECTRONIC SYS GP/NORTHROP PRECS. DIV

Company Name: ELECTRONIC SYS GP/NORTHROP PRECS. DIV

Address:100 MORSE STREET

Box:City:NORWOOD

State:MA ZIP:02062

Phone: (617) 762-5300

CAGE:88932

======= Composition/Information on Ingredients ========

Ingred Name:BERYLLIUM (SARA III)

CAS:7440-41-7

RTECS #:DS1750000 Fraction by Wt: 100% OSHA PEL:2 UG/M3

ACGIH TLV:0.002PPM; A2; 9293

========== Hazards Identification ==============

Routes of Entry: In

halation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:INHALATION: PNEUMONITUS, PULMONARY EDEMA, LIVER DAMAGE, SPLEEN & HEART, LESIONS, COUGH, CHEST PAIN, SHORTNESS OF BREATH, WEAKNESS, CHILLS, FEVER, & LUNG DISEASE. Explanation of Carcinogenicity:NONE Effects of Overexposure:INHALATION: PHENUMONITUS, PULMONARY EDEMA, LIVER DAMAGE, SPLEEN & HEART, LESIONS, COUGH, CHEST PAIN, SHORTNESS OF BREATH, WEAKNESS, CHILLS, LUNG DISEASES. Medical Cond Aggravated by Exposure:LUNG DISEASE
======================================
======================================
First Aid:INHALATION: REMOVE TO FRESH AIR, RESTORE BREATHING, GET MED ATT. EYES: FLUSH W/RUNNING WATER FOR 15 MINS, INCLUDING UNDER EYELIDS, SEEK MED ATT. SKIN: WASH W/SOAP & WATER. SEEK MEDICAL ATTENTION. INGE STION: NOT CONSIDERED A HAZARD BECAUSE ABSORPTION IS SO LOW.
======================================
Exting uishing Media:DRY POWDER EXTINGUISHER, SAND OR SALT. DON'T USE WATER OR CO2 Fire Fighting Procedures:WEAR SELF-CONTAINED BREATHING APPARATUS & FULL PROTECTIVE CLOTHING. Unusual Fire/Explosion Hazard:A CLOUD OF BERYLLIUM DUST IN AIR CAN BE EXPLOSIVE.
======== Accidental Release Measures ==========
Spill Release Procedures:EVACUATE/ENCLOSE AREA. CLEAN WHILE USING RESPIRATORS/PROTECTIVE CLOTHING.
======================================
Handling and Storage Precautions:WASH HANDS & ARMS BEFORE LEAVING. NO EATING, DRINKING OR SMOKING IN CONTROLLED AREA. KEEP IN DRY AREA FROM CHEMICALS. DON'T PRODUCE DUST.  Other Precautions:BERYLLIUM FABRICATION OPERATIONS MUST BE DONE IN A CONTROLLED BERYLLIUM AREA.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:FULL FACE HEPA RESPIRATOR >10 UG/CUM, SCBA >50 UG/CUM.

Ventilation:LOCAL EXHAUST: W/HEPA FILTRATION. MECHANICAL: ROOM

MUST HAVE NEGATIVE PRESSURE. Protective Gloves: AS REQUIRED Eye Protection: MANDATORY Other Protective Equipment: PROTECTIVE CLOTHING, COATS, GARMENTS.
Work Hygienic Practices:WASH HANDS/ARMS BEFORE LEAVING. NO EATING, DRINKING OR SMOKING IN CONTROLLED AREA.
Supplemental Safety and Health
======================================
Boiling Pt:B.P. Text:2970C
Melt/Freeze Pt:M.P/F.P Text:1280C
Vapor Pres:7.6 Spec Gravity:1.85
Solubility in Water:INSOLUBLE
Appearance
and Odor:GRAY METAL; NO ODOR.
======== Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES
PHOSPHOROUS, FLUORINE, CHLORINE, MOLTEN LITHIUM, FREON/METHANOL MIXTURES.
Stability Condition to Avoid: ACIDS, BASES, CHLORINATED HYDROCARBONS.  Hazardous Decomposition Products: OXIDES OF REBYLLIUM

========= Disposal Considerations ===========================

Waste Disposal Methods: DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE, AND FEDERAL REG ULATIONS. POISON LABEL REQUIRED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this inform

ation to their particular situation.