Product ID:MOLYKOTE(R) 44 GREASE-ALL GRADES MSDS Date:01/19/1981 FSC:9150 NIIN:01-014-3512 Kit Part:Y MSDS Number: BJMGT === Responsible Party === Company Name: DOW CORNING CORP Address:3901 SOUTH SAGINAW ROAD Box:997 City:MIDLAND State:MI ZIP:48640 Country:US Info Phone Num:517-496-5900 Eme rgency Phone Num:517-496-5900 Preparer's Name:L.C. VANVOLKINBURG CAGE:5D028 === Contractor Identification === Company Name: DOW CORNING CORP Address:3901 S SAGINAW RD Box:997 City:MIDLAND State:MI ZIP:48686-0997 Country:US Phone:517-496-6000/517-496-6315 CAGE:5D028 Company Name: DOW CORNING CORP Address:2200 W SALZBURG RD Box:City:AUBURN State:MI ZIP:48611 Country:US Phone:517-496-4388 CAGE:71984

Ingred Name:NOT HAZARDOUS INGRE

DIENTS Fraction by Wt: 100% Other REC Limits:NONE SPECIFIED

LD50 LC50 Mixture:LD50 (ORAL RAT) IS NOT AVAILABLE Routes of Entry: Inhalation:NO Skin:YES Ingestion:NO Health Hazards Acute and Chronic: ACUTE-EYES: MAY CAUSE TEMPORARY DISCOMFORT.CHRONIC-NONE SPECIFIED BY MANUFACTURER. Explanation of Carcinogenicity:NONE SPECIFIED BY MANUFACTURER. Effects of Overexposure: MAY CAUSE TEMPORARY DISCOMFORT TO EYES. Medical Cond Aggra vated by Exposure:NONE SPECIFIED BY MANUFACTURER. First Aid: EYES: FLUSH WITH WATER FOR AT LEAST 15 MINUTES. IF IRRITATION PERSISTS, CALL A PHYSICIAN. Flash Point Method:OC Flash Point:>250F,>121C Extinguishing Media:CARBON DIOXIDE OR FOAM Fire Fighting Procedures: FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE. Unusual Fire/Explosion Hazard:NONE KNOWN TO DOW CORNING. Spill Release Procedures: SCOOP UP EXCESS GREASE. USE ABSORBENT MATERIAL TO COLLECT THE REST AND CONTAIN FOR SALVAGE OR DISPOSAL. Neutralizing Agent:NONE SPECIFIED BY MANUFACTURER. 

Handling and Storage Precautions:STORE IN

A COOL, DRY PLACE WITH ADEQUATE VENTILATION. KEEP CONTAINERS TIGHTLY CLOSED WHEN NOT IN USE. KEEP AWAY FROM OPEN FLAMES & HIGH TEMPERATURES. Other Precautions: MINIMIZE SKIN CONTACT. WASH WITH SOAP & WATER BEFORE EATING, DRINKING, SMOKING OR USING TOILET FACILITIES. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. PROPERLY DISPOSE OF CONTAMINATED LEATHER ARTICLES (SHOES) THAT CAN NOT BE DECONTAMINATED.

======= Exposure Controls/Personal Protection ==========

Resp

iratory Protection:RESPIRATORY PROTECTION NOT ORDINARILY REQUIRED. Ventilation:MECHANICAL

Protective Gloves: NEOPRENE RUBBER AS REQUIRED.

Eye Protection: SAFETY GLASSES RECOMMENDED.

Other Protective Equipment: EYE WASH STATION AND SAFETY SHOWER.

INDUSTRIAL-TYPE WORK CLOTHING AND APRON AS REQUIRED.

Work Hygienic Practices:OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES. DO NOT WEAR CONTAMINATED CLOTHING OR FOOTWEAR.

Supplemental Safety and Health

KIT CONSISTS OF PART N

OS. 39479-P8,39479-P9,39479-P15, AND

39479-P16.ACTION INITIATED TO CANCEL SUBJECT NSN. NO FURTHER BUYS SHOULD BE MADE.MANUFACTURER HAS DISCONTINUED MARKETING ITEMS AS A KIT.

HCC:V6 Boiling Pt:B.P. Text:>300F,>149C Vapor Pres: