View NSN Online: https://aerobasegroup.com/nsn/9150-01-131-3325

Product ID: EMERY 2863 MIL-H-83282 HYDRAULIC FLUID MSDS Date:02/22/1989 FSC:9150 NIIN:01-131-3325 MSDS Number: BJNZF === Responsible Party === Company Name: HENKEL CORPORATION EMERY GROUP Address:4900 ESTE AVENUE City:CINCINNATI State:OH ZIP:45232 Country:US Info Phone Num :513-482-2297 Emergency Phone Num:513-482-2297 Preparer's Name: ROBERT E.BORGERDING CAGE:0JS01 === Contractor Identification === Company Name: COGNIS CORP Address:5051 ESTECREEK DR Box:City:CINCINNATI State:OH ZIP:45232 Country:US Phone:513-482-2814; 800-543-7370 CAGE:0JS01

Ingred Name:PROPRIETARY MIXTURE Fraction by Wt: 100.0% Other REC Limits:NONE SPECIFIED

LD50 LC50 Mixture:LD50 (ORAL RAT) IS 5 G/KG Routes of Entry: Inhalation:UNKNOWN Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:ACUTE:PER MSDS NOT TOXIC BY INHALATION ,INGESTION OR SKIN CONTACT.MAY CAUSE IRRITATION OF EYES,SKIN,RESPIRATORY OR G.I.TRACTS. Explanation of Carcinogenicity:DATA PER MSDS Effects of Overexposure:SEE HEALTH HAZARDS DATA. Medical Cond Aggravated by Exposure:NOT EXPECTED IF USED UNDER THE CONDITI

ONS ADVISED BY THE MFR.

First Aid:INHALATION:REMOVE TO FRESH AIR. RESUSCITATE IF NOT BREATHING. GET MEDICAL ATTENTION. EYES:IMMEDIATELY FLUSH WITH PLENTY OF WATER FOR 15 MINUTES HOLDING EYELIDS OPEN. GET MEDICAL ATTENTION. SKIN:REMOVE CONTAMINATED CLOTHING. WASH WITH SOAP AND WATER. IF IRRITATION PERSISTS, GET MEDICAL ADVICE. INGESTION:DO NOT INDUCE VOMITING. GIVE NOTHING BY MOUTH IF UNCONSCIOUS. GET IMM EDIATE

MEDICAL ATTENTION.

Flash Point Method:COC

Flash Point:400F,204C

Extinguishing Media:USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY CHEMICAL.

Fire Fighting Procedures:FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE. Unusual Fire/Explosion Hazard:FIRE OR EXCESSIVE HEAT MAY CAUSE PRODUCTION OF H

AZARDOUS DECOMPOSITION PRODUCTS.

Spill Release Procedures:USE PROPER PERSONAL PROTECTION;CONTAIN FREE MATERIAL IF POSSIBLE;USE SUITABLE INERT ABSORBENT MATERIAL AND RECOVER FOR PROPER DISPOSAL IN AN APPROVED CONTAINER. Neutralizing Agent:NOT APPLICABLE.

Handling and Storage Precautions:STORE IN A COOL, DRY, WELL VENTILATED AREA. KEEP CONTAINERS T IGHTLY CLOSED WHEN NOT IN USE. PROTECT CONTAINERS FROM PHYSICAL DAMAGE. Other Precautions: DO NOT TAKE INTERNALLY. DO NOT BREATHE MIST. AVOID PROLONGED OR REPEATED BREATHING OF VAPOR. AVOID CONTACT WITH EYES. USE WITH ADEQUATE VENTILATION. WASH THOROUGHLY AFTER HANDLING. Respiratory Protection: USE NIOSH/MSHA APPROVED RESPIRATOR AS REQUIRED IF ABOVE PEL/TLV OR SCBA IN AN ENCLOSED AREA. Ventilation:LOCAL/GENERAL T O MAINTAIN PEL/TLV. Protective Gloves: NEOPRENE, NITRILE, OR NATURAL RUBBER Eye Protection: SAFETY GOGGLES WITH OPTIONAL FACE SHIELD Other Protective Equipment: EYE WASH STATION AND SAFETY SHOWER, WORK CLOTHING AND APRON AS REQUIRED. Work Hygienic Practices: OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES. DO NOT WEAR CONTAMINATED CLOTHING OR FOOTWEAR. Supplemental Safety and Health

AVOID PROLONGED OR REPEATED EXPOSURE. DO NOT GET ON SKIN OR IN EYES. DO NOT BREATHE

VAPORS OR MISTS.

HCC:V6 Melt/Freeze Pt:M.P/F.P Text:-76F,-60C Vapor Pres: