View NSN Online: https://aerobasegroup.com/nsn/8040-00-463-7042

DEXTER HYSOL AEROSPACE INC DIV OF EXTER CORP -- EA 956 PART A -- 8040-00-463-7042

Product ID:EA 956 PART A MSDS Date:04/10/1990

FSC:8040

NIIN:00-463-7042

Kit Part:Y

MSDS Number: BLLVL === Responsible Party ===

Company Name: DEXTER HYSOL AEROSPACE INC DIV OF EXTER CORP

Address:2850 WILLOW PASS ROAD

Box:312

City:PITTSBURG

State:CA

ZIP:94565-3237 Country:US Info Pho

ne Num:510-458-8000

Emergency Phone Num:510-458-8000 Preparer's Name:SUZANNE FRANZ

CAGE:33564

=== Contractor Identification ===

Company Name: DEXTER CORPORATION ADHESIVE & COATING SYSTEMS

Address:2850 WILLOW PASS ROAD

Box:312

City:BAY POINT

State:CA

ZIP:94565-3299 Country:US

Phone:202-483-7616

CAGE:33564

======= Composition/Information on Ingredients ========

Ingred Name: EPOXY RESIN SYSTEM

Fraction by Wt: NA

Other REC Limits: NONE SPECIFIED

Ingred Name:4-GLYCIDYLOXY-N,N-DIGLYCIDYLA


NILINE CAS:5026-74-4 Fraction by Wt: < 65% Other REC Limits: NONE SPECIFIED Ingred Name: VOC: < 10 G/L RTECS #:9999999VO Other REC Limits: NONE SPECIFIED ============== Hazards Identification ======================= Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: MAY CAUSE SKIN IRRITATION AND POSSIBLE ALLERGIC REACTIONS. PROLONGED AND REPEATED CONTACT MAY CAUSE SENSITIZATION WHICH WILL R ESULT IN ALLERGIC REACTIONS. Effects of Overexposure: SKIN RASH, IRRITATION. First Aid:FLUSH SKIN AND EYE CONTACT WITH PLENTY OF WATER. WASH SKIN THOROUGHLY WITH SOAP AND WATER, RUBBING ALCOHOL OR HAND CLEANER. DO NOT USE SOLVENTS. REMOVE SOILED CLOTHING AND WASH BEFORE REUSE. IF IRRITA TION PERSISTS, SEE PHYSICIAN. Flash Point Method:TOC Flash Point:>300F,>149C Extinguishing Media: DRY CHEMICAL OR HALON FIRE EXTINGUISHER OR WATER SPRAY, FOAM OR FOG. Fire Fighting Procedures: USE SELF-CONTAINED BREATHING APPARATUS WHEN

FIGHTING FIRES IN CONFINED AREAS.

Unusual Fire/Explosion Hazard: DENSE SMOKE AND TOXIC GASES MAY BE LIBERATED.

----- Accidental Release Measures -----

Spill Release Procedures: WEAR PROTECTIVE CLOTHING, GLOVES AND SAFETY GLASSES. SCRAPE UP AND TRANSFER TO METAL CONTAINER. WIPE UP



BATCHES GREATER THAN 1 LB TOTAL. DO NOT HEAT MIXED ADHESIVE ABOVE 100F UNLESS CURING

======= Disposal Considerations ===========

Waste Disposal Methods:DISPOSE OF AS HAZARDOUS WASTE ACCORDING TO FEDERAL, STATE AND LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or imp

lied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.