

TBA INDUSTRIAL PRODUCTS LTD -- TBA 410 -- 5330-00-299-1163

===== Product Identification =====

Product ID:TBA 410
MSDS Date:01/01/1991
FSC:5330
NIIN:00-299-1163
MSDS Number: BMSMG
=== Responsible Party ===
Company Name:TBA INDUSTRIAL PRODUCTS LTD
Address:SEALING MATERIALS DIV
Box:40
City:ROCHDALE LANCS
Country:EN
Info Phone Num:800-527-1935
Emergency Phone Num:800-527-1935
CAGE:U1309
=== Contracto
r Identification ===
Company Name:R-WAY GASKET AND SUPPLY CO
Address:1950 E SEDGLEY AVE
Box:City:PHILADELPHIA
State:PA
ZIP:19124-5622
Country:US
Phone:215-697-6350/215-743-1650
CAGE:5S153
Company Name:TBA INDUSTRIAL PRODUCTS
Box:21
City:ROCHDALE,LANCS,ENGLAND
Country:EN
Phone:800-527-1935
CAGE:U1309

===== Composition/Information on Ingredients =====

Ingred Name:ASBESTOS, CHRYSOTILE
CAS:12001-29-5
RTECS #:CI6478500
Other REC Limits:NONE SPECIFIED
OSHA PEL:0.2 FIBERS/CC
ACGIH T

LV:2 FIBERS/CC; A1;9192

Ingred Name:INERT FILLERS
Other REC Limits:NONE SPECIFIED

Ingred Name:BINDERS, RUBBER (SYNTHETIC)
Other REC Limits:NONE SPECIFIED

Ingred Name:CURING AGENTS
Other REC Limits:NONE SPECIFIED

=====
===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO
Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:YES
Health Hazards Acute and Chronic:BREATHING DUST CAN CAUSE CANCER AND LUNG DISEASE.

Explanation of
Carcinogenicity:THIS MATERIAL CONTAINS ASBESTOS.
Effects of Overexposure:NONE SPECIFIED BY MANUFACTURER.
Medical Cond Aggravated by Exposure:RESPIRATORY AND PULMONARY DISORDERS CAN BE AGGRAVATED BY EXPOSURE.

=====
===== First Aid Measures =====

First Aid:NONE SPECIFIED BY MANUFACTURER.

=====
===== Fire Fighting Measures =====

Extinguishing Media:USE WATER AND FOAM AS EXTINGUISHING AGENTS.
Fire Fighting Procedures:AVOID BREATHIN
G FUMES.
Unusual Fire/Explosion Hazard:NONE

=====
===== Accidental Release Measures =====

Spill Release Procedures:WET METHODS SHOULD BE USED FOR EXTRACTION OF DUST AND DEBRIS. HIGH EFFECIENCY PARTICULATE APPARATUS VACS SHOULD BE USED.
Neutralizing Agent:NONE

=====
===== Handling and Storage =====

Handling and Storage Precautions:NONE
Other Precautions:AVOID BREATHING DUST.

=====
===== Exposure Controls/Personal Protection =====

=====

Respiratory Protection:USE THE APPROPRIATE DUST RESPIRATOR TO PREVENT INHALATION OF HAZARDOUS MATERIALS.

Ventilation:LOCAL AND MECHANICAL EXHAUST VENTILATION.

Protective Gloves:AS NEEDED

Eye Protection:SAFETY GLASSES.

Other Protective Equipment:NONE

Work Hygienic Practices:WASH HANDS AFTER HANDLING THIS MATERIAL.

Supplemental Safety and Health
NONE

===== Physical/Chemical Properties =====

HCC:N1

Solubility in Water:INSOLUBLE

Appearance and Odor:BLACK S

HEET MATERIAL WITH A SLIGHT RUBBERY SMELL.

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

NONE

Stability Condition to Avoid:NONE

Hazardous Decomposition Products:MATERIAL MAY BURN WITH DIFFICULTY AND IN SUCH CIRCUMSTANCES EMIT TOXIC RUBBER COMBUSTION PRODUCTS.

===== Disposal Considerations =====

Waste Disposal Methods:WASTE SHOULD BE CONTAINED IN IMPERMEABLE BAGS, LABELED AND DISPOSED IN ACCORDANCE WITH LOCAL AND FEDERAL REGULATIONS FOR ASBESTOS CONTAINING PRODUCTS. WASTE IS TO BE CONTAINED IN IMPERMEABLE BAGS AND LABELED.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document

should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.