View NSN Online: https://aerobasegroup.com/nsn/5330-00-314-7555 COLT INDUSTRIES OPERATING CORP FAIRBANKS MORSE ENG -- 16200376 GASKET 5330-00-314-7555 ============= Product Identification ======================== Product ID:16200376 GASKET MSDS Date:09/30/1992 FSC:5330 NIIN:00-314-7555 MSDS Number: BNVYH === Responsible Party === Company Name: COLT INDUSTRIES OPERATING CORP FAIRBANKS MORSE ENG Address:701 LAWTON AVE City:BELOIT State:WI ZIP:53511-5447 Country:US Preparer's Name: DGSC-SSH CAGE:82796 === Contractor Identification === Company Name: COLT INDUSTRIES OPERATING CORP FAIRBANKS MORSE ENG Address:701 LAWTON AVE Box:City:BELOIT State:WI ZIP:53511-5447 Country:US Phone:608-364-4411 CAGE:82796 ======= Composition/Information on Ingredients ======== Ingred Name: ASBESTOS, CHRYSOTILE CAS:12001-29-5

RTECS #:CI6478500

Other REC Limits: NONE RECOMMENDED

OSHA PEL:0.2 FIBERS/CC

ACGIH TLV:2 FIBERS/CC; A1;9192

======= Hazards Identification ========

========

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO

Health Hazards Acute and Chronic:PROLONGED OR REPEATED EXPOSURE TO AIRBORNE ASBESTOS FIBERS FROM SANDING, CUTTING, SCRAPPING, FILING, ETC. MAY LEAD TO ASBESTOSIS AND MESOTHELIOMA. SMOKING COMBINED WITH FIBER INHALATION GREATLY INCREA SES LUNG CANCER RISK.

Explanation of Carcinogenicity:OVEREXPOSURE TO AIRBORNE CONCENTRATIONS OF ASBESTOS MAY LEAD TO ASBESTO

SIS AND MESOTHELIOMA.

Effects of Overexposure:INHALATION OF AIRBORNE DUST CONTAINING ASBESTOS FIBERS ON REPEATED EXPOSURE MAY CAUSE OR CAN LEAD TO ASBESTOSIS / MESOTHELIOMA; DUST MAY CAUSE EYE IRRITATION.

Medical Cond Aggravated by Exposure:PERSONS WITH RESPIRATORY DISEASE OR PERSONS WHO SMOKE MAY BE AT INCREASED RISK FROM EXPOSURE TO DUST CONTAINING ASBESTOS FIBERS.

First Aid:INHALATION: REMOVE TO FRESH AIR.

GET MEDICAL ATTENTION. EYE:

PROMPTLY FLUSH WITH RUNNING WATER FOR 15 MINUTES WHILE LIFTING EYELID. GET MEDICAL ATTENTION. SKIN: PROMPTLY FLUSH WITH SOAP AND WATER. REM OVE CONTAMINATED CLOTHING. GET MEDICAL ATTENTION IF IRRITATION PERSISTS. INGESTION: GET MEDICAL ATTENTION AS REQUIRED.

========== Fire Fighting Measures ===============

Flash Point:NONE

Autoignition Temp: Autoignition Temp Text: NONE

Extinguishing Media:MATERIAL IS NOT FLAMMABLE; USE MEDIA APPRO PRIATE


FOR SURROUNDING FIRE.

Fire Fighting Procedures: COMBUSTION PRODUCTS OF THIS MATERIAL MAY BE TOXIC. USE A SELF-CONTAINED BREATHING APPARATUS WHEN FIGHTING FIRES INVOLVING CHEMICAL PRODUCTS.

Unusual Fire/Explosion Hazard:NONE

======== Accidental Release Measures ===========

Spill Release Procedures:USE PROPER PERSONAL PROTECTION. VACUUM OR WET CLEAN IF DUST IS INVOLVED. ANY VACUUM SYSTEM SHOULD BE EQUIPPED WITH AN OUTLET "HEPA" FILTER TO PREVENT REINT



PERTAINING TO ASBESTOS. USE

LANDFILLS APPROVED FOR ASBESTOS DISPOSAL. INDICATE IF ITEM UNDER

CONSIDERATION FOR DISPOSAL IS "FRIABLE OR NON-FRIABLE".

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing th is

document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.