View NSN Online: https://aerobasegroup.com/nsn/5330-00-599-3261

Product ID: GASKET MATERIAL TYPE TBA 510 BLACK MSDS Date:11/01/1985 FSC:5330 NIIN:00-599-3261 **MSDS Number: BPBYS** === Responsible Party === Company Name: TBA INDUSTRIAL PRODUCTS LTD Address:SEALING MATERIAL DIVISION Box:40 City:ROCHDALE LANCS Country:UK CAGE:U1309 === Contractor I dentification === Company Name: FABRICATION SPECIALTY INC Address:955 SLOCUM ST Box:227018 City:DALLAS State:TX ZIP:75222-7018 Country:US Phone:214-742-3571 CAGE:28548 Company Name: TBA INDUSTRIAL PRODUCTS Box:21 City:ROCHDALE,LANCS,ENGLAND Country:EN Phone:800-527-1935 CAGE:U1309

Ingred Name:ASBESTOS, CHRYSOTILE CAS:12001-29-5 RTECS #:CI6478500 Fraction by Wt: 72% Other REC Limits:NONE RECOMMENDED OSHA PEL:0.2 FIBERS/CC ACGIH TLV:2 FIBERS/CC; A1;9293

Ingred Name:INERT FILLERS Fraction by Wt: 3% Other REC Limits:NONE RECOMMENDED

Ingred Name:RUBBER BINDER Fraction by Wt: 20% Other REC Limits:NONE RECOMMENDED

Ingred Name:CURING AGENTS, PROCESSING AIDS AND PIGMENTS Fraction by Wt: 5% Other REC Limits:NONE RECOMMENDED

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:YES Health Hazards Acute and Chronic:THE DISEASES WHICH MAY ARISE FROM THE INHALATION OF ASBESTOS DUST ARE ASBESTOSIS, LUNG CANCER AND MESOTHALIOMA. Explanation of Carcinogenicity:ASBESTOS IS A HUMAN CARCINOGEN. Effects of Overexposure:THE EFFECTS OF ASBESTOS AND TOBACCO ACT SYNERGISTICALLY SO THAT SMOKING GREATLY INCREASES THE HEALTH RISK FOR AN ASBESTOS WORKER.

Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.

Fir

st Aid:NONE SPECIFIED BY MANUFACTURER.

Extinguishing Media:USE WATER OR FOAM AS EXTINGUISHING AGENT. Fire Fighting Procedures:AVOID BREATHING FUMES. Unusual Fire/Explosion Hazard:MATERIAL WILL BURN WITH DIFFICULTY.

Handling and Storage Precautions:NONE SPECIFIED BY MANUFACTURER. Other Precautions:NONE

======= Exposure Controls/Personal Protection =

Respiratory Protection:NOT REQUIRED FOR NORMAL HANDLING (CUTTING OPERATIONS) BUT USE APPROVED TYPE IF MATERIAL IS ABRADED OR BECOMES FRIABLE.

Ventilation: IN HEAVY DUTY JOINT CUTTING OPERATIONS, LOCAL DUST EXTRACTION MAY BE DESIRABLE.

Protective Gloves: NONE SPECIFIED BY MANUFACTURER.

Eye Protection: NONE SPECIFIED BY MANUFACTURER.

Other Protective Equipment: HAVE EMERGENCY EYE WASH AND SAFETY SHOWER AVAILABLE.

Work Hygienic Practices: GOOD HOUSEKEEPING IS IMPORTANT.

Sup

plemental Safety and Health

THE DEBRIS RESULTING FROM GASKET CUTTING, ETC. SHOULD NOT BE ALLOWED TO ACCUMULATE BUT SHOULD BE FREQUENTLY REMOVED BY DUSTLESS METHODS, PREFERABLY BY MEANS OF A VCAUUM CLEANER WHICH HAS BEEN APPROVED FOR USE AGAINST ASBESTOS.

HCC:T7

Solubility in Water:NOT SOLUBLE

Appearance and Odor: BLACK SHEET MATERIAL (SLIGHT RUBBERY SMELL)

========= Stability and Reactivity Data =======

\_\_\_\_\_

Stability Indicator/Materials to Avoid:YES

NONE SPECIFIED BY MANUFACTURER.

Stability Condition to Avoid:AVOID ABRADING THE MATERIAL UNLESS DUST EXTRACTION IS AVALIABLE OR RESPIRATORY PROTECTION IS WORN. Hazardous Decomposition Products:MATERIAL WILL BURN WITH DIFFICULTY & IN SUCH CIRCUMSTANCES EMIT TOXIC RUBBER COMBUSTION PRODUCTS.

Waste Disposal Methods:DISPOSE OF CUT MATERIAL AND OLD GASKETS IN ACCORD

ANCE WITH LOCAL GOVERNMENT LEGISLATION FOR ASBESTOS CONTAINING PRODUCTS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume respo nsibility for the suitability of this information to their particular situation.