FLEXITALLIC GASKET CO -- ASBESTOS FILLED SPIRAL WOUND GASKET -- 5330-01-044-2328

Product ID:ASBESTOS FILLED SPIRAL WOUND GASKET MSDS Date:07/09/1986 FSC:5330 NIIN:01-044-2328 MSDS Number: BPMJL === Responsible Party === Company Name: FLEXITALLIC GASKET CO Address:6915 LAPORTE RD **City:DEER PARK** State:TX ZIP:77536 Country:US Info Phone Num:713-479-3491 **Emergency Ph** one Num:713-479-3491 CAGE:5N484 === Contractor Identification === Company Name: FLEXITALLIC GASKET CO Address:6915 LAPORTE RD Box:City:DEER PARK State:TX ZIP:77536 Country:US Phone:713-479-3491 CAGE:5N484 Company Name: PRO TECHNICAL PRODUCS INC Address:1220 ROCK ST Box:City:ROCKFORD State:IL ZIP:61101 Country:US Phone:815-964-7940 CAGE:4V314

Ingred Name:ASBESTOS, CHRYSOTILE CAS:12001-29-5 RTECS #:CI6478500 Other REC Limits:NONE SPECIFIED OSHA PEL:0.2 FIBERS/CC ACGIH TLV:2 FIBERS/CC; A1;9192

Routes of Entry: Inhalation:YES Skin:NO Ingestion:YES Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:YES Health Hazards Acute and Chronic: TOXIC BY INHALATION OF DUST. ACUTE: DUST MAY CAUSE IRRITATION TO THE EYES, SKIN AND REPIRATORY TRACK. CHRONIC: INHALATION OF ASBESTOS FIBERS MAY CAUSE ASBESTOSIS AND MESOTHELIOMA. SMOKING GREATLY ENHANC ES T HE RISK OF ASBESTOSIS. Effects of Overexposure: IRRITATION, COUGHING, DIFFICULTY IN BREATHING, SHORTNESS OF BREATH, CHEST &/OR ABDOMINAL PAIN. Medical Cond Aggravated by Exposure: BRONCHIAL HYPER-REACTIVITY, PUMONARY DISEASES. First Aid:INHALATION:REMOVE TO FRESH AIR. EYE CONTACT:FLUSH WITH WATER FOR 15 MINUTES. SEE PHYSICIAN IF IRRITATION PERSIST. SKIN CONTACT: WASH WITH SOAP AND WATER. GET MED ATTENTION IF SYMP TOMS PERSIST. INGESTIO N:DO NOT INDUCE VOMITING, CONSULT PHYSICIAN. Extinguishing Media:WATER Fire Fighting Procedures: FIRE FIGHTERS SHOULD BE EQUIPED WITH SELF-CONTAINED BREATHING APPARATUS. **Unusual Fire/Explosion Hazard:NONE** Spill Release Procedures: PICK UP MATERIAL. VACUUM UP POWDER. DO NO CREATE DUST. USE RESPIRATORY PROTECTION FOR DUSTY CON DITIONS. Neutralizing Agent:NONE Handling and Storage Precautions: AVOID CREATING DUST. DO NOT SAND OR DRY SWEEP WITHOUT RESPIRATORY PROTECTION. Other Precautions:NONE Respiratory Protection: NONE UNDER NORMAL CONDITIONS. WEAR NIOSH APPROVED DUST RESPIRATOR WHEN SANDING, ABRASING OR DRY SWEEPING ASBESTOS DUST. Ventilation:LOCAL Protective Gloves:NO

NE

Eye Protection:SAFETY GLASSES Other Protective Equipment:EYEWASH

Work Hygienic Practices: DO NOT SMOKE WHILE SANDING, BRADING OR SWEEPING DUST.

Supplemental Safety and Health FINISHED PRODUCT IN SPIRAL WOUND GASKETS.

HCC:T6 Vapor Density:0 Spec Gravity:2.5 Solubility in Water:INSOLUBLE Appearance and Odor:SOLID COMPOSITE MATERIAL, LIGHT BLUE, NO ODOR. Percent Volatiles by Volume:00

Stability Indicator/Materials to Avoid:YES HYDROFLOURIC ACID AND CONCENTRATED ALKALI. Stability Condition to Avoid:NONE Hazardous Decomposition Products:ASBESTOS FIBERS.

Waste Disposal Methods:STANDARD LANDFILL IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements o f the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.