View NSN Online: https://aerobasegroup.com/nsn/3439-01-009-2855

Product ID:FILLER METALS AND WELDING RODS, JB (10,14,38

MSDS Date:01/01/1987

FSC:3439

NIIN:01-009-2855

MSDS Number: BPVFW === Responsible Party ===

Company Name: RICKARD METALS INC

Address:1707 S GROVE AVE

City:ONTARIO

State:CA ZIP:91761 Country:US

Info Phone Num:714-947-4922/FAX

-4909

Emergency Phone Num:714-947-4922

CAGE:67604

=== Contractor Identification ===

Company Name: J B ALLOY CO INC

Address:330 S 66TH ST

Box:230070 City:HOUSTON State:TX

ZIP:77011 Country:US

Phone:713-926-3232

CAGE:4M698

Company Name: RICKARD METALS INC

Address:1707 S GROVE AVE

Box:City:ONTARIO

State:CA ZIP:91761 Country:US

Phone:714-947-4922

CAGE:67604

====== Composition/Information on Ingredients ========

Ingred Name: NICKEL (SARA III)

CAS:7440-02-0

RTECS #:QR5950000

Other REC L

imits:NONE RECOMMENDED

OSHA PEL:1 MG/M3

ACGIH TLV:1 MG/M3; 9293

Ingred Name:BORON

CAS:7440-42-8

RTECS #:ED7350000

Other REC Limits: NONE RECOMMENDED

ACGIH TLV:10 MG/M3 (MFR)

Ingred Name:IRON CAS:7439-89-6

RTECS #:NO4565500

Other REC Limits: NONE RECOMMENDED

OSHA PEL:5 MG/M3 (MFR) ACGIH TLV:10 MG/M3 (MFR)

Ingred Name: SILICON

CAS:7440-21-3

RTECS #: VW0400000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Name: CHROMIUM (SARA III)

CAS:7440-47-3

RTEC

S#:GB4200000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:1 MG/M3

ACGIH TLV:0.5 MG/M3; 9293

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name: SILICON

CAS:7440-21-3

RTECS #:VW0400000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9293

========= Hazards Identification ==============

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO

Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:NO Health Hazards Acute and Chronic:ACUTE-FUMES & GAS

ES CAN BE DANGEROUS TO YOUR HEALTH.ARC RAYS CAN INJURE EYES & BURN SKIN.ELECTRIC SHOCK CAN KILL.INHALATION OF FUMES MAY CAUSE DIZZINESS, NAUSEA, DRYNESS/IRRITATION OF NOSE, THROAT/EYES, TIGHTNESS IN CHEST, FEVER & ALLERGIC REACTIONS. MAY LEAD TO SIDEROSIS & AFFECT PULMONARY FUNCTION.CHRONIC-CAN CAUSE CANCER.

Explanation of Carcinogenicity: CONTAINS NICKEL AND CHROMIUM.

Effects of Overexposure: FUMES & GASES CAN BE DANGEROUS TO YOUR HEALTH. ARC RAYS CAN INJURE EYES & BURN SKIN, E

LECTRIC SHOCK CAN KILL.

INHALATION OF FUMES MAY CAUSE DIZZINESS, NAUSEA, DRYNESS/IRRITATION OF NOSE, THROAT/EYES. TIGHTNESS IN CHEST, FEVER & ALLERGIC REACTIONS. MAY LEAD TO SIDEROSIS & AFFECT PULMONARY FUNCTION.

Medical Cond Aggravated by Exposure: PRE-EXISTING SKIN DISORDERS MAY BE MORE SUSCEPTIBLE TO THIS MATERIAL.

First Aid:GET MEDICAL ATTENTION IF SYMPTOMS PERSIST. SKIN:WASH WITH SOAP & WATER, EYE:FLU

SH WITH WATER FOR 15 MINUTES, HOLDING EYELIDS OPEN. INHALED:REMOVE TO FRESH AIR. PROVIDE OXYGEN/CPR IF NEEDED. ORAL:GET P ROMPT MEDICAL ATTENTION.

============= Fire Fighting Measures ========================

Flash Point:NONE

Extinguishing Media: WATER SPRAY, CARBON DIOXIDE, FOAM OR DRY CHEMICAL FOR SURROUNDING FIRE. USE WATER SPRAY TO COOL FIRE EXPOSED CONTAINERS.

Fire Fighting Procedures: WEAR FULL PROTECTIVE CLOTHING AND NIOSH-APPROVED SELF-CONTAINED BREATHING APPAR

ATUS WITH FULL

FACEPIECE OPERATED IN THE POSITIVE PRESSURE MODE.

Unusual Fire/Explosion Hazard: WELDING ARC AND SPARKS CAN IGNITE COMBUSTIBLES AND FLAMMABLES.

======================================	
--	--

Handling and Storage Precautions: STORAGE- STORE IN DRY PLACE.

Other Precautions: AN ADEQUATE EXHAUST SYSTEM IS REQUIRED TO AVOID THE EFFECT OF FUMES. DO NOT INHALE FUMES OR DUST. WASH THOROUGHLY AFTER HANDLING.

====== Exposure Controls/Personal Pro

tection ========

Respiratory Protection:USE NIOSH APPROVED SUPPLIED AIR RESPIRATORY PROTECTION OR RESPIRABLE FUME RESPIRATOR WHEN WELDING, BRAZING OR SOLDERING IN CONFINED SPACE OR WHERE LOCAL EXHAUST OR VENTILATION DOES NOT KEEP EXPOSURE B ELOW TLV.

Ventilation:LOCAL EXHAUST

Protective Gloves: WELDER'S GLOVES

Eye Protection: CHEMICAL SAFETY GOGGLES

Other Protective Equipment: EYE WASH STATION, QUICK DRENCH SHOWER AND

IMPERVIOUS CLOTHING

Work Hygienic Practices: OBSERVE GOOD P

ERSONAL HYGIENE PRACTICES AND

RECOMMENDED PROCEDURES.

Supplemental Safety and Health

THE MSDS WAS UNDATED. THE MANUFACTURER STATED THAT THE ORIGINAL MSDS WAS WITHOUT DATE AND THEY ARE NOT MAKING PRODUCT SINCE 1987.

======================================
HCC:N1
======== Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES NONE Stability Condition to Avoid:NONE Hazardous Decomposition Products:CARBON MONOXID E, CARBON DIOXIDE, OZONE, NITROGEN OXIDES MAY BE FORMED.
====== Disposal Considerations ==========

Waste Disposal Methods:PREVENT WASTE FROM CONTAMINATING SURROUNDING ENVIRONMENT. DISCARD ANY PRODUCT RESIDUE, DISPOSABLE CONTAINER OR LINER IN AN ENVIRONMENTALLY ACCEPTABLE MANNER, IN FULL COMPLIANCE WITH FEDERAL, STATE & L OCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by

elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.