View NSN Online: https://aerobasegroup.com/nsn/9150-00-116-0506

PHILLIPS PETROLEUM COMPANY -- TROP-ARTIC ALL SEASON MOTOR OIL -- 9150-00-116-0506

Product ID:TROP-ARTIC ALL SEASON MOTOR OIL

MSDS Date:01/01/1987

FSC:9150

NIIN:00-116-0506

MSDS Number: BQMYF === Responsible Party ===

Company Name: PHILLIPS PETROLEUM COMPANY Address: 758 ADAMS BLDG, 4TH AND KEELER

City:BARTLESVILLE

State:OK ZIP:74004 Country:US

Info Phone Num:918-6 61-8327/5952(MSDS)

Emergency Phone Num:918-661-3865/8118

CAGE:46916

=== Contractor Identification ===

Company Name: PHILLIPS PETROLEUM CO

Address:613 ADAMS Box:City:BARTLESVILLE

State:OK ZIP:74004 Country:US

Phone:800-234-6603

CAGE:46935

Company Name: PHILLIPS PETROLEUM COMPANY

CAGE:46916

======= Composition/Information on Ingredients ========

Ingred Name: SOLVENT REFINED HEAVY PARAFFINIC OIL

Other REC Limits:NONE SPECIFIED OSHA PEL:5 MG/M3 AS OIL MIST ACGIH TLV:5 MG/M3 AS OIL MIST

======================================
Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:EYE: MILD IRRITATION. SKIN: PRACTICALLY NON-TOXIC BY SKIN ABSORPTION. MILD TO MODERATE IRRITATION WITH PROLONGED OR REPEATED CONTACT. INHALE: NONE EXPECTED TO 25 MG/M3 OF AIR. INGESTION: PRACTICALLY N ON-TOXIC. Explanation o f Carcinogenicity:NONE OF THE CHEMICALS IN THIS PRODUCT IS
LISTED BY IARC, NTP OR OSHA AS A CARCINOGEN. Effects of Overexposure:MILD EYE & SKIN IRRITATION. Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.
======================================
First Aid:EYES: IMMEDIATELY FLUSH WITH RUNNING WATER FOR AT LEAST 15 MINUTES WHILE LIFTING EYELIDS OPEN. IF IRRITATION DEVELOPS OR PERSISTS, GET MEDICAL ATTENTION. SKIN: WASH WITH SOAP AND PLEN TY OF
WATER. IF I RRITATION DEVELOPS OR PERSISTS, GET MEDICAL ATTENTION. VAPOR INHALATION UNLIKELY: REMOVE TO FRESH AIR. GET MEDICAL ATTENTION IF REQUIRED. INGESTION: DO NOT INDUCE VOMITING. GET MEDICAL ATTENTION.
======================================
Flash Point Method:COC Flash Point:>400F,>204C Extinguishing Media:USE CARBON DIOXIDE, FOAM, OR DRY CHEMICAL. Fire Fighting Procedures:SHUT OFF SOURCE. USE NIOSH/MHSA APPROVED SCBA & OTHER PROTEC TIVE EQUIPMENT . USE WATER SPRAY/FOG TO COOL EXPOSED CONTAINERS. DO NOT SPRAY DIRECTLY ON FIRE. Unusual Fire/Explosion Hazard:CARBON OXIDES AND VARIOUS HYDROCARBONS FORM WHEN BURNED.
Flash Point:>400F,>204C Extinguishing Media:USE CARBON DIOXIDE, FOAM, OR DRY CHEMICAL. Fire Fighting Procedures:SHUT OFF SOURCE. USE NIOSH/MHSA APPROVED SCBA & OTHER PROTEC TIVE EQUIPMENT . USE WATER SPRAY/FOG TO COOL EXPOSED CONTAINERS. DO NOT SPRAY DIRECTLY ON FIRE. Unusual Fire/Explosion Hazard:CARBON OXIDES AND VARIOUS HYDROCARBONS
Flash Point:>400F,>204C Extinguishing Media:USE CARBON DIOXIDE, FOAM, OR DRY CHEMICAL. Fire Fighting Procedures:SHUT OFF SOURCE. USE NIOSH/MHSA APPROVED SCBA & OTHER PROTEC TIVE EQUIPMENT. USE WATER SPRAY/FOG TO COOL EXPOSED CONTAINERS. DO NOT SPRAY DIRECTLY ON FIRE. Unusual Fire/Explosion Hazard:CARBON OXIDES AND VARIOUS HYDROCARBONS FORM WHEN BURNED. ===================================
Flash Point:>400F,>204C Extinguishing Media:USE CARBON DIOXIDE, FOAM, OR DRY CHEMICAL. Fire Fighting Procedures:SHUT OFF SOURCE. USE NIOSH/MHSA APPROVED SCBA & OTHER PROTEC TIVE EQUIPMENT . USE WATER SPRAY/FOG TO COOL EXPOSED CONTAINERS. DO NOT SPRAY DIRECTLY ON FIRE. Unusual Fire/Explosion Hazard:CARBON OXIDES AND VARIOUS HYDROCARBONS FORM WHEN BURNED. ===================================
Flash Point:>400F,>204C Extinguishing Media:USE CARBON DIOXIDE, FOAM, OR DRY CHEMICAL. Fire Fighting Procedures:SHUT OFF SOURCE. USE NIOSH/MHSA APPROVED SCBA & OTHER PROTEC TIVE EQUIPMENT. USE WATER SPRAY/FOG TO COOL EXPOSED CONTAINERS. DO NOT SPRAY DIRECTLY ON FIRE. Unusual Fire/Explosion Hazard:CARBON OXIDES AND VARIOUS HYDROCARBONS FORM WHEN BURNED. ===================================
Flash Point:>400F,>204C Extinguishing Media:USE CARBON DIOXIDE, FOAM, OR DRY CHEMICAL. Fire Fighting Procedures:SHUT OFF SOURCE. USE NIOSH/MHSA APPROVED SCBA & OTHER PROTEC TIVE EQUIPMENT. USE WATER SPRAY/FOG TO COOL EXPOSED CONTAINERS. DO NOT SPRAY DIRECTLY ON FIRE. Unusual Fire/Explosion Hazard:CARBON OXIDES AND VARIOUS HYDROCARBONS FORM WHEN BURNED. ===================================
Flash Point:>400F,>204C Extinguishing Media:USE CARBON DIOXIDE, FOAM, OR DRY CHEMICAL. Fire Fighting Procedures:SHUT OFF SOURCE. USE NIOSH/MHSA APPROVED SCBA & OTHER PROTEC TIVE EQUIPMENT. USE WATER SPRAY/FOG TO COOL EXPOSED CONTAINERS. DO NOT SPRAY DIRECTLY ON FIRE. Unusual Fire/Explosion Hazard:CARBON OXIDES AND VARIOUS HYDROCARBONS FORM WHEN BURNED. ===================================

Ingred Name: ADDITIVES
Other REC Limits: NONE SPECIFIED

and Storage ==========

Handling and Storage Precautions:STORE IN A COOL, WELL-VENTILATED AREA AWAY FROM IGNITION SOURCES. KEEP CONTAINERS CLOSED.

Other Precautions:AVOID INHALATION AND SKIN AND EYE CONTACT. WEAR PROTECTIVE EQUIPMENT. WASH HANDS AFTER HANDLING. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE.

====== Exposure Controls/Personal Protection ========

Respiratory Protection: NONE NORMALLY REQUIRED.

Ventilation: USE ADEQUATE VENTILATION.

Protective GI

oves: NONE NORMALLY REQUIRED.

Eye Protection: SAFETY GLASSES WITH SIDE SHIELD.

Other Protective Equipment: NONE SPECIFIED BY MANUFACTURER.

Work Hygienic Practices: WASH THOROUGHLY AFTER HANDLING.

Supplemental Safety and Health

PERSONAL PROTECTION INFORMATION IS BASED UPON GENERAL INFORMATION AS TO NORMAL USES AND CONDITIONS. WHERE SPECIAL OR UNUSUAL USES OR CONDITIONS EXIST, IT IS SUGGESTED THAT THE EXPERT ASSISTANCE OF AN INDUSTRIAL HYGIENIST OR OTHER QUALIFIEDPROFESSIONAL BE SOUGHT.

======== Physical/Chemical Properties ==========

HCC:V6 Vapor Pres: