View NSN Online: https://aerobasegroup.com/nsn/8040-01-323-3635

RUBATEX CORP SUB OF GREAT AMERICAN INDUSTRIES INC -- R-27710 CONTACT ADHESIVE -- 8040-01-323-3635

Product ID:R-27710 CONTACT ADHESIVE MSDS Date:11/01/1991 FSC:8040 NIIN:01-323-3635 MSDS Number: BRMBW === Responsible Party === Company Name: RUBATEX CORP SUB OF GREAT AMERICAN INDUSTRIES INC Address:605 ADAMS ST Box:340 City:BEDFORD State:VA ZIP:24523 Country:US Inf o Phone Num:703-586-2611 Emergency Phone Num:703-586-2611 CAGE:82942 === Contractor Identification === Company Name: RUBATEX CORP SUB OF GREAT AMERICAN INDUSTRIES INC Address:605 ADAMS ST Box:340 City:BEDFORD State:VA ZIP:24523 Country:US CAGE:82942

Ingred Name:TOLUENE (SARA III) CAS:108-88-3 RTECS #:XS5250000 Fraction by Wt: 14% Other REC Limits:NONE RECOMMENDED OSHA PEL:200 PPM/150 STEL ACGIH TLV:50 PPM; 9293 EPA Rpt Qty:10 00 LBS DOT Rpt Qty:1000 LBS

Ingred Name:HEXANE (N-HEXANE) CAS:110-54-3 RTECS #:MN9275000 Fraction by Wt: 32% Other REC Limits:NONE RECOMMENDED OSHA PEL:500 PPM ACGIH TLV:50 PPM; 9293 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:ACETONE (SARA III) CAS:67-64-1 RTECS #:AL3150000 Fraction by Wt: 32% Other REC Limits:NONE RECOMMENDED OSHA PEL:1000PPM ACGIH TLV:750PPM/1000STEL;9293 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Rout

es of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:INHALATION: BREATHING DIFFICULTY, & LOSS OF COORDINATION. EYE CONTACT: SEVERE IRRITATION. SKIN CONTACT: CAN DRY & DEFAT SKIN CAUSING IRRITATION & DERMATITIS. INGESTION: CAN CAUSE GASTROINTESTINAL IRRI TATION. Explanation of Carcinogenicity:THIS COMPOUND CONTAINS NO INGREDIENTS AT CONCENTRATIONS OF 0.1% OR GREATER THAT ARE CARCINOGENS OR SUSPEC T

CARCINOGENS.

Effects of Overexposure:INHALATION: DIZZINESS, HEADACHE. SKIN & EYE CONTACT: CAN CAUSE CRACKS IN SKIN. CAN CAUSE TEARING, REDNESS & BLURRED VISION. INGESTION: CAN CAUSE VOMITING, NAUSEA & DIARRHEA. Medical Cond Aggravated by Exposure:ANESTHESIA, RESPIRATORY IRRITATION, DERMATITIS, NAUSEA, VOMITING.

First Aid:INHALATION: MOVE PERSON TO FRESH AIR. IF BREATHING STOPS, APPLY CPR & SEEK IMMEDIATE MEDICAL ATTENTION. EYE: FLUSH WITH LARGE QUANTITIES OF WATER FOR 15 MIN. SKIN: WASH THOROUGHLY WITH SOAP & WATER & SEE A DOCTOR. INGESTION: DO NOT INDUCE VOMITING, CAN CAUSE CHEMICAL PHEUMONITIS EDEMA. CONTACT A PHYSICIAN IMMEDIATELY.

Flash Point Method:CC Flash Point:-14F.-26C Lower Limits:1.0% Extinguishing Media: FOAM, CARBON DIOXIDE, DRY CHEMICAL. Fire Fighting Procedures: RESPIRATORY EQUIPMENT SHOULD BE WORN TO AVOID INHALATION OF CONCENTRATED VAPORS. WATER SHOULD NOT BE USED EXCEPT AS FOG TO KEEP NEARBY CONTAINERS COOL. Unusual Fire/Explosion Hazard: HANDLE AS FLAMMABLE LIQUID. VAPORS FORM AN EXPLOSIVE MIXTURE IN AIR BETWEEN THE UPPER & LOWER EXPLOSIVE LIMITS WHICH CAN BE IGNITED BY MANY SOURCES. Spill Release Procedures: ELIMINATE IGNITION SOURCES, PROVIDE GOOD VENTILATION. DIKE SPILL AREA AND USE ABSORBENT MAT ERIAL TO CLEANUP. 

Handling and Storage Precautions: USE NON-SPARKING UTENSILS WHEN HANDLING THIS MATERIAL. AVOID HOT METAL SURFACES, USE IN COOL WELL-VENTILATED AREAS. KEEP CONTAINERS CLOSED.
Other Precautions: KEEP AWAY FROM EXCESSIVE HEAT AND OPEN FLAMES. SMOKING AREAS WHERE THIS MATERIAL IS USED SHOULD BE STRICTLY PROHIBITED. TOOLS USED WITH THIS MATERIAL SHOULD BE MADE OF ALUMINUM, BRASS, OR COPPER. PLAS
TIC UTENSILS SHOULD NOT BE USED.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection: WHEN SPRAYING THIS ADHESIVE USE A NIOSH APPROVED CARTRIDGE RESPIRATOR IN GAS MASK SUITABLE TO KEEP AIRBORNE MISTS AND CONCENTRATIONS BELOW THE TTLV. WHEN USING IN POORLY VENTILATED/CONFINED SPACES, US E A FRESH AIR SUPPLYING RESPIRATOR/SCBA.

Ventilation: GENERAL MECHANICAL VENTILATION OR LOCAL EXHAUST (EXPLOSION PROOF) SHOULD BE USE TO KEEP VAPOR CONCEN

TRATIONS BELOW TLV.
Protective Gloves: IMPERMEABLE CHEMICAL HANDLING GLOVES.
Eye Protection: CHEMICAL SAFETY GOGGLES.
Other Protective Equipment: USE IMPERMEABLE APRONS & PROTECTIVE CLOTHING WHENEVER POSSIBLE TO PREVENT SKIN CONTACT. THE USE OF HEAD CAPS RECOMMENDED
Work Hygienic Practices: EYE WASHES AND SAFETY SHOWERS IN THE WORK PLACE. IS RECOMMENDED.
Supplemental Safety and Health NONE

HCC:F2 Boiling Pt:B.P. Text: 132 TO 231F Vapor Density:>AIR Spec Gravity:0.8 Evaporation Rate & amp; Reference:SLOWER THAN ETHER. Solubility in Water:NO Appearance and Odor:BLACK, OFFENSIVE.

Stability Indicator/Materials to Avoid:YES ALKALINE MATERIALS, STRONG ACIDS AND OXIDIZING MATERIALS. Stability Condition to Avoid:EXCESSIVE HEAT, POOR VENTILATION,

CORROSIVE ATMOSPHERES, EXCESSIVE AGING. Hazardous Decomposition Products:CARBON MONOXIDE, CARBON DIOX IDE,

OXIDES OF NITROGEN, AND POSSIBLE ACROLEINS.

Waste Disposal Methods:COLLECT ABSORBED/SPILLED LIQUID MIXTURE & PLACE INTO METAL CONTAINERS. CONSULT STATE & FEDERAL HAZARDOUS WASTE REGULATIONS BEFORE DISPOSING INTO APPROVED HAZARDOUS WASTE LANDFILL. OBEY RELEVANT LAWS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.