View NSN Online: https://aerobasegroup.com/nsn/3439-01-137-7956

UNITED STATES WELDING CORP -- WELDING ROD -- 3439-01-137-7956

============= Product Identification ==============

Product ID:WELDING ROD MSDS Date:10/19/1993

FSC:3439

NIIN:01-137-7956

MSDS Number: BRSVQ === Responsible Party ===

Company Name: UNITED STATES WELDING CORP

Address:20700 DEARBORN ST

City:CHATSWORTH

State:CA

ZIP:91311-5912 Country:US

Info Phone Num:213-341-2021

Emergency Phone Num:213-341-2021

Preparer'

s Name:DGSC-SSH

CAGE:58401

=== Contractor Identification ===

Company Name: UNITED STATES WELDING CORP

Address:3579 HWY 50 E SUITE 104

Box: City: CARSON CITY

State:NV

ZIP:89701-2807 Country:US

Phone:775-883-7878

CAGE:58401

======= Composition/Information on Ingredients ========

Ingred Name: COBALT (SARA III)

CAS:7440-48-4

RTECS #:GF8750000 Fraction by Wt: 50%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:0.1 MG/M3;AS CO

ACGIH TLV:0.05 MG/M3;DUST 9293

Ingred Name: CHROMIUM (SARA III)

CAS

:7440-47-3

RTECS #:GB4200000 Fraction by Wt: 26.5%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:1 MG/M3

ACGIH TLV:0.5 MG/M3; 9293

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name: NICKEL (SARA III)

CAS:7440-02-0

RTECS #:QR5950000 Fraction by Wt: 11.5%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:1 MG/M3

ACGIH TLV:1 MG/M3; 9293

Ingred Name:TUNGSTEN

CAS:7440-33-7

RTECS #:YO7175000 Fraction by Wt: 8%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:5 MG/M3/ 10 STEL

ACGIH TLV:5 MG/M3/10 STEL;9293

Ingred Name:

MANGANESE (SARA III)

CAS:7439-96-5

RTECS #:OO9275000 Fraction by Wt: 1%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:(C) 5 MG/M3 DUST ACGIH TLV:5 MG/M3 DUST 9293

Ingred Name: SILICON

CAS:7440-21-3

RTECS #:VW0400000 Fraction by Wt: 1%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Name: CARBON BLACK

CAS:1333-86-4 RTECS #:FF5800000 Fraction by Wt: 0.55%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:3.5 MG/M3

ACGIH TLV:3.5 MG/M3; 9293

=== Hazards Identification ============
LD50 LC50 Mixture:TLV FOR WELDING FUMES IS 5 MG/M3 Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:NO Health Hazards Acute and Chronic:ACUTE: FUMES AND GASES CAN CAUSE EYES AND UPPER RESPIRATORY SYSTEM IRRITATION, AND CENTRAL NERVOUS SYSTEM EFFECTS. ARC RAYS CAN INJURE EYES AND BURN SKIN. ELECTRIC SHOCK CAN KILL. NOISE CAN DAMAGE HEA RING. CHRONIC: NEUROLOGICAL DAMAGE, LUN G
FIBROSIS, PNEUMOCONIOSIS. Explanation of Carcinogenicity:NICKEL AND CHROMIUM ARE LISTED UNDER IARC AND NTP.
Effects of Overexposure:SHORT TERM EXPOSURE: NAUSEA, FEVER, DIZZINESS, DRYNESS, IRRITATION OF EYES, NOSE AND THROAT, SKIN SENSITIVITY, WATERY EYES, HEADACHE, BREATHING DIFFICULTY, FREQUENT COUGHING, SHORTNESS OF BREATH.
Medical Cond Aggravated by Exposure:AGGRAVATION OF EXISTING RESPIRATORY OR ALLERGIC CONDITIONS.HIGHER LEVEL OF LUNG RELATED PROBLEMS AMONG SMO KERS.
======================================
First Aid:INHALATION: REMOVE FROM EXPOSURE. IF BREATHING IS DIFFICULT, GIVE OXYGEN. IF NOT BREATHING, GIVE CPR. IF NO DETECTABLE PULSE, GIVE HEART MASSAGE. EYES: FLUSH WITH LARGE AMOUNTS OF WATER FOR AT LEAST 1 5 MINUTES. SKIN: WASH WITH SOAP AND WATER. INGESTION: SEEK MEDICAL ATTENTION.
======================================
Extinguishing Media:USE WATER FOG, CARBON DIOXI DE, FOAM, OR DRY CHEMICAL. Fire Fighting Procedures:WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL FACED SELF CONTAINED BREATHING APPARATUS. COOL FIRE EXPOSED CONTAINERS WITH WATER SPRAY

Unusual Fire/Explosion Hazard: COMBUSTION OR HEAT OF FIRE MAY PRODUCE HAZARDOUS DECOMPOSITION PRODUCTS AND VAPORS. WELDING ARCS AND SPARKS CAN IGNITE COMBUSTIBLE MATERIAL.

======== Accidental Release Measures ============

Spill Release Procedures: CLEAN UP ANY GRINDING

AND PLACE IN APPROPIATE DISPOSAL CONTAINER. AVOID INHALATION AND SKIN EXPOSURE.
========== Handling and Storage ===========
Handling and Storage Precautions:STORE IN DRY AREA. ELECTRODES EXPOSED TO MOISTURE MAY EXPLODE VIOLENTLY IF USED. DRY MOIST RODS BY BAKING AT 300F FOR TEN HOURS.
Other Precautions:TRAIN WELDER TO KEEP HIS HEAD OUT OF THE FUMES. MONITOR AIR TO ENSURE ACCEPTABLE EXPOSURES. AVOID ELECTRICAL SHOCK BY MAINTA
INING DRY WORK AREA.
====== Exposure Controls/Personal Protection ========
Respiratory Protection: FUME RESPIRATOR OR AIR SUPPLIED RESPIRATOR IN CONFINED SPACES OR WHERE VENTILATION DOES NOT KEEP EXPOSURE BELOW TLV.
Ventilation:LOCAL EXHAUST TO KEEP BELOW TLV.
Protective Gloves:WELDER'S GLOVES. Eye Protection:HELMET OR FACE SHIELD WITH FILTER LENS.
Other Protective Equipment:SUBSTANTIAL DARK CLOTH, ARM PROTECTOR, APRON, HAT AND SHOULDER PROTECTION. AIR SAMPLING TO DETE
RMINE CORRECTIVE MEACURES
CORRECTIVE MEASURES Work Hygienic Practices:WASH HANDS THOROUGHLY BEFORE EATING, SMOKING OR USING SANITARY FACILITIES.
Supplemental Safety and Health COMPANY OUT OF BUSINESS.INGREDIENTS AND DIMENSIONS ARE DERIVED FROM THE TIR.
========= Physical/Chemical Properties ==========
HCC:N1 Solubility in Water:INSOLUBLE. Appearance and Odor:SOLID ROD,LENGTH=36",OS DIAM=0.03"NOMINAL
========= Stability and Reactivity Data =========
Stability Indi

DUST OR WASTE RESIDUE

NONE.
Stability Condition to Avoid:AVOID GENERATION OF AIRBORNE DUST.
Hazardous Decomposition Products:FUMES OF METALS AND METAL OXIDES FROM ELECTRODE AND BASE METAL, CARBON MONOXIDE, CARBON DIOXIDE, OZONE, NITROGEN OXIDES.

======= Disposal Considerations ==========

cator/Materials to Avoid:YES

Waste Disposal Methods:CONSULT WITH YOUR LOCAL ENVIRONMENTAL OFFICER.
DISPOSE OF FUMES, FLUX OR WELD GRINDING RESIDUE FROM THE WORK AREA
OR FROM FILTERS IN ACCOR
DANCE WITH FEDERAL, STATE AND LOCAL
ENVIRONMENTAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.