City:ALLENTOWN

State:PA

ZIP:18195-1501 Country:US

Info Phone Num:215-481-4911

Emergency Phone Num:215-481-4911 OR 800-523-9374

CAGE:00742

=== Contractor Identification ===

Company Name: AIR PRODUCTS AND CHEMICALS INC

Address:7201 HAMILTON BLVD

Box:City:ALLENTOWN

State:PA

ZIP:18195-1501 Country:US

Phone:800-345-3148/800-752-1597

CAGE:00742

======= Composition/Information on Ingredients ========

Ingred Name: OXYGEN

CAS:7782-44-7

RTECS #:RS2060000

========== Hazards Identification ===========================

LD50 LC50 Mixtur

e:NONE SPECIFIED BY MANUFACTURER.

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:OXYGEN IS NON TOXIC UNDER MOST CONDITIONS OF USE AND IS NECESSARY TO SUPPORT LIFE. LIQUID OXYGEN OR COLD GAS WILL FREEZE TISSUES AND CAN CAUSE SEVERE CRYOGENIC BURNS. BREATHING OF PURE OXYGEN AT 60% M AY PRODUCE COUGH & CHEST PAIN, CNS MANIFESTATIONS. INFANTS EXPOSED TO 35-40% OXYGEN MAY SUFFER PERMANENT VISUAL DAMAGE.

Explanation of Carcinogenicity: NONE SPE

CIFIED BY MANUFACTURER.

Effects of Overexposure:WHEN EXPOSED TO 60% OXYGEN, SYMPTOMS INCLUDE COUGHING AND CHEST PAIN. THESE SYMPTOMS MAY BE SEEN IN SEVERAL DAYS. AT TWO ATMOSPHERES SYMPTOMS OCCUR IN 2-3 HOURS. INFANTS EXPOSED TO OXYGEN LEVELS IN EX CESS OF 35-40% MAY SUFFER PERNAMENT VISUAL IMPAIRMENT OR BLINDNESS.

Medical Cond Aggravated by Exposure: NONE SPECIFIED BY MANUFACTURER.

First Aid: IF CRYOGENIC LIQUI

D OR COLD BOIL-OFF GAS CONTACTS A WORKER'S SKIN OR EYES, FROZEN TISSUES SHOULD BE FLOODED OR SOAKED WITH TEPID WATER (105-115F; 41-46C). DO NOT USE HOT WATER. BURNS WHICH RESULT IN B LISTERING OR DEEPER TISSUE FREEZING SHOULD BE SEEN PROMPTLY BY A PHYSICIAN.

========= Fire Fighting Measures ==============

Flash Point:NONE

Extinguishing Media: NONE SPECIFIED BY MANUFACTURER.


Fire Fighting Procedures:OXYGEN IS NONFLAMMABLE, BUT SUPPORTS AND VIGOROUSLY ACCE

LERATES COMBUSTION OF FLAMMABLES. TO FIGHT FIRES, SHUT OFF SOURCES OF OXYGEN AND FIGHT FIRE.

Unusual Fire/Explosion Hazard:OXYGEN SUPPORTS AND VIGOROUSLY ACCELERATES COMBUSTION OF FLAMMABLES. SOME MATERIALS WHICH ARE NONCOMBUSTIBLE IN AIR WILL BURN IN THE PRESENCE OF OXYGEN.

======== Accidental Release Measures ==========

Spill Release Procedures:PREVENT LIQUID OXYGEN FROM CONTACTING GREASE, OIL AND OTHER COMBUSTIBLES. VENTILATE AREA TO DISPERSE OXYGEN,



ata ========

Stability Indicator/Materials to Avoid:YES

ALL FLAMMABLES, ESPICALLY PETROLEUM PRODUCTS, ASPHALT, OTHER VOLATILE FLAMMABLES.

Stability Condition to Avoid:MATERIALS WHICH BURN IN AIR WILL BURN VIOLENTLY IN ATMOSPHERE RICHER THAN APPROX. 25% OXYGEN. Hazardous Decomposition Products:NONE SPECIFIED BY MANUFACTURER.

======== Disposal Considerations =============

Waste Disposal Methods:ALLOW LIQUID OXYGEN TO EVAPORATE IN A WELL VENTILATED OUTD

OOR AREA. VENT OXYGEN GAS TO OUTSIDE LOCATION.
DISPOSAL SITE SHOULD BE REMOTE FROM WORK AREAS, OPEN FLAMES OR SOURCES OF IGNITION AND COMBUSTI BLES. RETURN CYLINDERS TO AIR PRODUCTS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability f

or its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.