View NSN Online: https://aerobasegroup.com/nsn/8040-00-145-0043

## 

Product ID:EPK 0151 HARDENER

MSDS Date:03/08/1993

FSC:8040

NIIN:00-145-0043

Kit Part:Y

MSDS Number: BZSSY === Responsible Party ===

Company Name: DEXTER CORP HYSOL DIV

Address:164 FOLLY MILL RD

City:SEABROOK

State:NH ZIP:03874 Country:US

Info Phone Num:603-474-5541

Emergency Phone Num:800-424-9300

Pre

parer's Name: KEN DE COSTA

CAGE:1JB33

=== Contractor Identification ===

Company Name: DEXTER CORP THE HYSOL DIV

Address:1 DEXTER DR Box:City:SEABROOK

State:NH ZIP:03874 Country:US

Phone:603-474-5541/FAX: 603-474-5545

CAGE:1JB33

======= Composition/Information on Ingredients ========

Ingred Name:TRIETHYLENE TETRAMINE

CAS:112-24-3

RTECS #:YE6650000 Fraction by Wt: 10-30%

Other REC Limits: NONE RECOMMENDED

**ACGIH TLV:1 PPM** 

Ingred Name: REACTIVE POLYAMIDE

CAS:68410-23-1 Fraction by Wt: 60 -100%

Other REC Limits: NONE RECOMMENDED

=========

Respiratory Protection: FRESH AIR MASK IN CONFINED SPACES.

Ventilation:LOCAL EXHAUST PREFERRED. MECHANICAL EXHAUST ACCEPTABLE.

RESPIRATORS SHOULD BE AVAILABLE IF VENTILATION FAILS.

Protective Gloves: RUBBER OR PLASTIC.

Eye Protection: SAFETY GLASSES OR GOGGLES.

Other Protective Equipment: SAFETY SHOWER & EYEBATH

Supplemental Safety and Health

NOTE TO DR.: MAY CAUSE TISSUE DESTRUCTION LEADING TO STRICTURE. IF LAVAGE PERFORMED, SUGGEST ENDOTRACHEAL &/OR ESOPHAGUSCOPIC CONTROL.

IF BURNS PRESENT, TREAT AS THERMAL AFTER DECONTAMINATION. NO SPEC IFIC ANTEDOTE. SUPPORT, CARE. TREATMENTBASED ON JUDGEMENT OF DR IN

RESPONSE TO REACTION OF PATIENT.

Boiling Pt:B.P. Text:500F,260C Vapor Pres: