

UNIVERSAL FLUX AND MANUFACTURE INC -- UNIVERSAL #45 FLUX -- 3439-00-250-2629

=====  
Product Identification  
=====

Product ID:UNIVERSAL #45 FLUX

MSDS Date:03/26/1997

FSC:3439

NIIN:00-250-2629

MSDS Number: CDJPM

=== Responsible Party ===

Company Name:UNIVERSAL FLUX AND MANUFACTURE INC

Address:5309 BOUGHNER ROAD

City:ROCK CREEK

State:OH

ZIP:44084-9768

Country:US

Info Phone Num:216-731-1507 NOT LISTED

Emergency Phone Num:800-2424-9300

Preparer's Name:DSCR-VBA

CAGE:59819

=== Contractor Identification ===

Company Name:UNIVERSAL FLUX AND MANUFACTURE INC

Address:5309 BOUGHNER ROAD

Box:City:ROCK CREEK

State:OH

ZIP:44084-9768

Country:US

Phone:216-731-1507 WRONG NUMBER

CAGE:59819

=====  
Composition/Information on Ingredients  
=====

Ingred Name:ZINC CHLORIDE (SARA III)

CAS:7646-85-7

RTECS #:ZH1400000

Other REC Limits:NONE SPECIFIED

OSHA PEL:1 MG/M3/2 STEL

ACGIH TLV:1 MG/M3/2STEL FUM

E93

EPA Rpt Qty:1000 LBS

DOT Rpt Qty:1000 LBS

Ingred Name:HYDROGEN CHLORIDE (HYDROCHLORIC ACID) (SARA III)

CAS:7647-01-0

RTECS #:MW4025000

Other REC Limits:NONE SPECIFIED

OSHA PEL:C 5 PPM

ACGIH TLV:C 5 PPM; 9192

EPA Rpt Qty:5000 LBS

DOT Rpt Qty:5000 LBS

Ingred Name:AMMONIUM CHLORIDE (SARA III)

CAS:12125-02-9

RTECS #:BP4550000

Other REC Limits:NONE SPECIFIED

OSHA PEL:10 MG/M3/20 STEL

ACGIH TLV:10 MG/M3 FUME; 9192

EPA Rpt Qty:5000 LBS

:ZC0110000

Other REC Limits:NONE SPECIFIED

=====  
===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO  
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO  
Health Hazards Acute and Chronic:ACUTE- MAY BE CORROSIVE TO ALL  
TISSUES, MAY IRRITATES OR BURN EYES AND SKIN. INHALATION:IRRITATION  
OF RESPIRATORY SYSTEM. INGESTION: BURNING SENSATION OF G.I. TRACT,  
AND MAY CAUSE VOMITING. CHRONIC-NO NE KNOWN.

Effects of Overexposu

re:IRRITATION OF RESPIRATORY SYSTEM, BURNING,  
ITCHTING AND IRRITATION OF EYES, INGEATION MAY CAUSE VOMITING AND  
BURNING SENATION OF G.I. TRACT.

Medical Cond Aggravated by Exposure:PULMONARY AND SKIN DISEASES.

=====  
===== First Aid Measures =====

First Aid:GET MEDICAL ATTENTION. EYE/SKIN:IMMEDIATELY FLUSH WITH WATER  
FOR AT LEAST 15 MINUTES. HOLD EYELIDS OPEN. INHALED:REMOVE TO FRESH  
AIR & PROVIDE OXYGEN/CPR IF NEEDED. ORAL:DO NOT INDUCE VOMITING.

IF

CON SCIOUS, DRINK PLENTY OF WATER/MILK. CALLA PHYSICIAN  
IMMEDIATELY. NEVER GIVE ANYTHING BY MOUTH TO AN UNCONSCIOUS PERSON.

=====  
===== Fire Fighting Measures =====

Flash Point:>200F,>93C

Extinguishing Media:WATER SPRAY, CO2, FOAM/DRY CHEMICAL. WATER SPRAY  
MAY BE USED TO KEEP FIRE EXPOSED CONTAINERS COOL & FLUSH SPILLS  
AWAY.

Fire Fighting Procedures:WEAR FULL PROTECTIVE CLOTHING AND NIOSH-  
APPROVED SELF-CONTAINED BREATHING APPARATUS WITH FULL  
FACEPIECE

OPERATED IN THE POSITIVE PRESSURE MODE.

Unusual Fire/Explosion Hazard:MAY RELEASE TOXIC VAPORS OF HYDROCHLORIC  
ACID AND ZINC CHLORIDE.

=====  
===== Accidental Release Measures =====

Spill Release Procedures:CONTAIN SPILL, ABSORB, SWEEP-UP AND TRANSFER  
TO SUITABLE CONTAINER FOR LATER DISPOSAL. FLUSH AREA WITH WATER TO  
CHEMICAL SEWER.

Neutralizing Agent:SODA BICARB OR LIME.

=====  
===== Handling and Storage =====

Handli

ng and Storage Precautions:STORE IN A COOL, DRY, WELL VENTILATED AREA AWAY FROM FLAMES AND INCOMPATIBLE MATERIALS. KEEP CONTAINERS TIGHTLY CLOSED.

Other Precautions:AVOID BREATHING VAPORS. DO NOT GET IN EYES, ON SKIN OR ON CLOTHING. WASH THOROUGHLY AFTER HANDLING AND BEFORE EATING OR DRINKING. REMOVE CONTAMINATED CLOTHING PROMPTLY. KEEP OUT OF REACH OF CHILDREN.

=====  
===== Exposure Controls/Personal Protection =====

Respiratory Protection:RESPIRATOR WILL NOT NORMALLY BE NECESSARY. USE

NIOSH-APPROVED AIR SUPPLIED RESPIRATOR OR RESPIRATOR WITH FILTER FOR ACID, OR USE SELF-CONTAINED BREATHING APPARATUS.

Ventilation:GENERAL ROOM VENTILATION IS NORMALLY ADEQUATE.

Protective Gloves:NEOPRENE, NITRILE, VPC OR NATURAL RUBBER

Eye Protection:SAFETY GLASSES OR GOGGLES/FACE SHIELD

Other Protective Equipment:EYE WASH STATION AND SAFETY SHOWER.

INDUSTRIAL-TYPE WORK CLOTHING AND APRON AS REQUIRED.

Work Hygienic Practices:USE GOOD CHEMICAL HYGIENE PRACTICE

. AVOID

UNNECESSARY CONTACT.

Supplemental Safety and Health

MFR IS OUT OF BUSINESS AND IS UNLISTED. INFORMATION PRESENTED HEREIN IS

ACCURATE AND RELIABLE TO THE BEST OF OUR KNOWLEDGE AND BELIEF BUT

IS NOT GUARANTEED TO BE SO. IT IS THE USER'S RESPONSIBILITY TO

TAKE ALL SAFETY PRECAUTIONS AS MAY BE NECESSARY. WE HEREBY DISCLAIM

ALL LIABILITY WITH RESPECT TO IT'S USE.

=====  
===== Physical/Chemical Properties =====

HCC:C1

Boiling Pt:B.P. Text:NOT KNOWN

V

apor Pres:NOT KNOWN

Spec Gravity:NOT KNOWN

pH:ACID

Solubility in Water:COMPLETE

Appearance and Odor:CLEAR COLORLESS LIQUID WITH AN "ACIDIC" ODOR

=====  
===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

CYANIDES, BASES. CAN BE CONSIDERED A WEAK ACID. CORROSIVE TO SOME METALS ESPECIALLY IF HOT.

Stability Condition to Avoid:HEAT, FLAMES

Hazardous Decomposition Products:HYDROGEN CHLORIDE GAS, AND FUMES OF ZINC CHLORIDE.

=====

==== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH ALL LOCAL, STATE  
AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):  
This information is formulated for use by elements of the Department  
of Defense. The United States of America in no manner whatsoever,  
expressly or implied, warrants this information to be accurate and  
disclaims all liability for its use. Any person utilizing this  
do  
cument should seek competent professional advice to verify and  
assume responsibility for the suitability of this information to their  
particular situation.