

MINNESOTA MINING & MFG CO TELCOMM PRODUCTS DIV -- SEAL, 239087 (SUPPLEMENTAL) --  
5330-01-172-1533

===== Product Identification =====

Product ID:SEAL, 239087 (SUPPLEMENTAL)

MSDS Date:07/02/1990

FSC:5330

NIIN:01-172-1533

Kit Part:Y

MSDS Number: CDYHK

=== Responsible Party ===

Company Name:MINNESOTA MINING & MFG CO TELCOMM PRODUCTS DIV

Address:3M AUSTIN CTR

Box:2963

City:AUSTIN

State:TX

ZIP:78769-29

63

Country:US

Info Phone Num:512-834-1800

Emergency Phone Num:512-834-1800

CAGE:55203

=== Contractor Identification ===

Company Name:MINNESOTA MINING AND MFG CO TELCOMM MARKETS DIV

Address:3M AUSTIN CTR

Box:City:AUSTIN

State:TX

ZIP:79769-2963

Country:US

Phone:800-426-8688

CAGE:55203

Company Name:WHEELER BROTHERS INC

Address:INDUSTRIAL PARK, DRUM AVE

Box:737

City:SOMERSET

State:PA

ZIP:15501-2136

Country:US

Phone:814-445-9641

CAGE:2B144

Company Name:WHIRLPOOL CORP, BENTON HARBOR,MI

CAGE:81306

===

=====  
Composition/Information on Ingredients  
=====

Ingred Name:MFG STATES ARTICLE AND ALL OTHER PARTS (BESIDES ADHESIVES)  
ARE NON-HAZARDOUS.

RTECS #:9999999ZZ

Fraction by Wt: NA

Other REC Limits:NONE RECOMMENDED

=====  
Hazards Identification  
=====

Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:ITEM IS AN ARTICLE PER MFG.

Explanation of Carcinogenicity

:OF THE COMPOUNDS IN THIS PRODUCT IS

LISTED BY IARC, NTP, OR OSHA AS A CARCINOGEN.

Effects of Overexposure:NOT APPLICABLEACT

IRRITATION,DIZZINESS,TEMPORARY CNS IMPAIRMENT.INGESTION:MAY CAUSE

NAUSEA, VOMITING,GI IRRITATION,DIARRHEA AND POSSIBLY

UNCONSCIOUSNESS/DEATH.EYES/ SKIN:CAUSES PAIN,SEVERE IRRITATION.

VAPORS MAY CAUSE IRRITATION,BLURRED VISION.PROLONGED/REPEATED

CONTACT CAUSES DRYNESS,DEFATTING,DERMATI

=====  
First Aid Measures  
=====

====

First Aid:HMIS:USE APPROPRIATE AMERICAN RED CROSS 1ST AID  
PROCEDURES.SEE PHYSICIAN.

=====  
Fire Fighting Measures  
=====

Extinguishing Media:HMIS:UES APPROPRIATE FIRE EXTINGUISHING MEDIUM FOR  
SURROUNDING FIRE/MATLS.

Fire Fighting Procedures:HMIS:USE PPE AS CONDITIONS WARRANT.

=====  
Accidental Release Measures  
=====

Spill Release Procedures:HMIS:SWEEP UP AND DISPOSE ACCORDING TO ALL  
APPLICABLE LOCAL, STATE AND FEDER

AL REGULATIONS.

Neutralizing Agent:NONE

=====  
Exposure Controls/Personal Protection  
=====

Respiratory Protection:HMIS:NO RESPIRATORY PROTECTION REQUIRED UNDER  
NORMAL HNDLG CONDITONS.

Ventilation:HMIS:SUFFICIENT VENTILATION IN WORK AREA.

Protective Gloves:HMIS:RUBBER GLOVES RECOMMENDED.

Eye Protection:HMIS:SAFETY GLASSES/GOGGLES RECOMMENDED.

Other Protective Equipment:HMIS:USUAL PROTECTIVE CLOTHING RECOMMENDED.

Work Hygienic Practices:HMIS:WASH THOROUGHLY AFTER USE AND BEF

ORE

EATING OR SMOKING.

Supplemental Safety and Health

THIS KIT INCLUDES SEAL,SUPPORT,BUMPER,CLIP AND ADHESIVE. THIS ENTRY DESCRIBES SEAL ONLY.SEE PNIND:A FOR ADHESIVE.OTHER PARTS OF THE KIT ARE NON-HAZARDOUS (HARDWARES). PER TECH SUPP REQ970314T300A/J.CR AMER-HMIS:GENERATE MSDS FOR SEAL COMPO OF KIT IN THIS NSN.PER MSDS ITEM IS ARTICLE THEREFORE NO MSDS REQUIRED.

===== Physical/Chemical Properties =====

HCC:F2

pH:UNKNON

Evaporation Rate & Ref

erence:UNKNOWNHER=1

Appearance and Odor:PER MFG ITEM IS AN ARTICLE

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

Stability Condition to Avoid:HMIS:AVOID HIGH TEMEPRATURES.

===== Disposal Considerations =====

Waste Disposal Methods:HMIS:SWEEP UP AND DISPOSE ACCORDITN TO ALL APPLICABLE LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.